4-1201

- Lugusta G 8 O R G I A

ENGINEERING & ENVIRONMENTAL SERVICES DEPARTMENT

Hameed Malik, Ph.D., P.E. Director

MEMORANDUM

TO:

Geri Sams

FROM:

lameed Malik, Ph.D., P.E.

Director

DATE:

November 2, 2022

SUBJECT:

Warranty Repair Memo Price Increase

The Environmental Services Department requested a sole source for YANCEY BROS. CO in June of 2022. The Caterpillar D-8 Dozier 212233 was in need of a Bushing and Pin turn on both tracks. Yancey estimated the work originally at \$ 35,491.88. A purchase order was obtain through procurement, PO P436168 dated 06/22/2022, for that dollar amount and the machine was transported to Yancey Service Repair Center on 08/03/2022. By the time the machine reached Yancey the time for turning of the pins and bushings had pasted and the machine now needed a complete undercarriage. While doing the undercarriage Yancey found that the pivot bar seal, bogic rollers, track adjusters, and lift cylinders where damaged. This additional work was relayed to procurement by Environmental Services. We were advised to wait on final cost and then submit. The machine was returned to Environmental Services on 10/07/2022. Final Cost for all repairs made on machine while in Yancey's shop \$67,842.02. Repairs that were made would have to been done by Yancey to keep machine under warranty.

Yancey is the company that provided the unit and the warranty service agreement is in place to ensure machine stays in warranty even though the work being performed at this time does not qualify for warranty the areas being worked on if not done by Yancey will void the warranty.

Thank you in advance for your time and attention. Please feel free to contact me at 706-592-3206 should you have any questions or require any additional information

Attachment

Cc: File

TOTAL PRICE NAME OF BIDDER #3 UNIT PRICE 11/1/2022 REQUISITION NO REQUISITION DATE PURCHASE ORDER NO PURCHASE ORDER DATE . TOTAL PRICE NAME OF BIDDER #2 v, ŧ, UNIT PRICE 67,842.02 67,842.02 67,842.02 . 1 ı ï . • ı TOTAL PRICE YANCEY BROTHERS #1119 AUGUSTA-RICHMOND COUNTY GEORGIA PURCHASING DEPARTMENT YANCEY BROTHERS #1119 44 ₩ 47 NAME OF BIDDER #1 JAMIE BRANTLEY 67,842.02 UNIT PRICE QUANTITY -1 PHONE NUMBER VENDOR NAME QUOTED BY 53-19130 THEM NO. **ENVIRONMENTAL SERVICES** SHANE CAPITOSTI UNIT #212233 541 04 4210 SERVICE INVOICE #EMSI1957627 DEPARTMENT NUMBER REQUESTED BY DEPARTMENT NAME PURPOSE OF REQUEST TOTAL BID WITH SHIPPING APPROVAL - SIGNATURE **BID WITHOUT SHIPPING** BID# SOLE SOURCE SHIPPING CHARGES DESCRIPTION ITEM NO 17 # # 13 19 **8** 21 23 유 ੜ 17 디 23 N o H ო 4 'n 9 ~ 00

ţ



Page 17 of 17

Service Invoice

Invoice Number	Invoice Date
EMSI1957627	10/27/2022
Customer Number	Branch
901240	Augusta

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

A, GEORGIA

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

YANCEY BA

Yancey Bros. Co. Credit Department 259 Lee Industrial Blvd, Austell, GA 30168 7437

Sold To:

Ŀ

For Questions, please contact: Karol Evans 678-945-2664 Karol_Evans@yanceybros.com

212255 10302 W0 500 8-22

CUSTOMER C	RDER NO.	STORE	DIV	S	SALESMAN		TERMS	PSO/WO NO.	DOC. DATE		PC	LC	MC
P4964	P496168		G	G Jamie Brantley 392		2 1A03863		1A03863	08/22/2022		10	10	10 10
SHIP VIA		INV SEQ I	NO.	MAKE	MODEL	S	ERIAL NO.	EQUIPMENT NO. METER READ			MACH. ID		
		325205	5	AA	D8T	0	MLN01622	212233		4395		UP1013	37
QUANTITY	ITEM	NR				DES	CRIPTION	^		UNIT PR	ICE	EXTEN	ISION

Total Parts A2

2,373.03

Total Labor A2

2,090.40

Total Segment A2

4,463.43

TAKE ADVANTAGE OF OUR NEW INVOICE MANAGEMENT PORTAL - NOW AVAILABLE

To enroll, use the enrollment token found on the bottom of your invoice

Please contact your Credit Representative if you have any questions

TO AVOID DELAYS IN PAYMENT PROCESSING

PLEASE MAKE ALL REMITTANCES TO: YANCEY BROS CO DRAWER CS 198757 ATLANTA, GA 30384-8757

MACHINE INVOICES ARE DUE UPON RECEIPT; ALL OTHER INVOICES ARE DUE NET 30 DAYS FROM INVOICE DATE UNLESS OTHERWISE SPECIFIED ON ORIGINAL INVOICE. ANY ACCOUNT NOT PAID WITHIN TERMS WILL BE CONSIDERED PAST DUE AND A FINANCE CHARGE WILL COMPUTED BY A SINGLE PERIODIC RATE OF 1.5% PER MONTH WHICH IS AN ANNUAL PERCENTAGE RATE OF 18%. ANY ACCOUNT OVER 60 DAYS PAST DUE MAY BE PLACED ON C.O.D.

PAY THIS AMOUNT

67,842.02

THANK YOU FOR YOUR BUSINESS!!

VIEW AND PAY ONLINE	YOUR WEB ENROLLMENT TOKEN	Please log in to view your account information and make
https://Yanceybros.billtrust.com	SQP DZD HSB	online payments



Sole Source Justification (Reference Article 6, Procurement Source Selection Methods and Contract Awards, § 1-10-56 SOLE SOURCE PROCUREMENT

Vendor:	YANCEY BROTHERS	_ E-Verify Number	*	515740
Commodity:	SERVICE REPAIR	-		
Estimated annual	expenditure for the above commodity	y or service:	\$	67,842.02
justification and	below that apply to the proposed support documentation as directed in cts/services requested).	purchase. Attach a mer initialed entry. (More th	norandun an one ei	n containing complete atry will apply to most
	SOLE SOURCE REQUEST IS THERE ARE NO REGION certification that no regional dist	AL DISTRIBUTORS. (A	Attach the	e manufacturer's written
	 SOLE SOURCE REQUEST DISTRIBUTOR OF THE OR manufacturer's — not the dis distributors. Item no. 4 also must 	UGINAL MANUFACTUR stributor's — written certi	ER OR	PROVIDER. (Attach the
	3. THE PARTS/EQUIPMENT AS ANOTHER MANUFACTURES			TH SIMILAR PARTS OF
X	4. THIS IS THE ONLY KNOWN NEEDS OF THIS DEPARTM memorandum with details of spe	ENT OR PERFORM THE	INTENE	
	5. THE PARTS/EQUIPMENT . STANDARDIZATION. (Attach			
	6. NONE OF THE ABOVE APP FOR THIS SOLE SOURCE RE			
	requests that competitive procurements attended in this sole source			
Name: S	HANE CAPITOSTI Departm	nent: ENVIRONMENTAL	SERVIC	Date: 11/1/2022
Department Head	Signature:		м	Date: // m/n
Approval Author	ity:			Date:
Administrator Ap	proval: (required - not required)			Date:
COMMENTS:				



Sold To:

AUGUSTA, GEORGIA 530 GREENE ST **PURCHASING DEPT ROOM 105** AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Invoice Date
EMSI1957627	10/27/2022
Customer Number	Branch
901240	Augusta

Remit To: YANCEY BROS. CO. **Drawers CS 198757** Atlanta, GA 30384-8757

Ship To:

For Questions, please contact: Karol Evans 678-945-2664 Karol_Evans@yanceybros.com

CUSTOMER C	RDER NO.	R NO. STORE DIV		SALESMAN Jamie Brantley 392		TERMS	PSO/WO NO.	DOC. DATE	PĊ	LC	MC 10
SHIP VIA INV SI		01	G			2	1A03863	08/22/2022	10	10	
		INV SEQ	NO. MAKE		IAKE MODEL	SERIAL NO.	EQUIPMENT NO	. METER REA	D	MACH. ID	
		3252055 AA		AA	D8T 0MLN016		212233	4395		UP10137	
QUANTITY	QUANTITY ITEM NR				DESCRIPTION		UNIT P	RICE	EXTE	HOISK	

SEG 01

CLEAN MACHINE

COMPLAINT: CLEAN MACHINE

CAUSE: N/A

RESULTANT DAMAGE: N/A

CORRECTION:

REMOVED TRASH FROM LH SIDE ROLLER FRAMES, CHECKED

LH SIDE EQUALIZER BAR PIN, PIN SHOWS NO WEAR,

FILLED PIVOT BAR OIL RESERVOIR, LET AIR BLEED,

WILL CHECK IN THE MORNING

CHECKED PIVOT SHAFT RESERVOIR, WAS STILL LOW,

FILLED WITH MORE OIL, WILL CHECK AGAIN LATER IN

THE DAY, REMOVED TRASH FROM RH SIDE ROLLER FRAME,

CHECKED EQUALIZER BAR PIN, NO WEAR, SEALS ARE

INTACT ON BOTH SIDES

REMOVED TRASH FROM UNDER MACHINE, CHECKED LH SIDE

PROBLEM ROLLERS, THEY PIVOT, CHECKING RH SIDE

TUESDAY

CLEANED OIL SPOT FROM POPPED BLUE CAPS IN TILT

CYLINDER

TOOK BELLY PANS TO WASH BAY, CLEANED THEM OFF,

INSTALLED BELLY PANS, CLEANED AROUND MACHINE

DROVE MACHINE OUT OF BAY. AND REFILLED SYSTEMS TO

SPEC.

Flat Rate Labor 01

1.872.00

Total Segment 01

1,872.00

SEG 02

REMOVE & INSTALL TRACK ASSEMBLY

COMPLAINT: R&I TRACKS

CAUSE: N/A CORRECTION:

4314



Sold To:

SIDE #5 ROLLER

4.3

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Invoice Date
EMSI1957627	10/27/2022
Customer Number	Branch
901240	Augusta

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

CUSTOMER ORDE	R NO.	STORE	DIV	S	ALESMAN	TERMS	PSO/WO NO.	DOC	. DATE	PC	LC	MC
P4 26168		01	G	Jami	e Brantley 392	2	1A03863	08/22/2022		10	10	10
SHIP VIA		INV SEQ I	10.	MAKE	MODEL	SERIAL NO.	EQUIPMENT NO.	M	ETER READ		MACH.	ID
		325205	5	AA	D8T	0MLN01622	212233		4395	UP10137		37
QUANTITY IT	EM	NR					UNIT PRI	CE	EXTENSION			
ASSISTED IN LIFTIN 5424 8/31- LIFTED AND SUPPO BOTH TRACKS AND 5424 - UNWRAPPED FRAMES, WRAPPED MASTER LINK SHOE 4346 10/05/2022 THEM TO BE READ UNDER MACHINE. L ROLLER FRAME. W AND SPROCKET BO LOCATED MASTER AND BOLTS. TORQ DEG TURN. MARKE OTHER SIDE. CHEC TOPPED OFF OIL. P FOR COVERS. 7 7 4 4 1 1 1	DRTED I D SENT D TRACE D TRACE E, TORG UNWRA DY TO IN J SED C J/RAPPE DLT AND L LINK B UED TO D BOLT CKED OI	MACHINE. TO TO SPE KS, SLID TI KS WITH T QUED TO S APPED TRA STALLED. RANE TO I ED METAL S O USED MA OLTS AND O SPEC PL S. REPEA' IL LEVEL W O TRACKS	EC SHO HEM U HE CF PEC. ACKS, PUSH- LIFT TI SLING ACHINI PADS US AD TED PI /ITHN	OP. INDER RO RANE, INS' AND POSI' IED TRACI RACKS AN AROUND E TO WRA 6. INSTALL IDITIONAL ROCESS C ROLLER F MARKED E N C INS Tota	TALLED TION (S ID ABOVE FINAL P TRACKS. ED PAD 120 DN THE FRAME.					2.06 4.73 5.10 1.87 95.71 20.00		14. 33. 20. 7. 95. 20. 191. 1,032.



Sold To:

CAUSE:

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Invoice Date
EMSI1957627	10/27/2022
Customer Number	Branch
901240	Augusta

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

CUSTOMER (ORDER NO.	STORE	DIV	S	ALESMAN		TERMS	PSO/WO NO.	DOC.	DATE	PC	LC	MC
₽4 36	168~	01	G	Jami	e Brantley 392	2	2	1A03863	08/22	2/2022	10	10	10
SHIP V	IA	INV SEQ N	10.	MAKE	MODEL	5	SERIAL NO.	EQUIPMENT N	D. ME	TER READ	AD MACH. II		
		3252058	5	AA	AA D8T 0			0MLN01622 212233		4395	UP10137		37
QUANTITY	ITEM	NR				DES	SCRIPTION			UNIT PRI	CE	EXTEN	ISION
5424 - 9/7/22 - REMOVAL, HA ALL ROLLERS INSTALL TOMO 55424 - 9/9/22 - FOUND MULTI ROLLERS, MA BUT NO OTHE 5424 - BROUG TORQUED TO CYLINDER BO — 4346 LOOS ROLLERS INS' TIGHTEN THE OTHER SIDE TO SIDE FIRST TO THE CAP. REF CRANE TO INS SPEC. 36	D TO SET U ON RH SIDI ORROW, TO BS BEGAN INS BEGAN INS PLE BROKE NAGED TO RS, ORDER HT PUSH AI SPEC, INST LTS TO SPE EN UP ALL TALLED. PU TE ALED. PU TE ABUTMENT OF THE ROL D SPEC AND PEATED PRO	IP 3/4 TORQ E EXCEPT # PRQUED ALL TALLING LH EN BOLTS, C REMOVE BF RED NEW BG RMS IN, INS FALLED BLA EC THE BOLTS IT ANTI-SIEZ IT SIDE FIRS D TIGHTEN TO DCESS ON A RIER ROLLE	EUE GL 12, SET 1 SIDE 1 SIDE 1 SIDE 1 SIDE 1 SIDE 1 SIDE 1 TALLE 1 FROM 2 E ON 2 TALLE 1 ORQU 1 THE O' ALL RO	JN, INSTA TUP TO TS TO CAT ROLLERS #4, AND # N BOLT FR ED PUSH A DRQUED I M THE NEV THE BOLT HTEN THI IED ABUTI THER SID DILLERS. U	SPEC, 5, 77 COM #7, ARMS, LIFT FS AND E MENT E OF ISED	ם					2.06		74.
36 8		-	T1140 X8399	_	OLT /ASHER						4.73 4.90		170. 39.
9			60775		OLLER GP SI	F				7	83.55		7,051.
				Tota	al Parts 03								7,335.
				Flat	Rate Labor 03	3							1,032.
				Tota	al Segment 03	J.							8,367.
SEG 04 REPLACE BOO COMPLAINT :	GIE PAD/AIF	SPRING											



Sold To:

3 4

Service Invoice

Invoice Number	Invoice Date			
EMSI1957627	10/27/2022			
Customer Number	Branch			
901240	Augusta			

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

CUSTOMER ORDER N). STORE	DIV	S	ALESMAN		TERMS	PSO/WO NO.	DOC.	DATE	PC	LC	MC
P436168	01	G	Jami	e Brantley 392	2	2	1A03863	08/22	2/2022	10	10	10
SHIP VIA	INV SEQ	NO.	MAKE	MODEL	S	ERIAL NO.	EQUIPMENT NO	D. ME	TER READ		MACH.	ID
	325205	5	AA	AA D8T 0MLN01			2 212233		4395	UP10137		37
QUANTITY ITEM	NR				DES	CRIPTION			UNIT PRI	EXTEN	ISION	
RESULTANT DAMAGE: CORRECTION: 5424 9/1- INSPECTED B DEFECTS. SEG 05 REPLACE SPROCKET S 5424 - 9/13/22 - REMOV AND LH SIDE SPROCKE CLEANED SURFACES, TORQUED LH SIDE TO 221 +/- 22 LB FT, BEGAI 5424 - 9/14/22 - FOUND LH SIDE, ORDERED NE BOLTS, TURNED ALL N PER SIS	EGMENT ED PACKED II TS, REMOVE NSTALLED SI CAT SPEC OF I TORQUING TO BE 1 WAS W WASHER, (N DEBR D SPR PROCK F INITIA RH SIC HER S CHECK	Tota Tota RIS ON RI- OCKET SI KET SEGM AL TORQU DE HORT ON KED TORQ	EGMENTS, JENTS, E OF THE JUE ON ALL								129. 129.
70 71 70 10 2	6 7 3	5P7665 5V5841 7H3608 145462 U5517	V S N 2 S 3	OLT //ASHER-HARI //UT EEGMENT-SPI " DISC (59361) al Parts 05 al Labor 05	RO				1	2.47 1.76 2.32 168.50 2.38		172 124 162 1,685 4 2,150
SEG 06 REPLACE TR PIN& BSH 3825- WASHED BOTH T		I REMO		al Segment 05	5							2,924



Sold To:

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Invoice Date			
EMSI1957627	10/27/2022			
Customer Number	Branch			
901240	Augusta			

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

For Questions, please contact: Karol Evans 678-945-2664 Karol_Evans@yanceybros.com

2	5Y2373	BUSHING G	3,284.41	6,568.82
344	6V1723	BOLT	5.10	1,754.40
(280)	6V1723	BOLT	5.10	(1,428.00)
4	6V1724	BOLT	5.69	22.76
4	6V1725	BOLT	7.71	30.84
88	6Y0473	PLUG	0.24	21.12
2	6Y1081	RING G	450.21	900.42
344	7G6442	NUT	1.87	643.28
(100)	7G6442	NUT	1.87	(187.00)
88	9G1642	STOPPER	0.46	40.48
1	9W9675	RING G	91.60	91.60
44	3602308	RING-THRUST	5.43	238.92
132	3602308	RING-THRUST	5.43	716.76
88	4606952	PIN-TRACK	44.90	3,951.20
1	4606952	PIN-TRACK	44.90	44.90
1	6052194	WIPER	10.85	10.85
12	PYSFR11	AEROSOL CLEANER	4.44	53.28
1	6062XL	NITRILE GLOVES-XL	32.99	32.99
1	1540591	GASKET SEAL	30.93	30.93

Total Parts 06 13,538.55



Sold To:

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Invoice Date			
EMSI1957627	10/27/2022			
Customer Number	Branch			
901240	Augusta			

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

For Questions, please contact: Karol Evans 678-945-2664 Karol_Evans@yanceybros.com

CUSTOMER	ORDER NO.	STORE	DIV	S	ALESMAN	TERMS	PSO/WO NO.	DOC	DOC. DATE PC		LC	MC
P436	488	01	G	G Jamie Brantley 392		2	1A03863	08/2	08/22/2022		10	10
SHIP \	/IA	INV SEQ I	VO.	MAKE	MODEL	SERIAL NO.	EQUIPMENT NO	o. Mi	ETER READ		MACH.	ID
		325205	5	AA	D8T	0MLN01622	212233		4395		UP10137	
QUANTITY	ITEM	NR.	DESCRIPTION UNIT PRIC						CE	E EXTENSION		
				Flat	Rate Labor 06						1	6,837.0
				Tota	I Segment 06						2	0,375.5
REPLACE LIG 5424 - 9/8/22 - BRACKET, W/ INSTALL 5424 - 10/5/22 TOGETHER, I 4346 FROI AFTER BEING TO SEE IF PO POWER WAS A BAD FUSE. ARE WORKIN WHEN LIGHT POWER. CHI REPLACED BE 4	REPAIRED I AITING UNTII - PUT NEW NSTALLED C NT CYLINDE GREPLACED WER WAS O BEING SUP! REPLACED G NOW. NOT SWITCH WA ECKED BULE	L CYLINDER LIGHTS AND N MACHINI R LIGHTS W J. REMOVED SETTING TO PLIED. CHE 115A FUSE A TICED BACK US ENGAGE BS. BOTH BI ALL LIGHT 3	RS ARE D BRA(E, TOR /ERE N HARN THE L CKED ND CY (LIGH D. LIGH ULBS N S ARE E9860	E BACK TO CKETS QUED TO NOT WORI NESS AND LIGHTS. NO FUSES AN /LINDER L TS WERE HTS WERE HTS WERE WERE BLC WORKING	SPEC KING CHECKED D ID FOUND IGHTS NOT ON E GETTING DWN. E NOW.					2.02		8.0
4 16			M3062 P1075		OLT ASHER					0.53 0.73		2.1 11.6
4		_	P2955		DLT					0.94		3.7
16			V8801		UT					0.37		5.9
10			K1181		RAP-CABLE					0.47		
8		8	T 4224		ASHER					0.44		4.7
												3.6
4		-	T4896		ASHER					0.45		3.6 1.8
8		9	W4361	i M	IOUNT					16.59		3.5 1.8 132.7
		9	W4361 118314	i M	IOUNT RKT AS					16.59 44.38		3.6 1.8 132.7 177.6
8 4 1		9 1 ⁻ 18	W4361 118314 552270	i M	IOUNT RKT AS LUG KIT	7				16.59 44.38 5.31		3.4 1.8 132.1 177.9 5.3
8 4 1 3		9 1: 1: 2:	W4361 118314 552270 275978	i M B D P	IOUNT RKT AS LUG KIT AMP GP-FLOO				1	16.59 44.38 5.31 21.38		3.5 1.8 132.7 177.5 5.3 364.1
8 4 1		9 1: 1: 2: 3:	W4361 118314 552270	i M i B) P 3 L	IOUNT RKT AS LUG KIT				1	16.59 44.38 5.31		3.9 1.3 132.7 177.9 5.3



Sold To:

Service Invoice

Invoice Number	Invoice Date			
EMSI1957627	10/27/2022			
Customer Number	Branch			
901240	Augusta			

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

CUSTOMER ORDER NO.		STORE DIV		SALESMAN		TERMS	TERMS PSO/WO NO.	DOC. DATE		PC	LC	MC	
P438	t68	01	G	Jami	e Brantley 392	2 2	1A03863	08/22	2/2022	10	10	10	
SHIP V	1A	INV SEQ I	10.	MAKE	MODEL	SERIAL NO.	EQUIPMENT NO.	ME	TER READ		MACH.	ID	
		325205	5	AA	D8T	0MLN01622	212233		4395		UP10137		
QUANTITY	ITEM	NR				DESCRIPTION	-		UNIT PR	ICE	EXTENSION		
1		42	15567	В	RACKET AS-I	R				126.73		126.7	
1			215568	_	RACKET AS-I					126.73		126.7	
2		53	95528	L	AMP GP-FLO	О			4	120.92		841.8	
				Tota	al Parts 07							3,391.2	
				Flat	Rate Labor 0	7						936.	
				Tota	il Segment 07							4,327.	
EG 08													
REPLACE FEN	IDER												
		DEBRIS FRO	OM OLI	D TREAD,									
5424 - 9/1/22 -	REMOVED I	DEBRIS FRO	OM OLI	D TREAD, E, INSTAL	LED NEW								
5424 - 9/1/22 - REMOVED OL	REMOVED I D BOLTS, CI	LEANED SU	OM OLI IRFACI	D TREAD, E, INSTAL	LED NEW								
5424 - 9/1/22 - REMOVED OL	REMOVED I D BOLTS, CI	LEANED SU PEC	OM OLI IRFACI C8585	E, INSTAL	LED NEW					3.40		30.	
5424 - 9/1/22 - REMOVED OL TREAD, TIGHT	REMOVED I D BOLTS, CI	LEANED SU PEC 8	IRFACI	E, INSTAL B	LED NEW					3.40 478.42			
	REMOVED I D BOLTS, CI	LEANED SU PEC 8	IRFACI C8585	E, INSTAL B T	LED NEW OLT HEX							30.6 478.4 509.6	
5424 - 9/1/22 - REMOVED OL TREAD, TIGHT 9	REMOVED I D BOLTS, CI	LEANED SU PEC 8	IRFACI C8585	E, INSTAL B T	LED NEW OLT HEX READ-RH							478. 509.	
5424 - 9/1/22 - REMOVED OL TREAD, TIGHT 9	REMOVED I D BOLTS, CI	LEANED SU PEC 8	IRFACI C8585	E, INSTAL B T Tota	LED NEW OLT HEX READ-RH al Parts 08	ı						478.	
5424 - 9/1/22 - REMOVED OL TREAD, TIGHT 9 1	REMOVED I D BOLTS, CI	LEANED SU PEC 8	IRFACI C8585	E, INSTAL B T Tota	OLT HEX READ-RH al Parts 08 al Labor 08	1						478. 509. 624.	
5424 - 9/1/22 - REMOVED OL TREAD, TIGHT 9 1	REMOVED I D BOLTS, CI IENED TO SI	LEANED SU PEC 8 34	IRFACI C8585	E, INSTAL B T Tota	OLT HEX READ-RH al Parts 08 al Labor 08	1						478. 509. 624.	
5424 - 9/1/22 - REMOVED OL TREAD, TIGHT 9 1	REMOVED I D BOLTS, CI IENED TO SI	LEANED SU PEC 8 34	IRFACI C8585 401461	E, INSTAL B T Tota Tota	OLT HEX READ-RH al Parts 08 al Labor 08							478. 509. 624.	
5424 - 9/1/22 - REMOVED OL TREAD, TIGHT 9 1	REMOVED I D BOLTS, CI IENED TO SI	LEANED SU PEC 8 34 34 S S EPAIR BROK	IRFACI C8585 401461	E, INSTAL B Tota Tota Tota ASS.	OLT HEX READ-RH al Parts 08 al Labor 08	1				478.42 18.52		478. 509. 624. 1,133.	
5424 - 9/1/22 - REMOVED OL TREAD, TIGHT 9 1 SEG 09 REPLACE WIN NOVUS CAME	REMOVED I D BOLTS, CI IENED TO SI	LEANED SU PEC 8 34 S S PAIR BROK	(EN GL	E, INSTAL B T Tota Tota ASS.	LED NEW OLT HEX READ-RH al Parts 08 al Labor 08 al Segment 08					478.42		478. 509. 624.	
5424 - 9/1/22 - REMOVED OL TREAD, TIGHT 9 1 SEG 09 REPLACE WIN NOVUS CAME	REMOVED I D BOLTS, CI IENED TO SI	LEANED SU PEC 8 34 S S EPAIR BROK 5	(EN GL	E, INSTAL B T Tota Tota ASS.	LED NEW OLT HEX READ-RH al Parts 08 al Labor 08 al Segment 08	0			,	478.42 18.52		478. 509. 624. 1,133. 259. 258.	
5424 - 9/1/22 - REMOVED OL TREAD, TIGHT 9 1 SEG 09 REPLACE WIN NOVUS CAME 14 1	REMOVED I D BOLTS, CI IENED TO SI	LEANED SU PEC 8 34 S S EPAIR BROW 5 31 31	(EN GL 5P6605 897520	E, INSTAL B T Tota Tota ASS.	LED NEW OLT HEX READ-RH al Parts 08 al Labor 08 al Segment 08 I-SEAL STK GLASS AS-FR	0			;	18.52 258.27		478. 509. 624. 1,133.	
5424 - 9/1/22 - REMOVED OL TREAD, TIGHT 9 1 SEG 09 REPLACE WIN NOVUS CAME 14 1	REMOVED I D BOLTS, CI IENED TO SI	LEANED SU PEC 8 34 S S EPAIR BROK 5 31 31	(EN GL 5P6605 897520	E, INSTAL B Tota Tota ASS.	LED NEW OLT HEX READ-RH al Parts 08 al Labor 08 al Segment 08 LSEAL STK GLASS AS-FR GLASS AS-DO	O O O			;	18.52 258.27 499.43		478. 509. 624. 1,133. 259. 258. 499.	



Sold To:

Customer Number

Invoice Number

Invoice Date EMSI1957627 10/27/2022 Branch 901240 Augusta

Service Invoice

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

CUSTOMER (ORDER NO.	STORE	DIV	S	ALESMAN	TERMS	PSO/WO NO.	DOC.	DATE	PC	LC	MC	
P436	P436468		G	Jami	e Brantley 392	2 2	1A03863	08/22	2/2022	10	10	10	
SHIP V	'IA	INV SEQ N	10.	MAKE	MODEL	SERIAL NO	EQUIPMENT N	D. ME	TER READ		MACH.	ID	
		3252055	5	AA	D8T	0MLN01622	212233		4395		UP1013	37	
QUANTITY	ITEM	NR DESCRIPTION							UNIT PRI	CE	EXTENSION		
				Tota	l Labor 09						_	70.2	
1 1					GLASS INSTA					62.50 31.16		862.5 31.1	
				Tota	I Miscellaneo	us 09						893.	
				Tota	l Segment 09						;	3,510.4	
COMPLAINT: I CAUSE: WORI RESULTING D CORRECTION ARMS, FOUNE NUTS, INSTAL 6 1 4 2 2 1	N WIPERS AMAGE: WIF 1: 5424 - 10/5/ D TO BE MIS:	PERS NO LC /22 - REMO\ SING SOME /IPER ARMS 6 12 22 22	ONGER VED O	R CLEAN LD WIPER 5, ORDERI BLADES N BI B B B B B B B B B B B B B B B B B	ED NEW UT LADE A LADE A RM GP-WIPE RM GP-WIPE LADE AS-WIF	:R				0.27 25.25 23.82 33.66 33.66 39.18		1. 25. 95. 67. 67. 39.	
					al Parts 10							295.	
				Tota	al Labor 10							624.	
				Tota	al Segment 10	•						919.	
EG 11 REPLACE HAI COMPLAINT: I CAUSE: N/A RESULTANT (DOOR HAND		IBLY II	NOP									



Sold To:

474.54

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Invoice Date			
EMSI1957627	10/27/2022			
Customer Number	Branch			
901240	Augusta			

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

CUSTOMER	ORDER NO.	STORE	DIV	S	ALESMAN	TERMS	PSO/WO NO.	DOC.	DATE	PC	LC	MC
*P430	168·	01	G	Jami	e Brantley 392	2	1A03863	08/22	2/2022	10	10	10
SHIP V	/IA	INV SEQ	VO.	MAKE MODEL		SERIAL NO.	EQUIPMENT NO.	ME	TER READ		MACH.	ID
		325205	5	AA	D8T	0MLN01622	212233		4395	1	UP1013	37 -
QUANTITY	ITEM	NR	DESCRIPTION					UNIT PRICE		EXTENSION		
CORRECTION REPLACED DO REPLACED DO GORDERED ME (335-6263), HA DRILLED OUT RH SIDE OF M AND WASHER 2 4 2 4 1 1 SEG 12 REMOVE & IN 5424 - 9/6/22 - MACHINE, BE HARNESES FI 5424 - 9/9/22 - BOTH LH AND TO THER SIDE. DOWN AND TO OTHER SIDE.	STALL LIFT/I STALL LIFT/I STALL LIFT/I REMOVED F GAN REMOVE REMOVED F OR H SIDE CY O SEAL KIT, ON O ALBANY AS I/2022 RETRI I/ECTED MOL	CORRECT CORRECT CORRECT CORRECT COLTS AND T STALLED NI AND MARKI S 5 7 8 8 8 36 8 36 4 4 6 8 10 10 10 10 10 10 10 10 10 10 10 10 10	IDLES HAND APPE EW HA ED BO W3896 X7729 T4137 T4139 662271 NDER BLAI BRAC NDERS LINES SET O EC SH ATES IOUNT	WERE OF LES D BOLT HO INDRAIL,B LTS. S W W W BO BO Tota Tota Tota Tota	RDERED OLES ON OLTS, BRAB HANDLE ASHER ASHER OLT OOR AS BI Parts 11 BI Labor 11 BI Segment 11 O WIRING ED RAPPED FO T SEAL O DER. EN BOLTS					110.00 1.67 1.03 0.59 1.27 306.10		220.0 6.6 2.0 1.1 5.0 306.1 541.1 546.0



Sold To:

47 34

AUGUSTA, GEORGIA 530 GREENE ST

PURCHASING DEPT ROOM 105

AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Involce Date				
EMSI1957627	10/27/2022				
Customer Number	Branch				
901240	Augusta				

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

For Questions, please contact: Karol Evans 678-945-2664 Karol_Evans@yanceybros.com

CUSTOMER C	CUSTOMER ORDER NO. STORE DIV		S	SALESMAN Jamie Brantley 392		PSO/WO NO.	DOC.	DOC. DATE		LC	MC	
P486168- SHIP VIA		01 G Jan				Jami	1A03863	08/22	2/2022	10	10	10
				MAKE	MODEL	SERIAL NO.	EQUIPMENT NO	. METER READ		MACH. ID		ID
		325205	5	AA	D8T	0MLN01622	212233		4395		UP101:	37
QUANTITY	ITEM	NR			ſ	DESCRIPTION			UNIT PRI	EXTENSION		
5 9			7K1181 145168		TRAP-CABLE AT HYDO ADV	BULK				0.47 18.23		2.3 164.0
				Tota	l Parts 12							166.4
				Tota	l Labor 12							1,466.4
				Tota	il Segment 12							1.632.

SEG 13

RECONDITION/ REBUILD LIFT/HOIST CYLINDER BOTH LIFT CYLINDERS # 250-5861 WERE LEAKING AROUND THE RODS, BOTH RODS WERE BENT - SCRATCHED -DENTED. STEAM CLEANED AND DISASSEMBLED BOTH CYLINDERS. THE MACHINE SHOP/WELDING SHOP MADE TWO NEW RODS, HYD SHOP LIGHT HONED BARRELS AND REMOVED OLD SEALS, BEAD BLASTED BOTH HEADS TO REMOVE RUST AND DEBRIS, CLEANED/INSPECTED ALL PARTS AND REMOVED TRUNNION BUSHINGS. INSTALLED NEW SEAL KITS #319-3557 IN HEADS/PISTONS. ASSEMBLED CYLINDERS AND PRESSURE TESTED THEM @ 3000 PSI. BLEW PROJECTILES THROUGH STEEL LINES AND ATTACHED THEM. PRESSED NEW TRUNNION BUSHINGS ON CYLINDERS. REMOVED TRUNNION BUSHINGS FROM MOUNTING CAPS AND PRESSED IN NEW BUSHINGS. CLEANED/PAINTED BOTH CYLINDERS AND MOUNTING CAPS. FABRICATED 2 RODS PER SAMPLE 3.000" X 61.875" 4865 - 9/24/22 (2 - RODS) TRANSPORTED ROD AND EYE TO WELD BAY. TAPED END OF ROD TO PREVENT DAMAGE FROM SPLATTER. FITTED EYE TO ROD AND TACKED IN PLACE, TIG WELDED A ROOT AND TWO HOT PASSES. USED MIG TO FILL UP THE REMAINDER OF THE BEVEL. REMOVED TAPE AND TAPE RESIDUE. DELIVERED



Sold To:

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Invoice Date
EMSI1957627	10/27/2022
Customer Number	Branch
901240	Augusta

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

CUSTOMER C	ORDER NO.	STORE	DIV	S	ALESMAN		TERMS	PSO/WO NO.	DOC.	DATE	PC	LC	MC
P4901	16 8	01	G	Jami	e Brantley 39	2	2	1A03863	08/22	2/2022	10	10	10
SHIP V	IA	INV SEQ	NO.	MAKE	MODEL	S	ERIAL NO.	EQUIPMENT NO). ME	ETER READ		MACH.	ID
		325205	5	AA	D8T	0	MLN01622	212233		4395		UP1013	37
QUANTITY	ITEM	NR.	-			DES	CRIPTION	1		UNIT PR	ICE	EXTENSION	
ROD TO HYDR	AULIC SHO	P.								1			
1			U9939		RUSH END						12.13		12.1
2			254078		EAL-O-RING						2.53		5.0
2			J0520		AL-O-RING						2.49		4.9
2			K1388		EAL-O-RING						2.14		4.2
2			K9090		EAL-O-RING						1.64		3.2
4			E1108		EARING						33.62		134.4
2			V8400		EAL-O-RING						1.82		3.6
4			041844		EARING						69.14		276.5
2			193557		IT-SEAL-H.C					1	63.59		327.1
1			589586		LOSS BLACK						13.32		13.3
4			YSFR1		AEROSOL CI. :P ROD	_EANI	EK				4.44		17.7
125		3	.000	IHÇ	PROD						7.40		925.0
				Tota	l Parts 13								1,727.6
				Tota	l Labor 13							;	3,481.9
				Tota	l Segment 13	3						!	5,209.6
TROUBLESHO COMPLAINT: CAUSE: RIGH RESULTANT D CORRECTION 5424 9/1- FOUI PIVOT SHAFT TO INSPECT. I	PIVOT SHA T PIVOT SH AMAGE : LO : ND EXCESS . CLEANED	FT LOW ON IAFT SEAL OSS OF OIL SIVE DEBRI DEBRIS AN	N OIL S ARO ND CUT	UND EQ B	ABLES								
SHAFT SEAL L	_			TH CUSTO									156.0
				ı ota	al Segment 14	+							156.0



Sold To:

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Invoice Date
EMSI1957627	10/27/2022
Customer Number	Branch
901240	Augusta

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

For Questions, please contact: Karol Evans 678-945-2664 Karol_Evans@yanceybros.com

CUSTOMER C	CUSTOMER ORDER NO. STORE DIV		DIV	S	ALESMAN	TERMS	PSO/WO NO.	DOC. DA	TE	PC	LC	MC
P4 86168		01 G		Jamie Brantley 392		2	2 1A03863		08/22/2022		10 10	10
SHIP VIA		INV SEQ	NO.	MAKE	MODEL	SERIAL NO	EQUIPMENT N	D. METER	METER READ		MACH. ID	
		32520	55	AA	D8T	0MLN0162	2 212233	43	395		UP1013	37
QUANTITY	ITEM	NR			1	DESCRIPTION			UNIT PRIC	E	EXTEN	ISION

SEG 15

REMOVE TRACK ROLLER

COMPLAINT: REMOVED ROLLER FRAME

CAUSE: NEEDS RESEALING RESULTANT DAMAGE:

CORRECTION: - 4346 REMOVED TILT CYLINDER PINS AND BOLTS. USED DOUBLE END HOOK CHAIN TO CHAIN CYLINDER TO BLADE, CLEANED ARE AROUND PIN. REMOVED PUSH ARM BOLTS FROM THE ARMS, REMOVED PIN HOLDING PUSH ARMS TO BLADE, REMOVED RIGHT SIDE PUSH ARM. LOWERED ON TO BLOCKS AND PLACED OUTSIDE BAY DOOR. REMOVED TRUNNION BOLTS AND TRUNNION. REMOVED PLUG AND O-RING SEAL PLATE. REMOVED PIVOT SHAFT THRUST RING AND PLATE. AFTER TECH FINISHED REMOVED EQ BAR BOLTS, I WENT THROUGH AND REMOVED EQ PIN CONNECTED TO THE ROLLER FRAME, REMOVED ROLLER FRAME COMPLETELY. NOTICED THAT THE MOUNTING BOLTS BEHIND THE ROLLER FRAME WERE ALL MISSING OR BROKEN OFF. 5424 - 9/23/22 - ASSISSTED ENIOR TECH IN CLEANING DEBRIS FROM ROLLER FRAME, REMOVING LH SIDE PUSH ARM, CLEANING AREA AROUND LH SIDE ROLLER FRAME, AND REMOVING LH SIDE TRUNION BALL. WASHED MULTIPLE PARTS IN WASH BAY, REMOVED PUSH ARM PIN, REMOVED EQUALIZER BAR BOLTS --- 4346 09/26/2022 REMOVED PUSH ARMS BOLTS FROM **ROLLER** FRAME TRUNNION, HAD TO CUT ONE BOLT OUT. REMOVED PIN HOLDING PUSH ARM TO BLADE. REMOVED PUSH ARM COMPLETELY. REPEATED SAME PROCESS ON THE OTHER SIDE. REMOVED STABILIZER BAR FROM MACHINE. PICKED ENTIRE BLADE AND PLACED A COUPLE FEET IN FRONT OF BLADE TO REMOVED TRACK ADJUSTERS, REMOVED TRUNNION FROM RIGHT SIDE OF MACHINE. REMOVED O-RING PLATE



Sold To:

11.4

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Invoice Date
EMSI1957627	10/27/2022
Customer Number	Branch
901240	Augusta

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

For Questions, please contact: Karol Evans 678-945-2664 Karol_Evans@yanceybros.com

CUSTOMER OR	DER NO.	STORE	DIV	S	SALESMAN		PSO/WO NO.	DOC. DATE	PC	LC	MC
P436168 SHIP VIA		01 G		Jami	e Brantley 392	2	1A03863	08/22/2022	10	10	10
		INV SEQ NO.		MAKE	MODEL	SERIAL NO.	EQUIPMENT NO	. METER READ		MACH. ID	
		3252055	5	AA	D8T	0MLN01622	212233	4395		UP101	37
QUANTITY	ANTITY ITEM NR DI			DESCRIPTION		UNIT PI	RICE	EXTEN	ISION		

AND BOLT FROM RH ROLLER FRAME. REMOVED DEBRIS FROM AROUND FINAL TO SEE BEHIND ROLLER FRAME. ALL EXTERIOR MOUNTING BOLTS WERE MISSING FROM ROLLER FRAME. REMOVED PIVOT SHAFT COVER BOLTS. CONNECTED CRANE TO RH ROLLER FRAME. REMOVED EQ PIN AND BOLTS. DRAINED ROLLER FRAME AND REMOVED FROM MACHINE. PLACED RH ROLLER FRAME ON BLOCKS. USED HYDRAULIC RAM TO PUSH TRACK ADJUSTER FROM ROLLER FRAME. REMOVED TRACK ADJUSTERS AND PLACE ON BLOCKS.

---- 4346 10/04/2022 AFTER REPAIRS WERE MADE, REINSTALLED ROLLER FRAME TO MACHINE. TIGHTEN DOWN MOUNTING BOLTS TO BOLT SPEC OF 90 FT-LBS. INSTALLED PIVOT SHAFT MOUNTING BOLTS. TORQUED TO SPEC. INSTALLED EQ BAR PIN AND TIGHTEN DOWN THE BOLTS AND NUTS. TORQUED TO SPEC AND MARKED BOLTS. PLACED TRUNNION ON ROLLER FRAME AND TORUGED BOLTS DONW. MARKED ALL HARWARE IN THE PROCESS. INSTALLED PUSH ARMS TO TO ROLLER FRAME WITH NEW HARDWARE, USED TORQUED GUN TO TORQUED PUSH ARM BOLTS DOWN. INSTALLED BLADE TO PUSH ARM. INSTALLED PINS AND HOLD DOWN PLATES. TORQED BOLTS TO HOLD DOWN PLATES.

---- 4346 INSTALLED BLADE BRACE AND TILT CYLINDER BACK TO PUSH ARMS. TORQUED PIN HOLD DOWN PLATES TO SPEC.

Flat Rate Labor 15

2.580.00

Total Segment 15

2,580.00

SEG 16

REMOVE FASTENERS, CONN & HARDWR COMPLAINT: TWO BROKEN BOLTS IN BOGIE ROLLERS CAUSE: BOLTS BACKED OUT



Sold To:

PIVOT SHAFT COVER.

RESULTANT DAMAGE: PIVOT SHAFT LEAKS.

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Invoice Date
EMSI1957627	10/27/2022
Customer Number	Branch
901240	Augusta

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

01 INV SEQ N 3252055 NR DKEN BOLT NTER OF B R BUILT UP ED BROKEN	rs OTH B	Jami MAKE AA	e Brantley 392 MODEL D8T	SERIAL NO OMLN01622 DESCRIPTION			2/2022 ETER READ 4395	10	MACH.	10 ID
3252055 NR DKEN BOLT NTER OF B R BUILT UP	rs OTH B			0MLN01622		IO. MI				ID
NR DKEN BOLT NTER OF B R BUILT UP ED BROKEN	rs BOTH B	AA	D8T		212233		4395		1154546	
NTER OF B R BUILT UP D BROKEN	ЮТН В		!	DESCRIPTION				UP1013		37
NTER OF B R BUILT UP ED BROKEN	ЮТН В			DESCRIPTION UNIT PRICE						ISION
W FASTENI		E WELDEI NOT DA Tota MISC Tota	D NUT TO MAGE TO II Labor 16 WELD SUPPL II Miscellaneou				5	0.00		312. 50. 50.
		MISC	HAUL MACHI	NE TO 01			3,74	7.77	;	3,747.
		Tota	l Miscellaneou	ıs 18					:	3,747.
		Tota	al Segment 18						:	3,747.
L	ROLLER ER FRAM	ER FRAME PIVE	Tota MISC Tota Tota Tota Tota ROLLER FRAME PIVOT SHAFF	Total Labor 16 MISC WELD SUPPL Total Miscellaneou Total Segment 16 MISC HAUL MACHI Total Miscellaneou	Total Labor 16 MISC WELD SUPPLIES Total Miscellaneous 16 Total Segment 16 MISC HAUL MACHINE TO 01 Total Miscellaneous 18 Total Segment 18 ROLLER FRAME PIVOT SHAFT ER FRAME PIVOT SHAFT	Total Labor 16 MISC WELD SUPPLIES Total Miscellaneous 16 Total Segment 16 MISC HAUL MACHINE TO 01 Total Miscellaneous 18 Total Segment 18 ROLLER FRAME PIVOT SHAFT ER FRAME PIVOT SHAFT	Total Labor 16 MISC WELD SUPPLIES Total Miscellaneous 16 Total Segment 16 MISC HAUL MACHINE TO 01 Total Miscellaneous 18 Total Segment 18 ROLLER FRAME PIVOT SHAFT ER FRAME PIVOT SHAFFT	Total Labor 16 MISC WELD SUPPLIES Total Miscellaneous 16 Total Segment 16 MISC HAUL MACHINE TO 01 Total Miscellaneous 18 Total Segment 18 ROLLER FRAME PIVOT SHAFT ER FRAME PIVOT SHAFT	Total Labor 16 MISC WELD SUPPLIES 50.00 Total Miscellaneous 16 Total Segment 16 MISC HAUL MACHINE TO 01 3,747.77 Total Miscellaneous 18 Total Segment 18 ROLLER FRAME PIVOT SHAFT ER FRAME PIVOT SHAFFT	Total Labor 16 MISC WELD SUPPLIES 50.00 Total Miscellaneous 16 Total Segment 16 MISC HAUL MACHINE TO 01 3,747.77 Total Miscellaneous 18 Total Segment 18 ROLLER FRAME PIVOT SHAFT ER FRAME PIVOT SHAFT



Sold To:

\$ 4 m

AUGUSTA, GEORGIA 530 GREENE ST **PURCHASING DEPT ROOM 105** AUGUSTA GA 30911-4406

Service Invoice

Invoice Number	Invoice Date
EMSI1957627	10/27/2022
Customer Number	Branch
901240	Augusta

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

For Questions, please contact: Karol Evans 678-945-2664 Karol_Evans@yanceybros.com

CUSTOMER C	RDER NO.	STORE	DIV	SALESMAN		TERMS	PSO/WO NO.	DOC. DATE	PC	rc	MC
P436168 SHIP VIA		01 G		Jamie Brantley 392		2	1A03863	08/22/2022	10	10	10
		INV SEQ I	NV SEQ NO.		MODEL	SERIAL NO.	EQUIPMENT NO.	METER READ		MACH. ID	
		325205	5	AA	D8T	0MLN01622	212233	4395		UP1013	37
QUANTITY	ITEM	NR			D	UNIT PR	ICE	CE EXTENSION			

-		43	346	A 6	F	TE	R	RI	ΞN	4
TI	H	E	<u>۱۱</u>	/0	T	Sŀ	ΗA	FI	. 8	ŝĒ
-	_		-		-				_	

EAL WAS CRUSHED AND FRAME SIDE ROLLER FRAME BEARING HAD BEEN REMOVED FROM THE ROLLER FRAME CRUSHED AND STRETCHED ALL WHILE INSIDE THE PIVOT SHAFT COVER, DID NOT SEE ANY DAMAGES TO THE PIVOT SHAFT. CLEANED SURFACES ON PIVOT SHAFT AND FRAME SIDE OF ROLLER FRAME. CLEANED PIVOT SHAFT COVER USING BUFFING WHEELS AND PADS. FOUND TRASH INSIDE ROLLER FRAME PIVOT SHAFT SIDE. CLEANED INSIDE ROLLER FRAME. REMOVED ALL SEALS FROM ROLLER FRAME. INSTALLED NEW SEALS WITH LITHIUM GREASE. CLEANED ALL SURFACES WHERE O-RINGS WOULD SEAL AT. REMOVED PIVOT SHAFT COVER BEARINGS AND REPLACED WITH NEW ONE AFTER CLEANING AREA WITH BUFFING WHEEL. REFILLED ROLLER FRAME AND PIVOT SHAFT RESERVOIR. REFILLED PIVOT SHAFT ON ROLLER FRAME UNTILL OIL WAS VISIBLE. LET SIT OVER THE WEEKEND. DID NOT FIND NO LEAKS. 09/30/22 DF5017 CLEANED HOLE WHERE THREADED INSERT WILL BE. PUT THREADED INSERT INTO PROPPER DEPTH TACKED IN PLACE USING TIG WELDING PROCESS.

2	2D1690	SEAL	10.23	20.46
4	2K4472	O RING	6.74	26.96
4	3E9850	BOLT	52.77	211.08
1	3T4243	BEARING	117.92	117.92
2	5L4751	RING-RETAINI	25.41	50.82
1	5P5374	SEAL	9.91	9.91
1	6V3263	SEAL	11.84	11.84
1	7T1151	SEAL	452.13	452.13
8	8C4436	BOLT	1.34	10.72
8	8T4176	BOLT	3.54	28.32
16	8T4223	WASHER	0.94	15.04
12	9W7602	SHIM	4.22	50.64



Sold To:

Service Invoice

Invoice Number	Invoice Date
EMSI1957627	10/27/2022
Customer Number	Branch
901240	Augusta

Remit To: YANCEY BROS. CO. Drawers CS 198757 Atlanta, GA 30384-8757

Ship To:

AUGUSTA, GEORGIA 530 GREENE ST PURCHASING DEPT ROOM 105 AUGUSTA GA 30911-4406

CUSTOMER ORDER NO. P436168 SHIP VIA		STORE	DIV	SALESMAN Jamie Brantley 392		TERMS	PSO/WO NO. 1A03863	DOC. DATE		PC	LC	MC
		01				2		08/22	/2022	10	10	10
		INV SEQ NO.		MAKE	MAKE MODEL	SERIAL NO.	EQUIPMENT NO. 212233	ME	TER READ	,	MACH, ID	
		3252055		AA	D8T	OMLN01622			4395		UP10137	
QUANTITY	ITEM	NR:				DESCRIPTION			UNIT PRIC	CE	EXTEN	ISION
2		9	X7505	SE	AL AS				2	16.93		433.80
4			X8258	W	ASHER					6.06		24.2
4		19	56283	N	UT-SQUARE					5.01		20.0
1		25	45327	W	HEEL-FLAP				•	15.37		15.3
				Tota	l Parts A1						,	1,499.3
				Flat	Rate Labor A1						:	2,322.0
				Tota	Segment A1						;	3,821.3
SEG A2												
REPLACE GAS	SKET/RESEA	AL TRACK A	DJUST	ER								
COMPLAINT:	RESEAL TRA	ACK ADJUS	TER									
CAUSE : SEAL												
RESULTANT [DAMAGE : CO	DULD LEAD	TO LE	AKS IN TH	łE							
CORRECTION												
CORRECTION — 4346 09/27	/2022 AFTER											
CORRECTION — 4346 09/27 FROM ROLLE	/2022 AFTER R FRAMES.	REMOVED	ALL BI	EARINGS,	SEALS,							
CORRECTION — 4346 09/27 FROM ROLLE AND GASKET:	/2022 AFTER ER FRAMES. S. INSTALLE	REMOVED D RETAININ	ALL BI	EARINGS, MPOUND	SEALS, ON							
FUTURE CORRECTION — 4346 09/27 FROM ROLLE AND GASKET: SEALS, REPE FRAME	/2022 AFTER ER FRAMES. S. INSTALLE	REMOVED D RETAININ	ALL BI	EARINGS, MPOUND	SEALS, ON							
CORRECTION — 4346 09/27. FROM ROLLE AND GASKET: SEALS, REPE. FRAME.	/2022 AFTER ER FRAMES. S. INSTALLE ATED SAME	REMOVED D RETAININ PROCESS	ALL BI IG COI ON LH	EARINGS, MPOUND (SIDE ROL	SEALS, ON							
CORRECTION — 4346 09/27 FROM ROLLE AND GASKETS SEALS, REPE FRAME. — 4346 09/29 LATHERED TH	/2022 AFTER ER FRAMES. S. INSTALLE ATED SAME //2022 AFTER HE TRACK AI	REMOVED D RETAININ PROCESS R INSTALLE DJUSTER V	ALL BI NG COI ON LH D NEW VITH O	EARINGS, MPOUND (SIDE ROL (SEALS. IL FOR BE	SEALS, ON LLER							
CORRECTION — 4346 09/27 FROM ROLLE AND GASKETS SEALS. REPE. FRAME. — 4346 09/29 LATHERED THINSTALLATION	/2022 AFTER ER FRAMES. S. INSTALLE ATED SAME //2022 AFTER HE TRACK AI	REMOVED D RETAININ PROCESS R INSTALLE DJUSTER V D TRACK A	ALL BI NG COI ON LH D NEW VITH O DJUST	EARINGS, MPOUND (SIDE ROL / SEALS. IL FOR BE 'ER.	SEALS, ON LER TTER							
CORRECTION — 4346 09/27 FROM ROLLE AND GASKET: SEALS. REPE. FRAME. — 4346 09/29 LATHERED THINSTALLATION 1	/2022 AFTER ER FRAMES. S. INSTALLE ATED SAME //2022 AFTER HE TRACK AI	REMOVED D RETAININ PROCESS R INSTALLE DJUSTER V D TRACK A	ALL BI NG COI ON LH D NEW VITH O DJUST LU105	EARINGS, MPOUND (SIDE ROL / SEALS. IL FOR BE ER. P	SEALS, ON LLER TTER IG BLUE ABS	L T-W T			(54.80		64.8
CORRECTION — 4346 09/27 FROM ROLLE AND GASKETS SEALS. REPE FRAME. — 4346 09/29 LATHERED TH INSTALLATION 1 2	/2022 AFTER ER FRAMES. S. INSTALLE ATED SAME //2022 AFTER HE TRACK AI	REMOVED D RETAININ PROCESS R INSTALLE DJUSTER W D TRACK A BI 3	ALL BI NG COI ON LH D NEW VITH O DJUST LU105 S1223	EARINGS, MPOUND (SIDE ROL SEALS. IL FOR BE ER. P	SEALS, ON LLER TTER IG BLUE ABS EAL-O-RING	LT-WT				7.80		15.6
CORRECTION — 4346 09/27 FROM ROLLE AND GASKETS SEALS. REPE FRAME. — 4346 09/29 LATHERED TH INSTALLATION 1 2 2 2	/2022 AFTER ER FRAMES. S. INSTALLE ATED SAME //2022 AFTER HE TRACK AI	REMOVED D RETAININ PROCESS R INSTALLE DJUSTER W D TRACK A BI 3 3	ALL BI NG COI ON LH D NEW VITH O DJUST LU105 S1223 T5898	EARINGS, MPOUND OF SIDE ROL SEALS. IL FOR BE ER. P SI RI	SEALS, ON LER TITER IG BLUE ABS EAL-O-RING NG	LT-WT			13	7.80 32.92		15.6 265.8
CORRECTION — 4346 09/27 FROM ROLLE AND GASKETS SEALS. REPE FRAME. — 4346 09/29 LATHERED TH INSTALLATION 1 2 2 2 2	/2022 AFTER ER FRAMES. S. INSTALLE ATED SAME //2022 AFTER HE TRACK AI	REMOVED D RETAININ PROCESS R INSTALLE DJUSTER V D TRACK A BI 3 3 7	ALL BI NG COI ON LH D NEW VITH O DJUST LU105 S1223 T5898 G7379	EARINGS, MPOUND OF SIDE ROL SEALS. IL FOR BE TER. P SI RI BI	SEALS, ON LER TTER IG BLUE ABS EAL-O-RING NG EARING	LT-WT			13	7.80 32.92 25.84		15.6 265.8 451.6
CORRECTION — 4346 09/27 FROM ROLLE AND GASKETS SEALS. REPE FRAME. — 4346 09/29 LATHERED TH INSTALLATION 1 2 2 2 2 2 2	/2022 AFTER ER FRAMES. S. INSTALLE ATED SAME //2022 AFTER HE TRACK AI	REMOVED D RETAININ PROCESS R INSTALLE DJUSTER V D TRACK A BI 3 3 7 9	ALL BI NG COI ON LH D NEW VITH O DJUST LU105 S1223 T5898 G7379 W3301	EARINGS, MPOUND SIDE ROL SIDE ROL SEALS. IL FOR BE ER. P SI RI B R	SEALS, ON LER TITER IG BLUE ABS EAL-O-RING NG EARING ING	L T-W T			13 22	7.80 32.92 25.84 62.20		15.6 265.8 451.6 124.4
CORRECTION — 4346 09/27 FROM ROLLE AND GASKETS SEALS. REPEL FRAME. — 4346 09/29 LATHERED TH INSTALLATION 1 2 2 2 2 2 2 2	/2022 AFTER ER FRAMES. S. INSTALLE ATED SAME //2022 AFTER HE TRACK AI	REMOVED D RETAININ PROCESS R INSTALLE DJUSTER V D TRACK A BI 3 3 7 9 9	ALL BI NG COI ON LH D NEW VITH O DJUST LU105 S1223 T5898 G7379 W3301 X4584	EARINGS, MPOUND SIDE ROL SIDE ROL SEALS. IL FOR BE ER. PI SI BI BI SI	SEALS, ON LER ITTER IG BLUE ABS EAL-O-RING NG EARING ING EAL A				13 22 6 36	7.80 32.92 25.84 62.20 63.55		15.6 265.8 451.6 124.4 727.1
CORRECTION — 4346 09/27 FROM ROLLE AND GASKETS SEALS. REPE FRAME. — 4346 09/29 LATHERED TH INSTALLATION 1 2 2 2 2 2 2	/2022 AFTER ER FRAMES. S. INSTALLE ATED SAME //2022 AFTER HE TRACK AI	REMOVED D RETAININ PROCESS R INSTALLE DJUSTER V D TRACK A BI 3 3 7 7 9 9 8	ALL BI NG COI ON LH D NEW VITH O DJUST LU105 S1223 T5898 G7379 W3301	EARINGS, MPOUND SIDE ROL SIDE ROL SEALS. IL FOR BE ER. P SI RI B B SI C	SEALS, ON LER TITER IG BLUE ABS EAL-O-RING NG EARING ING	T 5GA			13 22 6 36	7.80 32.92 25.84 62.20		15.6 265.8 451.6 124.4