




**Central Services Department - Fleet Management Division
Replacement Evaluation Form**

Asset Information	
Department Name:	Fleet Management
Org Key:	626-01-6440
Date:	1-Mar-23
Vehicle Description:	2000 Ford Explorer
Asset Number:	994421
Assigned Use:	The vehicle was used as a pool car and for staff to attend meetings at various locations.
Signature of Director/Elected Official:  Name of Director/Elected Official: Ron Lampkin, Interim Central Services Director	
Purchase Date:	6/19/2000
Purchase Price:	\$22,422.25
Current Mileage:	129,995
Current Hours:	N/A
Replacement Criteria Scoring	
	Score
Miles/Hours	13
Type of Service	3
M&R Cost	4
Reliability	5
Condition	4
Total Score	29
Details <div style="border: 1px solid black; padding: 5px; margin-top: 5px;"> 91% OR \$20,484.90 Paint peeling, does not stay running, smokes once crunk </div>	
Fleet Manager Recommendation: This 2000 Ford Explorer can no longer be used as the vehicle is not safe to operate as it will not stay running and smokes once it is started. The vehicle needs an ABS hydraulic control unit that is no longer available due to age of vehicle.	
Planned Replacement Year:	2023
Funding Source:	2023 Capital
Fleet Manager Approval:	
Name of Fleet Manager:	Laquona C. Sanderson, Fleet Manager
Central Services Director Approval:	
Name of Director:	Ron Lampkin, Interim Central Services Director