

Pearsall Machine Shop
PO BOX 738
Pearsall, TX 78061
830-334-5898
mariame1121@yahoo.com

PROPOSAL

DATE: 04/24/2026

CITY OF BANDERA
Bandera WWTP: Rotary Fan Repairs

1. Remove damaged bearings.
Install new ones on both sides of roller bearings and labor. \$17,300.00
2. Remove shaft front roller. Build new one and install on roller and gear box.
We will need to rent big fork lift / lift boom truck to move roller and install. \$23,300.00
3. Replace damaged plates and frame on doors or gate. Material and labor. \$9,300.00

TOTAL \$49,900.00