Bay St. Louis Historic Preservation Commission, P.O. Box 2550, Bay St. Louis, MS 39521 rtificate of Appropriateness/Concentual Review Application For

	Certificate of Appropriateness/Conceptual Review Application Form		
	Property Address: 343 St George Street		
	Applicant Name: City of Bay Homer Name: David Davzet		
	Mailing Address: 604 N Bengal Post		
	Phone; (228) 4406 - 5516 Phone:		
	Project Classification: Criteria for issuance of certificates of appropriateness can be found in Section VIII of the BSL Historical Preservation Ordinance, No. 509. Please check appropriate box(es)		
	[ ] Conceptual Review: Discuss with the commission preliminary design ideas for a project. The commission will address the appropriateness of the proposal and provide helpful advice. Items needed include, but are not limited to, site plan (plat) indicating where the proposed project is to be built. Photos and/or sketches of the proposed improvements. No architectural drawings are required. A COA will be not be issued for a C.R.		
	[ ] Addition/Renovation: Exterior alterations and or additions should be compatible with the building itself; its original design & style. Items needed: photos of existing improvements. Site plan accurately depicting the placement of current & proposed improvements. Plans & exterior elevations drawn to scale that clearly show the design and architectural character of the proposed addition or alteration as it relates to the existing improvements. List of materials describing the size, textures and other characteristics about their appearance.		
,	[ ] New Construction: New Construction should be visually compatible with the buildings and environment to which it is related, their effect upon the immediate surroundings and the district as a whole while maintaining the rhythm created by building masses, relationships between windows, doors, materials, textures, the patterns, the trims, and the design of the roof. Items needed: Architectural drawings to scale. Site plan, to scale (plat) indicating where the proposed project is to be built. Specific description of materials, types & sizes. Photographs of proposed site. Incomplete application for new construction may be considered under conceptual review.		
	Demolition: Consideration is given to the individual architectural, cultural, and/or historical significance of the resource; the importance or contribution of the resource to the architectural character of the district; and to neighboring property values. Items needed; Photographs of existing building, Site Plan to scale. Condition reports; Foundation plan of replacement and/or documentation of justification.  Thereby certify that I understand this application will not be accepted and processed until all		
	I hereby certify that I understand this application will not be accepted and processed until all requested information has been supplied. I also understand this application may require a site visit/additional research.		
	Applicant's Signature: Date: 3/14/7025		
	Owner' Signature		
	Required: Date:		
	Please refer to the checklist of materials required with your application  A Meeting with the Bay St Louis APC to discuss the specific details of your project is strongly encouraged.		
1	Historic Preservation Commission / City Council Use Only		
	Historic District Control Commission Reviewed Control		
	Recommendation:     Laprockij   Approckity in Conditions		
-	alk course Brodserty Owner (amplicant Signiform)		
į	The state of the s		
-	Togs only Colinial Reviewed.		
	Districting Council Technology  COA Authors Approval I   Clivies   No. Date COA action   District   Coale   Date   Coale   Coa		

USB Historic Ineservation Commissioner (MCLV Connella exident Signature)

Once Completed & Signed - Original copy - HPC, Copy-Building Department

BPC Review /City Council Review



Bay St. Louis



## Historic Preservation Commission

### SUBMITTAL CHECKLIST

Property Owners Information:
Name: David Dauzet
Address:(No P.O. Boxes)
Telephone Number ( ) Cell Number ( )
ADDRESS OF PROPERTY IN QUESTION IF DIFFERENT FROM ADDRESS STATES ABOVE: 343 5+ George Street BSL, MS
Give written scope of work to be performed:
Demo of duelling
,


# **ADDITIONS OR CORRECTIONS** DO NOT REMOVE

Owner's Name: SANDA DAUZAT

Date: 2-24-25

THIS JOB HAS NOT BEEN COMPLETED.  THE FOLLOWING ADDITIONS OR CORRECTIONS SHALL BE MADE BEFORE THE JOB WILL BE ACCEPTED.  This property is in violation of Bay ST Louis city prairances Sec. 22-202 and Sec. 22-204 (See Attached Ordinances), And has been placed On the blighted properties List. Please contact Bay ST Louis Building Department AT 228-469-0531 to discuss this matter and avoid Firsther action, to include citations county city Council proceedings.
ON the blighted properties List, I lesse Contact Bay ST Louis Building Department At 228-469-0531 to discuss this matter and Avoid Further Action, to include citations/court/
Further Action, to include citations/count
D. M. A. A. D. M. A.
It is unlawful for any Carpenter, Contractor, Builder, or other persons, to cover or cause to be covered, any part of the work with flooring lath, earth or other material, until the proper inspector has had ample time to approve the installation.  After additions or corrections have been made, call 228-469-053 Building Department for an inspection. Field Inspectors are the office from
INSPECTED BY: \(\text{len Code exforcement}\) NOTICE OF CORRECTED





DAVID DAUZAT 504-432-2966



Vince Owen <vowen@baystlouis-ms.gov>

#### 343 St George St (Blight)


1 message

Vince Owen <vowen@baystlouis-ms.gov>
To: Vince Owen <vowen@baystlouis-ms.gov>

Wed, Jan 29, 2025 at 4:03 PM









Vince Owen <vowen@baystlouis-ms.gov>

#### 343 St George St. (Blight)

1 message


Vince Owen <vowen@baystlouis-ms.gov>
To: Vince Owen <vowen@baystlouis-ms.gov>

Wed, Jan 29, 2025 at 3:59 PM





Structural engineer report



Compass Floodplain Consultants, LLC P.O. Box 3145 Bay St. Louis, Mississippi 39521 compass3@bellsouth.net September 20, 2023

City of Bay St Louis Structural inspection and analysis of property at 343 George Street, Bay St Louis

On September 12, 2023, I performed an on-site inspection of this property that is within the Bay St Louis Historic District. This inspection was to determine if the structure could economically and safely be retrofitted within reason to meet current code requirements. In addition, the owner obtained additional photos on the interior on September 20, 2023.

During this inspection and a review of all photos, I noted several issues which included.

- Extreme deterioration in the foundation/flooring with structural support members from both weathering and termites.
- Deterioration of the roof structure which included beams, rafters, bracing and a non-existent load path to the walls and foundation.
- Extensive mold on the interior
- Settlement of the entire structure

It is my opinion that the structure cannot be economically or safely retrofitted to meet code due to the extreme structural deterioration of the roof, wall, flooring, and foundation elements. The property will be best served by the owners' intentions for total demolition, that will allow for a new structure that will be compliant with all ordinances and codes within the Historic District. My opinions and analysis are supported by the following photographs:

Sincerely,

Stuart Williamson, P.E., CFM



Hancock County Geoportal and Hancock County 6IN 20X Mosaic parcel # 149E-0-29-118.000 343 St George Steet Dauzat Property



Photo 091223 deterioration of foundation elements



Photo 091223 deterioration from weathering and termites of horizontal support beam



Photo 091223 deterioration from weathering and termites of horizontal support beam



Photo 091223 exterior wall damage from weathering and termites.



Photo 091223 rafter and purlin damage and a non-existent load path from the roof to the exterior walls



Photo 092023 roof deterioration from weathering and termites of rafters, cross bracing and purlins



Photo 092023 roof deterioration of purlins, rafters, and cross bracing. In addition, no indication of a load path connecting rafters and plates to walls.




Photo 092023 interior ceiling damage from weathering and termites cross bracing and purlins can be seen in the background




Photo 092023 interior mold and structural cracks above door indicating settlement.




Photo 092023 a non existent load path from roof to exterior walls and indications of settlement.
Sincerely



possible rebuild floor plan





Compass Floodplain Consultants, LLC P.O. Box 3145 Bay St. Louis, Mississippi 39521 compass3@bellsouth.net September 20, 2023

Clinton Dauzat 343 St George Steet Bay St Louis, MS 39520

Structural inspection and report 343 St George Street

Total Fee \$750

Please Make Check Payable to: Compass Floodplain Consultants, LLC Sincerely

Stuart Williamson

#### Bay St. Louis




#### Historic Preservation Commission

o:	Bay St. Louis City Council
rom:	Clinton Dauzat and Sandra Dauzat
10111.	(Owner)
Re:	343 St George St Bay St Louis MS 39520
	(Property in Question)
	NOTICE OF APPEAL
Counc Comm	This day the applicant comes and files this appeal to the Bay St. Louis City il and would appeal the decision of the Bay St. Louis Historic Preservation ission on October 9, 2023, wherein the Bay St. Louis Historic vation Commission denied and or modified the application.
T	The applicant appeals on the following ground/ reason: he structural report shows significant structural damage from termite, water damage
as we	Il as a recommendation not to rebuild. The home has been hit with multiple large tree
and sl	hifted on the foundation, per the report.
date o: a hear Louis	The applicant acknowledges the time for appeal is 10 business days from the f denial/modification. After the appeal has been filed with the Clerk of Council, ing must be held within 60 days from the filing date of the appeal, by the Bay St City Council, otherwise the appeal shall be considered denied. The appeal to be placed on the City Council agenda no later than the Friday prior to said agenda.
	Respectfully submitted this 11 day of October , 2023
	Clinton Dauzat Owner/Agent Signature

Application

	_
	u
	II Keylew
	×
•	К
	и
	w
ı	Ψ.
,	-
i	3
1	u
ı	ň
ı	=
В	_
ľ	Ä
ú	٦
C	_
1	•
	•
Į	С
	Ę
•	Ę
ċ	5
į	ב כ
	Keview
	Keview
	Keview
	Keview

Bay St. Louis Historic Preservation Commission, P.O. Box 2550, Bay St. Louis, MS 39521  Certificate of Appropriateness/Conceptual Review Application Form		
Property Address: 343 St George St Bay St Louis M5 39520		
Applicant Name: Sandra Dawzat/Clint Dawzatowner Name: SANDra DAuzat		
Malling Address: 604 N Bengal RI LA 7000 Malling Address: SAME		
Phone: (564) 287-1647 Clint Phone: (225) 329-9433		
Project Classification: Criteria for issuance of certificates of appropriateness can be found in Section VIII of the BSL Historical Preservation Ordinance, No. 509. Please check appropriate box(es)		
[ ] Conceptual Review: Discuss with the commission preliminary design ideas for a project. The commission will address the appropriateness of the proposal and provide helpful advice. Items needed include, but are not limited to, site plan (plat) indicating where the proposed project is to be built. Photos and/or sketches of the proposed improvements. No architectural drawings are required. A COA will be not be issued for a C.R.		
[ ] Addition / Renovation: Exterior elterations and or additions should be compatible with the building itself, its original design & style. Items needed: photos of existing improvements. Site plan accurately depicting the placement of current & proposed improvements. Plans & exterior elevations drawn to scale that clearly show the design and architectural character of the proposed addition or alteration as it relates to the existing improvements. List of materials describing the size, textures and other characteristics about their appearance.		
[ ] New Construction: New Construction should be visually compatible with the buildings and environment to which it is related, their effect upon the immediate surroundings and the district as a whole while maintaining the rhythm created by building masses, relationships between windows, doors, materials, textures, the patterns, the trims, and the design of the roof. Items needed: Architectural drawings to scale. Site plan, to scale (plat) indicating where the proposed project is to be built. Specific description of materials, types & sizes. Photographs of proposed site. Incomplete application for new construction may be considered under conceptual review.		
Demolition: Consideration is given to the individual architectural, cultural, and/or historical significance of the resource; the importance or contribution of the resource to the architectural character of the district; and to neighboring property values. Items needed; Photographs of existing building. Site Plan to scale. Condition reports; Foundation plan of replacement and/or documentation of justification.		
I hereby certify that I understand this application will not be accepted and processed until all requested information has been supplied. I also understand this application may require a site visit/additional research.		
Applicant's Signature: Parks Date: 91123		
Owner' Signature		
Required: Date: 9 (11) 2.5		
Please refer to the checklist of materials required with your application  A Meeting with the Bay St Louis HPC to discuss the specific details of your project is strongly encouraged.  Historic Preservation Commission / City Council Use Only		
Historic Olympian Case Number:		
Historic Recognition Corporation Reviewed Review Date:		
Recommendation; [ ] Approval [ ] Approval with Conditions [ ] Disapprove		
Commence		
Requires Property Omier/Applicant Signature		
COA Action: Appendix 11 5 1 YES: [ ] NO Dime COA Action   Region 20   Coa Action   Region 20   Coa Action   C		
Comments:		
Osly Historic Deservation Computes ober 1/ City Council President Standings ( Ools)		



Compass Floodplain Consultants, LLC P.O. Box 3145 Bay St. Louis, Mississippi 39521 compass3@bellsouth.net September 20, 2023

City of Bay St Louis Structural inspection and analysis of property at 343 George Street, Bay St Louis

On September 12, 2023, I performed an on-site inspection of this property that is within the Bay St Louis Historic District. This inspection was to determine if the structure could economically and safely be retrofitted within reason to meet current code requirements. In addition, the owner obtained additional photos on the interior on September 20, 2023.

During this inspection and a review of all photos, I noted several issues which included.

- Extreme deterioration in the foundation/flooring with structural support members from both weathering and termites.
- Deterioration of the roof structure which included beams, rafters, bracing and a non-existent load path to the walls and foundation.
- Extensive mold on the interior
- Settlement of the entire structure

It is my opinion that the structure cannot be economically or safely retrofitted to meet code due to the extreme structural deterioration of the roof, wall, flooring, and foundation elements. The property will be best served by the owners' intentions for total demolition, that will allow for a new structure that will be compliant with all ordinances and codes within the Historic District. My opinions and analysis are supported by the following photographs:

Sincerely,

Stuart Williamson, P.E., CFM



Hancock County Geoportal and Hancock County 6IN 20X Mosaic parcel # 149E-0-29-118.000 343 St George Steet Dauzat Property



Photo 091223 deterioration of foundation elements



Photo 091223 deterioration from weathering and termites of horizontal support beam





Photo 091223 deterioration from weathering and termites of horizontal support beam






Photo 091223 rafter and purlin damage and a non-existent load path from the roof to the exterior walls




Photo 092023 roof deterioration from weathering and termites of rafters, cross bracing and purlins




Photo 092023 roof deterioration of purlins, rafters, and cross bracing. In addition, no indication of a load path connecting rafters and plates to walls.




Photo 092023 interior ceiling damage from weathering and termites cross bracing and purlins can be seen in the background




Photo 092023 interior mold and structural cracks above door indicating settlement.




Photo 092023 a non existent load path from roof to exterior walls and indications of settlement.

Sincerely

