



Bill To: City of Bay St. Louis  
P.O. Box 2550  
Bay St. Louis, MS 39521  
228.466.5450 – 228.466.5451  
Fax: 228.466.5506

**PURCHASING REQUISITION**  
City of Bay Saint Louis

Req By: Debbie Delcuze /  
Auth By: \_\_\_\_\_  
Charge to Acct: \_\_\_\_\_  
Vender Info: Capital Tractor  
Apprvd By: \_\_\_\_\_

Ship To: \_\_\_\_\_  
Received: \_\_\_\_\_

Date	Delivery Date	Ship Via	Project #	Requisition #	Purchase Order #
August 7, 2025			Isuzu NQR Sweeper		
Description of Material			QTY	Price	Amount
Estimate: E28421					
001: Removal and Install of Engine					
Shop Labor					3500.00
70000-10099 Oil, 1 Gallon			2	26.51	53.02
002: Reman of Engine (see detailed estimate attached E28421)					
Shop Customer Labor					8831.80
Requested by: Ronnie					
TOTAL					12,384.82

1925 N Eastern Blvd.  
Montgomery, AL 36109  
Phone: (334) 264-0086

9710 Highway 231 S  
Brundidge, AL 36010  
Phone: (334) 735-5394



5788 Highway 90 W  
Theodore, AL 36582  
Phone: (251) 653-1900

1287 Highway 63 S  
Lucedale, MS 39452  
Phone: (601) 766-3679

www.capitaltractor.com  
Remit to Capital Tractor, Inc.

Estimate: E2842I

COD Date: 08/06/2025

CITY OF BAY ST LOUIS

BAY ST LOUIS, MS

Year		Make/Model		Unit Number		
		2018 KUB V2403T		7JN8248		
Stock No	PO	License	Tag	Customer	Telephone	
125217				51539		

Cond	OpCode	T	Description	Quantity	List	Net	Total
------	--------	---	-------------	----------	------	-----	-------

Type: ENGINE RO Open Date: 08/06/25 Meter In: 1

001 REMOVAL AND INSTALL  
D REMOVAL AND INSTALL OF ENGINE SENDING TO BRUNDIDGE TO REMAN  
CUSTOMER STATES CHECK TURBO - SMOKING - ALSO CHECK FOR BAD OIL  
LINE. SYMPTOMS ARE SMOKES AT HIGH RPM'S, EATS OIL  
TURBO FAILURE. ENGINE HAS A DEAD CYLINDER. NEEDS ENGINE REBUILT  
OR REPLACE

SL L SHOP CUSTOMER LABOR 3500.00  
P 70000-10099 OIL,1 GAL 2.00 26.51 26.51 53.02  
Subtotal charges this section 3553.02

002 REMAN OF ENGINE  
D DISASSEMBLE ENGINE, CLEAN, INSPECT ENGINE COMPONENTS FOR WEAR.  
SEND BLOCK, HEAD, CRANKSHAFT AND COMPONENT TO MACHINE SHOP FOR  
REPAIRS. RE-ASSEMBLE ENGINE WITH NEW PISTONS, RINGS,  
NNECTING  
ROD BEARINGS, MAIN BEARINGS, SEALS, GASKETS, O-RINGS, OIL PUMP,  
WATER PUMP, AND THERMOSTAT USING THE PROPER SPECS LISTED IN THE  
WSM.

F BORE CYLINDERS FOR OVER SIZE PISTON AND RINGS, REWORK CYLINDER  
HEAD, POLISH CRANKSHAFT, JETWASH BLOCK AND ALL ENGINE  
COMPONENTS AND INSTALL NEW MAIN BUSHING  
SL L SHOP CUSTOMER LABOR 8831.80 8831.80  
S OTH SUBLET OTHER OUTSIDE LABOR  
REMAN FROM BRUNDIDGE  
Subtotal charges this section 8831.80

WE APPRECIATE YOUR BUSINESS!

**ARBITRATION AGREEMENT:** The customer identified above, its agents, employees, heirs, subsidiaries, successors, and assigns, (collectively "Customer") and CAPITAL TRACTOR, INC., its agents, employees, heirs, subsidiaries, successors, and assigns (collectively "Capital Tractor") agree that all claims, demands, disputes or controversies of every kind or nature that may arise between them concerning any negotiations for and performance of service or repairs to the above equipment, charges for and quality of such service or repairs, and all other aspects of the service and repairs performed on the above equipment shall be resolved by binding arbitration conducted pursuant to the provisions of 9 U.S.C. 1, et seq., and according to the Commercial Rules of the American Arbitration Association ("AAA"). Either party may demand arbitration by filing with the AAA a written demand for arbitration, along with a statement of the matter in controversy. The Customer and Capital Tractor agree that the arbitration proceedings shall be conducted in Montgomery, Alabama.

**DISCLAIMER:** The undersigned hereby agrees to waive all rights to claim exemption of personal property under the law of the State of Alabama or any other state of the United States. Undersigned agrees to pay all cost of collection, including a reasonable attorney's fee whether or not suit is to be instituted. An express mechanic is lien hereby acknowledged on above unit to secure the amount of repairs thereto. Any warranties on the item(s) sold hereby are those made by the manufacturer and/or those received in writing from the dealer principal of Capital Tractor. All other expressed or implied warranties from any other party are null and void. Capital Tractor is not responsible for loss or damage to vehicle, trailers or articles left in vehicle in case of fire, theft, accident or any other cause beyond Capital Tractor's control. Customer assumes responsibility for damage during loading and unloading to all customer equipment and vehicles.

**TERMS:** Outstanding balance due within 15 days of completed repair. Delinquent payment may result in Capital Tractor pursuing compensation for services rendered as allowed by applicable State law. Service Charge 2% per month (24% annual) on unpaid balance with a minimum of \$5.00 per month.

**STORAGE FEE POLICY:** A storage fee of \$25 per day shall be incurred if Capital Tractor stores equipment for longer than 30 days after the equipment's completed repair. Payment of storage charges is due at the time of equipment pickup or delivery.

**ABANDONMENT POLICY:** All equipment abandoned at a Capital Tractor facility will be appropriately destroyed or sent to auction in accordance with Alabama and Mississippi state laws. Action will be taken to resolve abandonment beginning 60 days after no communication with the equipment owner.

**PARTS RETURN POLICY:** Stock parts are returnable for 30 days. After 30 days, a 15% restocking fee applies. Special order parts are returnable for 15 days with a 20% restocking fee. There are no refunds on freight charges. Electrical parts are non-returnable if opened.

DESC	TOTALS
LABOR	3500.00
PARTS	53.02
SUBLET	8831.80
MISC	
OTHER	
SUBTOTAL	12384.82
TAX	
TOTAL	12384.82

Received By \_\_\_\_\_

capital\_servicepg2.template

CUSTOMER ESTIMATE

page 1 of 1

---

**Sweeper - Isuzu NQR**

Eric Harrison <eharrison@capitaltractor.com>  
o: Debbie Delcuze <ddelcuze@baystlouis-ms.gov>

Tue, Jul 1, 2025 at 9:19 AM

I understand. I will provide a quote of repair and wait for approval before any repairs are made.  
If by chance you elect to not have any repairs performed , a diagnosis fee will be charged based on the amount of time the technician has in it within reason.  
Thank you.

Eric Harrison  
Service Manager | Capital Tractor, Inc.  
O: 251-653-1900 | D: 251-259-6841  
5788 Highway 90 | Theodore, AL 36582  
eharrison@capitaltractor.com | www.capitaltractor.com



---

**From:** Debbie Delcuze <ddelcuze@baystlouis-ms.gov>  
**Sent:** Tuesday, July 1, 2025 9:11 AM  
**To:** Eric Harrison <eharrison@capitaltractor.com>  
**Subject:** Fwd: Sweeper - Isuzu NQR

You don't often get email from ddelcuze@baystlouis-ms.gov. [Learn why this is important](#)

[Quoted text hidden]