



PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2022-LAB-0016

Date: 2/23/2022

Page 1 of 5

Tag #: 2528

JobName: City of Beaumont

Customer Information

Company Name: CITY OF BEAUMONT

Contact: Kevin Lee

Address

Telephone:

550 E 6TH ST

Telephone:

BEAUMONT CA92223

Fax:

Email:

Following is an estimate prepared for you regarding the repair of your Flygt pump.

Product Identification

Product Number: 3301.090-0114

Serial Number: 3301.090-0510002

Model: 3301

Impeller Code: 454

HP: 105

Volts: 0

Phases: 3

Inspection Information

Inspected By: Rick Heaton

Motor Data: Wire Configuration: U1:Red V1:White W1:Black

Megger to ground: R 300 B 300 W 300

Sensors:

Resistance through cable: RB 05 RW 1.0 BW
1.2

FLS

Stator Condition: Poor

CLS

Shaft Condition: Good

KLIX

Oil Condition: Unusable

Bearing

Inspection Plugs:

Cable

Hydraulic: Impeller/Propeller Condition: Unusable

Cable Condition: Good

Volute Condition: Unusable

Cable Length:





PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2022-LAB-0016

Date: 2/23/2022

Page 2 of 5

Tag #: 2528

JobName: City of Beaumont

Hydraulic Type: N
Installation

Type: P

Control

Discharge Size: 6

MFV

Primary Requirement: Plug In Seal Failure

Repair/Service Requirements and remarks

Parts, Labor and Other Charges

Parts:

Qty	PartNo	Description	Sell Price	Total Price
1	657 17 05	KIT,REPAIR BASIC 3301.180	\$7,530.15	\$7,530.15
8	82 43 07	WASHER,SS 46.5MM ID 70MM OD	\$47.60	\$380.80
4	84 19 32	GROMMET,NBR 36ID 70OD 33L	\$60.35	\$241.40
1	608 63 20	IMPELLER,N HT CODE 454 CI	\$6,023.10	\$6,023.10
3	83 53 58	CLAMP,TERMINAL	\$8.24	\$24.73
8	83 53 17	CLAMP,TERMINAL	\$41.65	\$333.20
4	83 53 49	CONNECTION,CROSS	\$8.42	\$33.66
2	83 53 54	SUPPORT,END	\$7.14	\$14.28
1	83 53 50	PARTITION	\$4.93	\$4.93
1	800 45 03	LEAD-THROUGH UNIT	\$183.60	\$183.60
1	608 56 00	COVER,SEAL HOUSING CI	\$3,780.80	\$3,780.80
1	608 53 01	HOLDER,BEARING ALUM	\$831.30	\$831.30
1	663 04 00	SENSOR,LEVEL FLS-10	\$313.65	\$313.65
1	650 51 00	CABLE UNIT	\$94.35	\$94.35
1	663 80 01	STATOR,35-29-4A 460VD	\$7,110.25	\$7,110.25
1	704 60 00	RING,INSERT HC	\$3,983.10	\$3,983.10
1	704 58 00	VOLUTE,HT 6" UVF FV DVB CI	\$6,055.40	\$6,055.40





PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2022-LAB-0016

Date: 2/23/2022

Page 3 of 5

Tag #: 2528

JobName: City of Beaumont

4	83 04 53	SCREW,ALLEN M12 X 45 SS	\$5.61	\$22.44
1	82 44 38	WASHER,STEEL 170MM ID 200MM OD	\$87.55	\$87.55
2	82 44 28	WASHER,STEEL 95MM ID 115MM OD	\$43.35	\$86.70
		Block Price		\$37,135.40
		Total Price		\$37,135.40

Labor and Other Charges:

Qty	PartNo	Description	Sell Price	Total Price
20	14-69 00 00A	LABOR,SVC FLYGT,NO TAX Z1-TP MODELS: 3000,7000,8000	\$153.00	\$3,060.00
1	14-69 00 21D	ENV FEE >50HP TP ENVIRONMENTAL FEE	\$106.00	\$106.00
1	14-69 00 24A	SHOP SUPPLIES-MEDIUM PUMPS TP MISC SUPPLIES FOR REPAIR	\$61.00	\$61.00
		Total Price		\$3,227.00

Total Price: \$40,362.40

Product Replacement

Product Number:

Estimated Delivery: Weeks

Cost of New Unit:

Description:

Terms

Please note: If additional repair requirements are identified during service, the total cost of your repair may change. Should this occur, we will contact you for approval before proceeding.

A signed Purchase Order or approval below must be received before any repair work can begin.

If repaired unit is not picked up or delivered within 5 days of completion, the repair will be invoiced.

Taxes: The prices quoted above do not include any state, federal, or local sales tax or use taxes. Any such taxes as applicable must be added to the quoted prices.



Flygt Products
11161 Harrel Street , Mira Loma CA 91752
PH: (951) 332-3668
FX: (951) 332-3679





PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2022-LAB-0016

Date: 2/23/2022

Page 4 of 5

Tag #: 2528

JobName: City of Beaumont

Terms of delivery: Freight PP/Add Actual

Validity: This Quote is valid for thirty (30) days.

Terms of payment: Net 30 Standard

Warranty: Parts used for this repair carry a 12 month warranty.

This Quote does not include freight charges.

If this product is not repaired or replaced, a fee of \$291.00 will be charged for labor required for the inspection performed.

PLEASE NOTE: IF WE DO NOT HAVE A RESPONSE FROM YOU WITH IN 30 DAYS; WE WILL INVOICE YOU \$351.00 FOR TIME & LABOR HOURS OUR SERVICE DEPARTMENT HAS ALREADY SPENT IN PERFORMING THE TEARDOWN & INSPECTION OF YOUR PRODUCT. YOUR PROMPT ATTENTION & RESPONSE IS GREATLY APPRECIATED. THANK YOU.

Thank you for the opportunity to provide this quotation. Please contact us if there are any questions.

Manny Padilla Jr.

Phone: 562.760.9258

Fax:

Email: manny.padilla@xylem.com





PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2022-LAB-0016

Date: 2/23/2022

Page 5 of 5

Tag #: 2528

JobName: City of Beaumont

Customer Approval

Complete and sign this Approval and return to Xylem Water Solutions USA, Inc with, or in place of, your Purchase Order

I authorize Xylem Water Solutions USA, Inc to proceed for the amount shown above.

Repair

Replacement

Customer Name: _____

Date: _____

Customer Signature: _____

PO #: _____

Ship To:

Will Pick Up

Deliver

Ship To

Ship/Delivery Address:

Bill To:

Taxable:

Yes

No

Tax Exemption Certificate must be on file or tax will be applied to the invoice.

