



PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2021-LAB-0031

Date: 4/15/2021

Page 1 of 5

Tag #: 2437

JobName: City of Beaumont

Customer Information

Company Name: CITY OF BEAUMONT

Contact: Kevin Lee

Address

Telephone:

550 E 6TH ST

Telephone:

BEAUMONT CA92223

Fax:

Email:

Following is an estimate prepared for you regarding the repair of your Flygt pump.

Product Identification

Product Number: 3300.091-5620

Serial Number: 3300.091-0620017

Model: 3300

Impeller Code: 464

HP: 88

Volts: 0

Phases: 3

Inspection Information

Inspected By: Rick Heaton

Motor Data: Wire Configuration: U1:Red V1:Black W1:White

Megger to ground: R INF B INF W INF

Resistance through cable: RB .5 RW .5 BW .6

Stator Condition: Good

Shaft Condition: Good

Oil Condition: Unusable

Inspection Plugs:

Sensors:

FLS

CLS

KLIX

Bearing

Cable

Hydraulic: Impeller/Propeller Condition: Unusable

Cable Condition: Good

Volute Condition: Unusable

Cable Length:

Hydraulic Type: C

Flygt Products

11161 Harrel Street, Mira Loma CA 91752

PH: (951) 332-3668

FX: (951) 332-3679





PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2021-LAB-0031

Date: 4/15/2021

Page 2 of 5

Tag #: 2437

JobName: City of Beaumont

Installation

Type: P

Control

Discharge Size: 6

MFV

Primary Requirement: Impeller wear

Repair/Service Requirements and remarks

Parts, Labor and Other Charges

Parts:

Qty	PartNo	Description	Sell Price	Total Price
1	426 82 00	TERMINAL BOARD UNIT	\$554.00	\$554.00
1	279 76 01	PIPE,BRASS	\$66.00	\$66.00
1	374 81 03	PLATE,LOCKING 304	\$16.00	\$16.00
2	81 73 42	SCREW,SLOTTED M4 X 12 SS	\$2.80	\$5.60
1	393 03 00	WASHER,STEEL	\$28.00	\$28.00
1	391 32 00	COVER,STEEL	\$50.00	\$50.00
1	504 78 11	CABLE UNIT	\$158.00	\$158.00
1	518 89 02	DETECTOR,LEAKAGE UNIT FLS	\$248.00	\$248.00
1	601 89 24	KIT,REPAIR BASIC 3300.180	\$8,173.00	\$8,173.00
1	319 36 20	VOLUTE,HT 6" UVF FV CI	\$7,714.00	\$7,714.00
1	319 38 00	RING,WEAR STATIONARY STEEL/NBR	\$519.00	\$519.00
1	434 50 00	COVER,SUCTION CI	\$3,908.00	\$3,908.00
1	481 72 13	IMPELLER,C HT 335MM CI 3300	\$4,817.00	\$4,817.00
1	84 59 12	ASSEMBLY,LOCKING 55X85	\$327.00	\$327.00
8	82 01 11	SCREW,ALLEN M16 X 70 SS	\$63.00	\$504.00
2	81 41 55	SCREW,HEX M12 X 30 SS	\$5.70	\$11.40
1	433 56 00	COVER,CI	\$166.00	\$166.00
2	82 27 28	NUT,LOCK HEX M10 SS	\$4.60	\$9.20





PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2021-LAB-0031

Date: 4/15/2021

Page 3 of 5

Tag #: 2437

JobName: City of Beaumont

1	502 53 00	GASKET,NBR	\$90.00	\$90.00
2	80 95 07	STUD,M10 X 47 SS	\$24.00	\$48.00
85	94 21 11	CABLE,SUBCAB AWG 1/3-2-1-GC+ 41.7MM	\$66.00	\$5,610.00
1	84 44 19	GROMMET,CR 43ID 60OD 26L	\$166.00	\$166.00
		Block Price		\$33,188.20
		Total Price		\$33,188.20

Labor and Other Charges:

Qty	PartNo	Description	Sell Price	Total Price
24	14-69 00 00A	LABOR,SVC FLYGT,NO TAX Z1-TP MODELS: 3000,7000,8000	\$153.00	\$3,672.00
1	14-69 00 21D	ENV FEE >50HP TP ENVIRONMENTAL FEE	\$98.00	\$98.00
1	14-69 00 24B	SHOP SUPPLIES-LARGE PUMPS TP MISC SHOP SUPPLIES FOR REPAIR	\$91.00	\$91.00
		Total Price		\$3,861.00

Total Price: \$37,049.20

Product Replacement

Product Number:

Estimated Delivery: Weeks

Cost of New Unit:

Description:

Terms

Please note: If additional repair requirements are identified during service, the total cost of your repair may change. Should this occur, we will contact you for approval before proceeding.

A signed Purchase Order or approval below must be received before any repair work can begin.

If repaired unit is not picked up or delivered within 5 days of completion, the repair will be invoiced.

Taxes: The prices quoted above do not include any state, federal, or local sales tax or use taxes. Any such taxes



Flygt Products
11161 Harrel Street , Mira Loma CA 91752
PH: (951) 332-3668
FX: (951) 332-3679





PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2021-LAB-0031

Date: 4/15/2021

Page 4 of 5

Tag #: 2437

JobName: City of Beaumont

as applicable must be added to the quoted prices.

Terms of delivery: Freight PP/Add Actual

Validity: This Quote is valid for thirty (30) days.

Terms of payment: Net 30 Standard

Warranty: Parts used for this repair carry a 12 month warranty.

This Quote does not include freight charges.

If this product is not repaired or replaced, a fee of \$291.00 will be charged for labor required for the inspection performed.

PLEASE NOTE: IF WE DO NOT HAVE A RESPONSE FROM YOU WITH IN 30 DAYS; WE WILL INVOICE YOU \$351.00 FOR TIME & LABOR HOURS OUR SERVICE DEPARTMENT HAS ALREADY SPENT IN PERFORMING THE TEARDOWN & INSPECTION OF YOUR PRODUCT. YOUR PROMPT ATTENTION & RESPONSE IS GREATLY APPRECIATED. THANK YOU.

Thank you for the opportunity to provide this quotation. Please contact us if there are any questions.

Manny Padilla Jr.

Phone: 562.760.9258

Fax:

Email: manny.padilla@xylem.com





PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2021-LAB-0031

Date: 4/15/2021

Page 5 of 5

Tag #: 2437

JobName: City of Beaumont

Customer Approval

Complete and sign this Approval and return to Xylem Water Solutions USA, Inc with, or in place of, your Purchase Order

I authorize Xylem Water Solutions USA, Inc to proceed for the amount shown above.

Repair

Replacement

Customer Name: _____

Date: _____

Customer Signature: _____

PO #: _____

Ship To:

Will Pick Up

Deliver

Ship To

Ship/Delivery Address:

Bill To:

Taxable:

Yes

No

Tax Exemption Certificate must be on file or tax will be applied to the invoice.

