

Serving RI & MA
152 Forbes Street
Riverside, RI 02915



RI Reg. #4266
MA HIC #177317
MA CS #030132

• www.marshallbr.com •

Customer Information

Anne Tortorice
43 Byfield St
Bristol RI 02809


(401) 253-6927 ()
Eden.g@marshallbr.com

Date: 08/16/2024
Rep: Jonathan Pavao
Mobile: (508) 837-0873


The following windows/doors will be installed with full insulation package

Total number of windows being installed	2
Total number of doors being installed	0

ProVia



Inside View



Outside View

Aeries Window

- 1001 - Double Hung
- Oak Interior Material
- Unfinished Inside / White Outside
- White Jamb Pocket
- Opening Size: 32" x 54"
- Unit Size: 31 1/2" x 53 1/2"
- Compound Tension Balance System
- Double Profile DA Locks
- White Hardware
- Extruded Bottom Screen (White) with BetterVue Screen Mesh
- Top Glass:
 - ComforTech DLA-UV
 - Double Strength Glass
 - 1" IG Thickness
- Colonial Contoured Grid - 1V x 0H
- White Grids
- Bottom Glass:
 - ComforTech DLA-UV
 - Double Strength Glass
 - 1" IG Thickness
- Graphite Foam Insulation
- Brickmold with Nail Fin J-Channel Factory Installed
- Unfinished Oak Colonial 2 1/2" Casing

Quantity

1

12099052


Location

Garage

Additional Details

New install garage gable window
Exterior trim 5"

1. 1001 Double Hung Window



Inside View



Outside View

Aerie Window

- 1001 - Double Hung
- Oak Interior Material
- Unfinished Inside / White Outside
- White Jamb Pocket
- Opening Size: 29" x 48"
- Unit Size: 28 1/2" x 47 1/2"
- Compound Tension Balance System
- Double Profile DA Locks
- White Hardware
- Extruded Bottom Screen (White) with BetterVue Screen Mesh
- Top Glass:
- ComforTech DLA-UV
- Double Strength Glass
- 1" IG Thickness
- Colonial Contoured Grid - 1V x 0H
- White Grids
- Bottom Glass:
- ComforTech DLA-UV
- Double Strength Glass
- 1" IG Thickness
- Graphite Foam Insulation
- Brickmold with Nail Fin J-Channel Factory Installed
- Unfinished Oak Colonial 2 1/2" Casing

Quantity

1

12099052

Location

Garage

Additional Details

Left side of garage. New installation. Replace trim 5"

This space intentionally left blank

Image: 1.7
Image: 1.7



Image: 1.8




Image: 1.9

