



25 Byfield Street, Bristol, RI 02809



Window #1 Kitchen Exterior

- Replace sashing
- Broken plaster
- Leaking from windowsill behind paneling



Window #1 Kitchen interior



25 Byfield Street, Bristol, RI 02809



Window #2 Double Hung Kitchen interior



Window #2 & #3 exterior



Window #2 Double Hung Kitchen exterior

- Inside lock broken (\$800 replacement cost)
- Windows do not close properly causing heat loss
- Windows falling apart

25 Byfield Street, Bristol, RI 02809



Window #3 Back
Porch exterior



Window #3 Back Porch interior

- Windows do not close properly causing heat loss
- Porch is freezing in the winter

25 Byfield Street, Bristol, RI 02809



Window #4 Back Porch interior

- Porch is freezing in the winter
- Windows do not close properly causing heat loss



Window #4 & #5 Exterior



Window #5 Bathroom interior

- Concern bathroom pipes will freeze in winter
- Windows do not close properly causing heat loss

25 Byfield Street, Bristol, RI 02809