

OBJECTID	Street Name	PCI	Maintenance Suggestion	Estimated Cost	Repair Prio	Width (ft)	Length (ft)	Area (sy)	Last Repair Method
1	Edwards	86	Crack Sealing	4507	17.5	24	563	1502.269	
2	Tenney Hill	49	Mill & Overlay	269935	63.75	24	1191	3175.709	
3	Edes Falls	31	Reconstruction	84913	86.25	24	255	679.3064	
4	Heath	83	Crack Sealing	722	21.25	24	90	240.7565	
5	Mayberry Hill	81	Crack Sealing	2042	23.75	24	255	680.5981	
6	Quaker Ridge	87	Crack Sealing	27228	16.25	24	3404	9076.151	
7	Point Sebago	100	Defer Maintenance	0	0	24	244	650.0127	Crack Sealing
8	Ring Landing	32	Reconstruction	540167	85	24	1621	4321.333	
9	Heath	77	Crack Sealing	2444	28.75	24	305	814.6497	
10	Point Sebago	95	Defer Maintenance	0	6.25	24	651	1736.013	Crack Sealing
11	Quaker Ridge	64	Mill & Overlay	166600	45	24	735	1960.002	
12	Edes Falls		Grading	110670	0	24	1383	3689.003	
13	Quaker Ridge	83	Crack Sealing	5462	21.25	24	683	1820.548	Mill & Overlay
14	Heath	76	Crack Sealing	8828	30	24	1104	2942.805	
15	Ward	58	Mill & Overlay	44248	52.5	24	195	520.559	
16	Edwards	87	Crack Sealing	8554	16.25	24	1069	2851.286	
17	Spiller	36	Reconstruction	316766	80	24	950	2534.129	
18	Tenney Hill	67	Mill & Overlay	111127	41.25	24	490	1307.374	
19	Mayberry Hill	82	Crack Sealing	1179	22.5	24	147	393.1476	
20	Spiller	40	Mill & Overlay	227503	75	24	1004	2676.504	
21	Maturo	20	Reconstruction	153742	100	24	461	1229.935	
22	Mayberry Hill	78	Crack Sealing	3048	27.5	24	381	1015.944	
23	Quaker Ridge	60	Mill & Overlay	418568	50	24	1847	4924.333	
24	Stone	100	Defer Maintenance	0	0	24	833	2222.151	Reconstruction
25	Shawnee View	27	Reconstruction	133235	91.25	24	400	1065.88	
26	Quaker Ridge	79	Crack Sealing	9305	26.25	24	1163	3101.607	
27	Brown	79	Crack Sealing	2725	26.25	24	341	908.3735	Crack Sealing
28	Fernald	46	Mill & Overlay	63073	67.5	24	278	742.0336	
29	Hillcrest	84	Crack Sealing	9087	20	24	1136	3029.026	
30	Libby	95	Defer Maintenance	0	6.25	24	353	941.4171	Crack Sealing
31	Point Sebago	100	Defer Maintenance	0	0	24	239	638.6366	
32	Tenney Hill	46	Mill & Overlay	201215	67.5	24	888	2367.239	

33 Pine Hill	32 Reconstruction	220318	85	24	661	1762.546	
34 Libby	88 Crack Sealing	1402	15	24	175	467.4199	Crack Sealing
35 Raymond Cape	39 Reconstruction	402170	76.25	24	1207	3217.361	
36 Mayberry Hill	80 Crack Sealing	3441	25	24	430	1146.891	
37 Maturo	32 Reconstruction	495068	85	24	1485	3960.542	
38 Heath	72 Crack Sealing	1244	35	24	155	414.6652	
39 Libby	100 Defer Maintenance	0	0	24	142	379.0711	Crack Sealing
40 Libby	66 Mill & Overlay	88399	42.5	24	390	1039.992	Crack Sealing
41 Quaker Ridge	69 Mill & Overlay	68888	38.75	24	304	810.4485	
42 Andrews	Grading	31112	0	24	389	1037.079	
43 Shawnee View	30 Reconstruction	195698	87.5	24	587	1565.582	
44 Winslow	32 Reconstruction	482032	85	24	1446	3856.26	
45 Point Sebago	94 Defer Maintenance	0	7.5	24	256	681.6124	
46 Mayberry Hill	79 Crack Sealing	7853	26.25	24	982	2617.737	
47 Libby	88 Crack Sealing	23528	15	24	2941	7842.793	Crack Sealing
48 Quaker Ridge	65 Mill & Overlay	274011	43.75	24	1209	3223.656	
49 Brown	80 Crack Sealing	7142	25	24	893	2380.633	Crack Sealing
50 Hams Hill	35 Reconstruction	292520	81.25	24	878	2340.158	
51 Quaker Ridge	49 Mill & Overlay	206474	63.75	24	911	2429.105	
52 Point Sebago	100 Defer Maintenance	0	0	24	355	946.171	Crack Sealing
53 Hillside	Grading	20727	0	24	259	690.9139	
54 Johnson Hill	84 Crack Sealing	6881	20	24	860	2293.627	Crack Sealing
55 Mayberry Hill	78 Crack Sealing	4011	27.5	24	501	1337.052	
56 Casco Village	94 Defer Maintenance	0	7.5	24	761	2028.264	
57 Kimball	80 Crack Sealing	6278	25	24	785	2092.64	
58 Tarkiln Hill	45 Mill & Overlay	31864	68.75	24	141	374.8737	
59 Leach Hill	82 Crack Sealing	44333	22.5	24	5542	14777.73	Crack Sealing
60 Quaker Ridge	81 Crack Sealing	3829	23.75	24	479	1276.396	Mill & Overlay
61 Hillside	76 Crack Sealing	6778	30	24	847	2259.167	
62 Burgess	36 Reconstruction	451454	80	24	1354	3611.628	
63 Raymond Cape	44 Mill & Overlay	100429	70	24	443	1181.518	
64 Quaker Ridge	83 Crack Sealing	6895	21.25	24	862	2298.211	
65 Tenney Hill	80 Crack Sealing	38292	25	24	4787	12764.11	

66 Pine Hill	39 Reconstruction	158297	76.25	24	475	1266.38	
67 Circle	96 Defer Maintenance	0	5	24	857	2285.61	
68 Heath	64 Mill & Overlay	280776	45	24	1239	3303.242	
69 Pine Hill	24 Reconstruction	124756	95	24	374	998.05	
70 Heather	50 Mill & Overlay	198358	62.5	24	875	2333.625	
71 Libby	87 Crack Sealing	5673	16.25	24	709	1891.062	Crack Sealing
72 Leach Hill	100 Defer Maintenance	0	0	24	228	606.8973	
73 Quaker Ridge	61 Mill & Overlay	77539	48.75	24	342	912.2248	
74 Heath	67 Mill & Overlay	726385	41.25	24	3205	8545.706	
75 Tenney Hill	45 Mill & Overlay	10525	68.75	24	46	123.823	
76 Quaker Ridge	90 Defer Maintenance	0	12.5	24	824	2196.571	Mill & Overlay
77 Leach Hill	84 Crack Sealing	26072	20	24	3259	8690.587	
78 Mayberry Hill	83 Crack Sealing	28569	21.25	24	3571	9522.95	
79 Mayberry Hill	82 Crack Sealing	8863	22.5	24	1108	2954.308	
80 Mayberry Hill	80 Crack Sealing	3621	25	24	453	1206.965	
81 Quaker Ridge	78 Crack Sealing	5886	27.5	24	736	1961.92	
82 Leach Hill	100 Defer Maintenance	0	0	24	126	334.8233	
83 Mayberry Hill	75 Crack Sealing	11814	31.25	24	1477	3938.045	
84 Kimball	78 Crack Sealing	3366	27.5	24	421	1121.959	
85 Hillcrest	94 Defer Maintenance	0	7.5	24	244	650.9462	
86 Leach Hill	100 Defer Maintenance	0	0	24	536	1429.404	
87 Glen	100 Defer Maintenance	0	0	24	1671	4455.337	Reconstruction
88 Birch	Grading	25883	0	24	324	862.7601	
89 Pine Hill	32 Reconstruction	527767	85	24	1583	4222.134	
90 Ward	38 Reconstruction	120247	77.5	24	361	961.9789	
91 Point Sebago	88 Crack Sealing	19574	15	24	2447	6524.59	Crack Sealing
92 Leach Hill	82 Crack Sealing	2954	22.5	24	369	984.5593	Crack Sealing
93 Heath	71 Crack Sealing	12067	36.25	24	1508	4022.36	
94 Casco Village	61 Mill & Overlay	72946	48.75	24	322	858.1857	
95 Brown	80 Crack Sealing	546	25	24	68	181.9389	
96 Quaker Ridge	88 Crack Sealing	5673	15	24	709	1891.117	
97 Circle	82 Crack Sealing	2718	22.5	24	340	906.0049	
98 Mayberry Hill	75 Crack Sealing	413	31.25	24	52	137.5997	

99 Riggs	83 Crack Sealing	350	21.25	24	44	116.5482	
100 Overlook	83 Crack Sealing	4459	21.25	24	557	1486.479	Crack Sealing
101 Leach Hill	88 Crack Sealing	2535	15	24	317	844.9951	
102 Quaker Ridge	55 Mill & Overlay	700578	56.25	24	3091	8242.095	
103 Tenney Hill	47 Mill & Overlay	56373	66.25	24	249	663.2119	
104 Cold Springs	56 Mill & Overlay	49401	55	24	218	581.1924	
105 Nakrem	32 Reconstruction	229522	85	24	689	1836.179	
106 Crescent	94 Defer Maintenance	0	7.5	24	560	1494.51	
107 Pine Hill	25 Reconstruction	34277	93.75	24	103	274.2122	
108 Quaker Ridge	67 Mill & Overlay	461094	41.25	24	2034	5424.635	
109 Quaker Ridge	60 Mill & Overlay	299541	50	24	1322	3524.017	
110 Fountain Hill	88 Crack Sealing	8167	15	24	1021	2722.33	
111 Leach Hill	83 Crack Sealing	11567	21.25	24	1446	3855.618	Crack Sealing
112 Tarkiln Hill	52 Mill & Overlay	72579	60	24	320	853.8725	
113 Point Sebago	100 Defer Maintenance	0	0	24	1388	3700.194	Crack Sealing
114 Mayberry Hill	81 Crack Sealing	6442	23.75	24	805	2147.183	
115 Mayberry Hill	80 Crack Sealing	10787	25	24	1348	3595.513	
116 Tenney Hill	51 Mill & Overlay	509552	61.25	24	2248	5994.729	
117 Lakewood	95 Defer Maintenance	0	6.25	24	1783	4753.874	
118 Libby	86 Crack Sealing	3359	17.5	24	420	1119.605	Crack Sealing
119 Raymond Cape	46 Mill & Overlay	99476	67.5	24	439	1170.308	
120 Point Sebago	100 Defer Maintenance	0	0	24	712	1898.412	Crack Sealing
121 Heath	35 Reconstruction	441935	81.25	24	1326	3535.482	
122 Mayberry Hill	76 Crack Sealing	6338	30	24	792	2112.648	
123 Edwards	95 Defer Maintenance	0	6.25	24	681	1815.502	Cross Culvert
124 Tenney Hill	90 Defer Maintenance	0	12.5	24	277	739.1234	
125 Edwards	89 Crack Sealing	10960	13.75	24	1370	3653.193	
126 Lakewood	91 Defer Maintenance	0	11.25	24	908	2421.188	
127 Spiller	51 Mill & Overlay	90908	61.25	24	401	1069.51	
128 Johnson Hill	92 Defer Maintenance	0	10	24	3041	8110.372	Crack Sealing
129 New	93 Defer Maintenance	0	8.75	24	1116	2974.684	
130 Libby	85 Crack Sealing	1801	18.75	24	225	600.3165	Crack Sealing
131 Hams Hill	63 Mill & Overlay	85941	46.25	24	379	1011.073	

132 Quaker Ridge	74 Crack Sealing	1007	32.5	24	126	335.6104	
133 Quaker Ridge	73 Crack Sealing	10631	33.75	24	1329	3543.576	
134 Casco Village	47 Mill & Overlay	77927	66.25	24	344	916.7891	
135 Brown	82 Crack Sealing	7239	22.5	24	905	2413.068	Crack Sealing
136 Jim Small	48 Mill & Overlay	652713	65	24	2880	7678.98	
137 Larkspur	33 Reconstruction	183196	83.75	24	550	1465.568	
138 Point Sebago	78 Crack Sealing	658	27.5	24	82	219.4398	
139 Tenney Hill	80 Crack Sealing	7882	25	24	985	2627.318	
140 Point Sebago	92 Defer Maintenance	0	10	24	156	416.498	
141 Overlook	92 Defer Maintenance	0	10	24	1781	4750.099	Crack Sealing
142 Mayberry Hill	80 Crack Sealing	6797	25	24	850	2265.735	
143 Sonny Maines	29 Reconstruction	109714	88.75	24	329	877.7132	
144 Leach Hill	84 Crack Sealing	5855	20	24	732	1951.592	Crack Sealing
145 Heath	73 Crack Sealing	2925	33.75	24	366	974.8459	
146 Mayberry Hill	78 Crack Sealing	7388	27.5	24	924	2462.718	
147 Mayberry Hill	81 Crack Sealing	4880	23.75	24	610	1626.677	
148 Libby	89 Crack Sealing	4503	13.75	24	563	1501.143	Crack Sealing
149 Cooks Mills	90 Defer Maintenance	0	12.5	24	1378	3674.323	
150 Quaker Ridge	67 Mill & Overlay	178994	41.25	24	790	2105.807	
151 Heath	51 Mill & Overlay	87134	61.25	24	384	1025.109	
152 Tenney Hill	53 Mill & Overlay	50184	58.75	24	221	590.4014	
153 Quaker Ridge	76 Crack Sealing	2343	30	24	293	781.1583	
154 Libby	78 Crack Sealing	7963	27.5	24	995	2654.239	Crack Sealing
155 Cooks Mills	93 Defer Maintenance	0	8.75	24	193	514.8123	
156 Edwards	82 Crack Sealing	6301	22.5	24	788	2100.336	
157 Mayberry Hill	73 Crack Sealing	1372	33.75	24	172	457.4278	
158 Burgess	34 Reconstruction	270683	82.5	24	812	2165.461	
159 Ridge Terrace	29 Reconstruction	317281	88.75	24	952	2538.247	
160 Casco Village	86 Crack Sealing	2081	17.5	24	260	693.8023	
161 Edwards	57 Mill & Overlay	58155	53.75	24	257	684.1733	
162 Tenney Hill	77 Crack Sealing	5393	28.75	24	674	1797.52	
163 Point Sebago	100 Defer Maintenance	0	0	24	129	343.3903	Crack Sealing
164 Quaker Ridge	97 Defer Maintenance	0	3.75	24	534	1422.822	

165 Sunny Hill	94 Defer Maintenance	0	7.5	24	734	1957
166 Moose	94 Defer Maintenance	0	7.5	24	764	2036.118
167 Sunny Hill	49 Mill & Overlay	526051	63.75	24	2321	6188.839
168 Quaker Ridge	73 Crack Sealing	7673	33.75	24	959	2557.75
170 Dadmun Dr	50 Grading	48420	62.5	22	660	1614
171 Millstream Terrace	30 Base Repair (Gravel)	37675	87.5	19	714	1507
172 West Fountain Road	41 Grading	113040	73.75	22	1542	3768
173 Terrace lane	41 Grading	74430	73.75	22	1015	2481
174 Lord Road	41 Grading	397980	73.75	23	5191	13266
175 Pinkham Lane	41 Grading	103920	73.75	22	1417	3464
176 Freeman Road	50 Grading	145050	62.5	22	1978	4835
177 North Pine Hill Road	50 Grading	106170	62.5	22	1448	3539
178 Riggs Road	50 Grading	37860	62.5	22	516	1262
179 Bramble Hill Road	50 Grading	46440	62.5	24	580	1548
180 Camp Cedar Road	50 Grading	180930	62.5	24	2262	6031
181 PavilionRoad	50 Grading	64980	62.5	21	928	2166
182 Stone Road	100 Defer Maintenance	7076	0	20	1592	3538 Reconstruction