



**Broward Sheriff's Office
Cooper City District
10550 Stirling Rd.
Cooper City, FL 33026**

EXTERNAL MEMO

Date: 07-017-2026

To: Mr. Alex Rey
City Manager
City of Cooper City

From: Mr. Richard Brown
Cooper City District Chief
Department of Fire Rescue and Emergency Services

Subject: Fire Chief's Report – Commission Meeting July 21, 2026

The following is the Fire Chief's report for June 2026. The report highlights information pertinent to the city's fire safety concerns: Fire Rescue Incidents, Fire Apparatus / Station concerns, Fire Prevention, and Community Outreach.

I. FIRE / RESCUE INCIDENT REPORT

Fire / Hazardous Condition Related Incidents in Cooper City	53
Medical Related Incidents in Cooper City	213
<u>Fastest Unit Response to Other Jurisdictions</u>	<u>21</u>
Total Incidents	287

II. FASTEST UNIT RESPONSE / MUTUAL AID CALLS

Incidents where Cooper City units have responded to outside jurisdictions and incidents that outside agencies assisted Cooper City.

	Davie	Hollywood	Pembroke Pines	Totals
Cooper City units dispatched to outside jurisdiction	15	0	6	21
Outside agencies responded into Cooper City	12	0	3	15

III. INCIDENT RESPONSE SUMMARY

Total responses	Incident Responses < 6 min.	Priority 1 Incident Responses 6 - 9 min.	Priority 1 Responses > 9 min.	Lower Priority / Non- Emergent Responses	Fastest Unit Responses
287	143	76	5	42	21

IV. FIRE APPARATUS / STATION REPORT

APPARATUS SERVICE DAYS

Unit	Days In-Service	Days Out-of-Service
Q28	31	0
E28	31	0
R28	31	0
R228	5	25 (June) + 9 (July)
DC28	31	0

Rescue 228 - Frontline Unit was placed back in service July 9th

New Quint 28 Update: The vehicle is currently at Ten-8 to correct some minor issues found while “fitting out” the apparatus. It should be back to BSO Fire Fleet to continue equipping the truck. Manufacture’s training for the new Quint was provided to our crews on June 1st, 2nd and 3rd.

NEW Rescue 28 Update: The rescue vehicle was returned to Fire Fleet (6700 Powerline Road, Ft. Lauderdale) by the manufacturer to with only some of the agree upon corrections completed. BSO Fire Fleet manager sent a detailed email noting what was corrected and the issues that remain.


V. FIRE PREVENTION

Construction Plans Reviewed	19
Annual Fire Inspections	82
New Business Inspections	2
Complaint Inspections	1
Construction Permit Inspections	11
FY Annual Inspections Completed	63.7%


VI. COMMUNITY OUTREACH REPORT

- 6/4: Car Seat Install / Checkup (Life Safety Educators)
- 6/18: Teen Safety Symposium – Cooper City Church of God (Station 28 Units / Crews Rotated in Attendance and Assistance)
- 6/20 Station 28 Tour – Cooper City Home School Group (Station 28 Crewmembers)
- 6/23: Station 28 Tour – Nee's Kung Fu Summer Camp (Station 28 Crewmembers, Life Safety Educators)
- 6/26: Car Seat Install / Checkup (Life Safety Educators)

VII. Total Response by Incident Type



VIII. Map of Response Time Outliers



Cause for Delayed Response

- A. Distance
- B. Mechanical
- C. Distance
- D. Distance
- E. Distance

Response Time

09:11
09:23
09:25
10:21
10:42

Time of Day

15:20
21:37
02:16
00:57
00:22

Type of Incident

Fire Alarm
Medical
Medical
Electrical Fire
Medical