

INVOICE

Printed Date: 12/19/2025 **Work Completed: 12/19/2025**

COTTAGE CITY POLICE DEPARTMENT

2013 Ford - Explorer Police Interceptor - 3.7L, V6 (227CI) VIN(F
 Lic # : MG2720 Odometer In : 175108

Cellular 301-741-2287

VIN # : 1FM5K8AR3 **DGA56177**

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Catalytic Converter-Front Right Direct Fit w/Manifold DEALER	1.00	1,450.00	1,450.00	CHECK ENGINE LIGHT ON . CODE: P0420 CATALYTIC CONVERTER SYSTEM LOW BANK 1	338.00
Oxygen Sensor-Downstream WP	1.00	110.36	110.36	CATALYTIC CONVERTER - Remove & Replace - V6,Normally Aspirated,AWD Right Side	
Oxygen Sensor-Upstream WP	1.00	199.51	199.51	Air conditioning not working, replace schrader valve for a/c,Service air conditioner. Check condition of all belts and lines. Evacuate and recharge with reclaimed R-134. Test system performance.	250.00
Battery 850 CCA : RC = 150 WP	1.00	232.41	232.41	REAR RIGHT TIRE HAS LEAK DUE TO SCREW TIRE WAS PATCHED THREW THE INSIDE OUT.	45.00
Strut Assembly-Front Left 3340303	1.00	259.00	259.00	FRONT LEFT STRUT AND SWAY BAR LIKES HAS PLAY	n/c
Sway Bar Link-Front Left GB5Z 5K483-A	1.00	92.04	92.04	REPLACE STRUT AND BOTH SWAY BAR LIKES FREE.	
Sway Bar Link-Front Right GB5Z 5K484-A	1.00	80.02	80.02	[Discount] \$194.23 off labor	
Shop Supplies			20.00	Hazardous Materials	17.89

Org. Estimate 2,663.17 Revisions 0.00 Current Estimate 2,663.17

Labor:	633.00
Parts:	2,443.34
HazMat:	17.89
Discount:	-194.23
SubTotal:	2,900.00
Tax:	0.00
Total:	2,900.00
Bal Due:	\$2,900.00

[Payments -]

Vehicle Received: 12/19/2025

Customer Number : 5517

**** THERE IS NO WARRANTY FOR PARTS PROVIDED BY THE CUSTOMER ****

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspect. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 6 months or 6,000 miles whichever comes first. WITH THE EXCEPTION OF USED YUNK YARD PARTS. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature A/Chief D. Thompson

Date 12/19/25

Email Address: ebenezerautorepair6@gmail.com