2848

2/10/2025

Odyssey Shankle Bus and Truck

Repair

5200 46th Avenue Hyattsville, MD 20781 servicemngr@odyshank.com (301) 699-8500

Bill To

TOWN OF COTTAGE CITY 3820 40TH AVENUE BRENTWOOD, MD 20722

P: 240-461-3835

Remit Payment To

Primary

5200 46th Avenue Hyattsville, MD 20781

Estimate

Date:

	Service Order Pu	urchase Order	Authorizer	
	2848			
Item	Description	Quantity	Rate	Amount
=	nt: INSPECT SALT SPREADER CUTS OFF AFETE ER CONTROL HAS POWER BUT NOT SENDING			
Cause:				
Labor	Recommended Correction: Chassis / Chassis /	1.00000	\$170.00	\$170.00
			Subtotal	\$170.00
Complain	nt: REPLACE SERVICE KIT, AUGER SHORT AND	BEARING		
•	Customer request (Inspection)	, DET WHITE		
•		6.00000	\$170.00	\$1,020.00
Cause: (Customer request (Inspection) Recommended Correction: Chassis / Chassis / REPLACE SERVICE KIT, A	6.00000	*******	\$1,020.00 \$1,042.86
Cause: (Labor	Customer request (Inspection) Recommended Correction: Chassis / Chassis / REPLACE SERVICE KIT, A BEARING	6.00000 AUGER SHORT AND	*******	
Cause: (Labor	Customer request (Inspection) Recommended Correction: Chassis / Chassis / REPLACE SERVICE KIT, A BEARING SERVICE KIT AUGER - A	6.00000 AUGER SHORT AND 1	\$1,042.8625	\$1,042.86
Cause: (Customer request (Inspection) Recommended Correction: Chassis / Chassis / REPLACE SERVICE KIT, A BEARING SERVICE KIT AUGER - A	6.00000 AUGER SHORT AND 1	\$1,042.8625 \$159.195	\$1,042.86 \$159.20
Cause: (Labor	Customer request (Inspection) Recommended Correction: Chassis / Chassis / REPLACE SERVICE KIT, A BEARING SERVICE KIT AUGER - A FRONT AUGER BEARING - A	6.00000 AUGER SHORT AND 1	\$1,042.8625 \$159.195 Subtotal	\$1,042.86 \$159.20 \$2,222.06

Page: 2 of 2

Item Description	Quantity Rate	e Amount
Unit: mes-13989 VIN: 1FTWF31578EC87954 License Plate: md83815	Labor	\$1,190.00
2008FordF-350	Parts	\$1,202.06
Chassis: 47,503 Miles	HAZ MAT(1.50% of \$2,451.56)	\$36.77
	Subtotal	\$2,488.33
	Exempt (0% of \$0.00)	\$0.00
	Credit Card Pass-Through fee (3.000% of \$2,488.33)	\$74.65
	Total	\$2,562.98

^{*:} Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.

The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature:	
Printed Name:	Date: