Dalton, GA

This report was generated on 1/5/2022 8:57:01 AM



Incident Statistics

Zone(s): All Zones | Start Date: 12/01/2021 | End Date: 12/31/2021

	Zone(s). All Zones Start Date. 12/01/2021 End Date. 12/31/2021			
INCIDENT COUNT				
INCIDEN	INCIDENT TYPE		# INCIDENTS	
EMS			208	
	FIRE		114	
TOT			322	2
		PORTS (N2 and N3)		
APPARATUS	# of APPARATUS TRANSPORTS	# of PATIENT TRAN	SPORTS	TOTAL # of PATIENT CONTACTS
TOTAL				
PRE-INCIDE	ENT VALUE		LOSS	SES
\$770,3			\$42,80	0.00
		CHECKS		
736 - CO detector activa			2	
TOT			2	
	MUTUAL AI	ס		
Aid 7			Total	
	Aid Given		20	
Aid Re			1	
		PING CALLS		
	# OVERLAPPING % OVERLAPPING 84 26.09			
	4 TS AND SIREN - AVERAGE F	PESPONSE TIME (Disp.	26.0	
		•	aton to An	•
Station		EMS		FIRE
Station 1		04:11		0:04:17
Station 2	0:	04:38		0:05:49
Station 3	0:	04:11		0:05:22
Station 4	0:	0:04:01		0:05:42
Station 5	0:	05:15		0:06:38
	AVER	AGE FOR ALL CALLS		0:04:30
LIGHTS AND SIREN - AVERAGE TURNOUT TIME (Dispatch to Enroute)				
Station		EMS		FIRE
Station 1	0:	01:13		0:01:31
Station 2	0:	01:10		0:01:48
Station 3		0:01:16		0:01:18
Station 4		0:01:04		0:01:07
Otation 4	0.	01.07		0.01.07

Only Reviewed Incidents included. EMS for Incident counts includes only 300 to 399 Incident Types. All other incident types are counted as FIRE. CO Checks only includes Incident Types: 424, 736 and 734. # Apparatus Transports = # of incidents where apparatus transported. # Patient Transports = All patients transported by EMS. # Patient Contacts = # of PCR contacted by apparatus. This report now returns both NEMSIS 2 & 3 data as appropriate. For overlapping calls that span over multiple days, total per month will not equal Total count for year.



Station 5	0:00	:42	0:01:13
	AVERAGE FOR ALL CALLS		0:01:12
AGENCY		AVERAG	GE TIME ON SCENE (MM:SS)
Dalton Fire Department			18:35



Dalton, GA

This report was generated on 1/5/2022 8:57:57 AM



Monthly Incident Hydrant and Fire Marshal Services Report

Start Date: 12/01/2022 | End Date: 12/31/2022

Average Response Time - 1st arriving Unit		
Structure Fires	00:00	
Other Fires	00:00	
MVAs	00:00	
All EMS	00:00	
All Incidents	00:00	

Incident Count by Type		
Fires (100-199)	Total: 0	
Total Structure Fires (111,112)	0	
Structure Fires (111,112) w/Hose Deployment	0	
Other Fires (100, 113 – 173)	0	
Total Water Usage for all Fires	0	

EMS (300-399)	Total: 0
Medical Assist, Assist EMS Crew (311)	0
EMS call, excluding vehicle accident with injury (321)	0
Motor Vehicle Accidents (322,323,324)	0
Rescue (350 – 372)	0
All other EMS (300, 320, 331, 340-343, 381)	0
Specialized Responses (400-499)	Total: 0
Service Calls (500-599)	Total: 0
Lockouts (511)	0
Public Service (550 - 555)	0

All Other Incidents (200s, 600s – 900s)	Total: 0
Total Calls for Date Range (100 - 999)	Total: 0

Mutual and Automatic Aid	
Total Mutual and Automatic Aid Given for Fire (100s)	0
Total Mutual and Automatic Aid Received for Fire (100s)	0
Total Mutual and Automatic Aid Given for EMS (300s)	0

Only Completed and Reviewed Primary Exposure Reports are in calculations.



Dalton, GA

This report was generated on 1/5/2022 8:57:57 AM



Hydrants	
Hydrants Tested	0
Fire Marshal Services	




Dalton, GA

This report was generated on 1/5/2022 8:58:42 AM



Incidents by Day of the Week for Date Range

Start Incident Type: 100 | End Incident Type: 911 | Start Date: 12/1/2021 | End Date: 12/31/2021



DAY OF THE WEEK	# INCIDENTS
Sunday	38
Monday	42
Tuesday	42
Wednesday	69
Thursday	50
Friday	45
Saturday	36

TOTAL 322

Page # 1 of 1


Dalton, GA

This report was generated on 1/5/2022 8:59:10 AM



Incidents per Zone per Shift for Date Range

Start Date: 12/01/2021 | End Date: 12/31/2021



SHIFT	ZONE	# INCIDENTS
A	District 1	33
	District 2	20
	District 3	20
	District 4	15
	District 5	6
	Whitfield county	6
В	District 1	27
	District 2	19
	District 3	22
	District 4	19
	District 5	5
	Whitfield county	17
С	District 1	39
	District 2	24
	District 3	18
	District 4	13
	District 5	11
	Whitfield county	8

TOTAL: 322




Dalton, GA

This report was generated on 1/5/2022 8:59:43 AM



Incidents per Hour for Incident Type Range for Date Range

Start Incident Type: 100 | End Incident Type: 911 | Start Date: 12/01/2021 | End Date: 12/31/2021



HOUR	# of CALLS
00:00 - 00:59	14
01:00 - 01:59	9
02:00 - 02:59	12
03:00 - 03:59	7
04:00 - 04:59	3
05:00 - 05:59	6
06:00 - 06:59	11
07:00 - 07:59	8
08:00 - 08:59	16
09:00 - 09:59	21
10:00 - 10:59	14
11:00 - 11:59	15
12:00 - 12:59	19
13:00 - 13:59	15
14:00 - 14:59	20
15:00 - 15:59	11
16:00 - 16:59	13
17:00 - 17:59	18
18:00 - 18:59	21
19:00 - 19:59	15
20:00 - 20:59	16
21:00 - 21:59	12
22:00 - 22:59	13
23:00 - 23:59	13
TOTAL:	322

Only REVIEWED incidents included.



Dalton, GA

This report was generated on 1/5/2022 9:00:21 AM



Incident Type Count per Station for Date Range

Start Date: 12/01/2021 | End Date: 12/31/2021

INCIDENT TYPE	# INCIDENTS
Station: 1 - STATION 1	
111 - Building fire	1
151 - Outside rubbish, trash or waste fire	1
163 - Outside gas or vapor combustion explosion	1
311 - Medical assist, assist EMS crew	68
322 - Motor vehicle accident with injuries	4
412 - Gas leak (natural gas or LPG)	2
444 - Power line down	1
445 - Arcing, shorted electrical equipment	1
500 - Service Call, other	7
551 - Assist police or other governmental agency	1
561 - Unauthorized burning	1
611 - Dispatched & cancelled en route	7
622 - No incident found on arrival at dispatch address	1
733 - Smoke detector activation due to malfunction	1
735 - Alarm system sounded due to malfunction	5
743 - Smoke detector activation, no fire - unintentional	3
744 - Detector activation, no fire - unintentional	1
745 - Alarm system activation, no fire - unintentional	6

Incidents for 1 - Station 1:

Station: 2 - STATION 2					
111 - Building fire	2				
151 - Outside rubbish, trash or waste fire	1				
311 - Medical assist, assist EMS crew	40				
322 - Motor vehicle accident with injuries	6				
323 - Motor vehicle/pedestrian accident (MV Ped)	1				
324 - Motor vehicle accident with no injuries.	2				
444 - Power line down	2				
445 - Arcing, shorted electrical equipment	1				
611 - Dispatched & cancelled en route	9				
651 - Smoke scare, odor of smoke	1				
743 - Smoke detector activation, no fire - unintentional	2				
745 - Alarm system activation, no fire - unintentional	1				

Incidents for 2 - Station 2:

Only REVIEWED incidents included.



112

68

INCIDENT TYPE	# INCIDENTS						
Station: 3 - STATION 3							
143 - Grass fire	1						
251 - Excessive heat, scorch burns with no ignition	1						
311 - Medical assist, assist EMS crew	31						
322 - Motor vehicle accident with injuries	8						
324 - Motor vehicle accident with no injuries.	2						
411 - Gasoline or other flammable liquid spill	1						
561 - Unauthorized burning	1						
611 - Dispatched & cancelled en route	13						
733 - Smoke detector activation due to malfunction	3						
735 - Alarm system sounded due to malfunction	1						
736 - CO detector activation due to malfunction	1						
743 - Smoke detector activation, no fire - unintentional	1						
745 - Alarm system activation, no fire - unintentional	1						
# Incidents for 2 Ctation 2.	CE						

Incidents for 3 - Station 3: 65

Station: 4 - STATION 4					
131 - Passenger vehicle fire	3				
142 - Brush or brush-and-grass mixture fire	1				
311 - Medical assist, assist EMS crew	27				
322 - Motor vehicle accident with injuries	2				
324 - Motor vehicle accident with no injuries.	1				
353 - Removal of victim(s) from stalled elevator	1				
553 - Public service	1				
611 - Dispatched & cancelled en route	2				
622 - No incident found on arrival at dispatch address	1				
735 - Alarm system sounded due to malfunction	3				
743 - Smoke detector activation, no fire - unintentional	4				
744 - Detector activation, no fire - unintentional	1				
745 - Alarm system activation, no fire - unintentional	4				

Incidents for 4 - Station 4: 51

Station: 5 - STATION 5					
311 - Medical assist, assist EMS crew	10				
322 - Motor vehicle accident with injuries	3				
323 - Motor vehicle/pedestrian accident (MV Ped)	1				
357 - Extrication of victim(s) from machinery	1				
571 - Cover assignment, standby, moveup	1				
611 - Dispatched & cancelled en route	6				
736 - CO detector activation due to malfunction	1				
741 - Sprinkler activation, no fire - unintentional	1				
743 - Smoke detector activation, no fire - unintentional	2				

Incidents for 5 - Station 5: 26

Only REVIEWED incidents included.



emergencyreporting.com Doc Id: 857 Page # 2 of 2


Dalton, GA

This report was generated on 1/5/2022 9:00:59 AM



Major Incident Types by Month for Date Range

Start Date: 12/01/2021 | End Date: 12/31/2021



INCIDENT TYPE	DEC	TOTAL
False Alarm & False Call	42	42
Fire	11	11
Good Intent Call	40	40
Hazardous Condition (No Fire)	8	8
Overpressure Rupture, Explosion, Overheat(no fire)	1	1
Rescue & Emergency Medical Service Incident	208	208
Service Call	12	12
Total	322	322


Dalton, GA

This report was generated on 1/5/2022 9:01:28 AM



Count of Aid Given and Received for Incidents for Date Range

Start Date: 12/01/2021 | End Date: 12/31/2021



AID TYPE	TOTAL	% of TOTAL
Automatic aid received	1	0.3%
Mutual aid given	1	0.3%
Automatic aid given	19	5.9%
None	301	93.5%

Dalton, GA

This report was generated on 1/5/2022 9:01:56 AM



Detailed Fire Losses per Incident Type for Date Range

Start Date: 12/01/2021 | End Date: 12/31/2021

INCIDENT TYPE	COUNT	% OF INCIDENTS	TOTAL LOSSES (Sum of Property and Content Loss)	% OF TOTAL
111 - Building fire	4	66.67 %	\$32,500.00	75.93 %
131 - Passenger vehicle fire	2	33.33 %	\$10,300.00	24.07 %

Only REVIEWED incidents included.



Dalton, GA

This report was generated on 1/5/2022 9:02:37 AM



Detailed Property And Contents Saved for Date Range

Start Date: 12/01/2021 | End Date: 12/31/2021

INCIDENT #	DATE	TYPE	LOCATION	PRE-INCIDENT PROPERTY	PRE-INCIDENT CONTENTS	PRE- INCIDENT TOTAL	PROP. SAVED	CONT. SAVED	TOTAL SAVED
2021-03713	12/04/2021	131 - Passenger vehicle fire	1303 W Walnut AVE Dalton	\$25,000.00	\$300.00	\$25,300.00	\$23,000.00	\$0.00	\$23,000.00
2021-03776	12/11/2021	111 - Building fire	710 5th AVE Dalton	\$200,000.00	\$5,000.00	\$205,000.00	\$180,000.00	\$2,500.00	\$182,500.00
2021-03776	12/11/2021	111 - Building fire	710 5th AVE Dalton	\$200,000.00	\$5,000.00	\$205,000.00	\$198,000.00	\$4,000.00	\$202,000.00
2021-03776	12/11/2021	111 - Building fire	710 5th AVE Dalton	\$200,000.00	\$0.00	\$200,000.00	\$198,000.00	\$0.00	\$198,000.00
2021-03884	12/21/2021	131 - Passenger vehicle fire	Battlefield Prk Dalton	\$10,000.00	\$0.00	\$10,000.00	\$2,000.00	\$0.00	\$2,000.00
2021-03921	12/25/2021	111 - Building fire	843 Mcafee ST Dalton	\$125,000.00	\$0.00	\$125,000.00	\$120,000.00	\$0.00	\$120,000.00

TOTAL PRE- INCIDENT PROPERTY	TOTAL PRE- INCIDENT CONTENT	TOTAL PRE- INCIDENT	TOTAL PROP. SAVED	TOTAL CONT. SAVED	TOTAL SAVED
\$760,000.00	\$10,300.00	\$770,300.00	\$721,000.00	\$6,500.00	\$727,500.00

# INCIDENTS	AVG. VAL.	AVERAGE SAVED
6	\$128,383.00	\$121,250.00



Training Division Monthly Report December 2021

Overview

Year-end audits were completed and compliance reports were uploaded to Georgia Firefighter Standards and Training Council's records management system. Monthly training included territory familiarization, pre-fire training, core competency check-offs, special operations training, and company level drills chosen by company officers. Training hours during the month of December totaled 480.

Outside Schools

1 of the department's licensed paramedics completed Pediatric Advanced Life Support.

1 firefighter gained state and national certification after completing Fire Instructor 1 hosted by Gordon County Fire Rescue.

1 firefighter attended Rescue Systems 1: Fundamentals of Heavy Rescue at GPSTC.

Dalton, GA

This report was generated on 1/3/2022 12:01:10 PM



Completed Inspections per Inspection Type for Date Range

Occupancy Status: All | Start Date: 12/01/2021 | End Date: 12/31/2021

ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
Inspection Typ	e: Alcohol					
10736 - 15	Mistika	1001 Market ST #Suite 25 Dalton, GA 30720	12/20/2021	Hearn, Scott Raymond	Corrective Action Plan Given	
Total # Inspections for Alcohol:						1

					•				
Inspection Typ	nspection Type: Annual								
10866	Dalton Bearing	aring 601 S Glenwood AVE Dalton, GA 30720		Hearn, Scott Raymond	Corrective Action Plan Given	Add Knox Box to building.			
10148 - 4	48 - 4 United Grocery Outlet 912 N Glenwood AVE Dalton, GA 30721		12/01/2021	Hearn, Scott Raymond	Passed with Comments	Replace ceiling tiles.			
11410 - 1	La Esperanza Apartments	1702 E Morris ST Dalton, GA 30720	12/01/2021	Blankenship, Donnie	Failed				
11410	La Esperanza Bakery	1702 E Morris ST Dalton, GA 30720	12/01/2021	Blankenship, Donnie	Corrective Action Plan Given				
11417	Georgia United Credit Union 605 Calhoun ST Dalton, GA 30721		12/01/2021	Hearn, Scott Raymond	Passed				
10810	Georgia United Credit Union	1412 Chattanooga AVE Dalton, GA 30720	12/01/2021	Hearn, Scott Raymond	Passed				
11414	11414 Industrial Automation 205 E I Products Dalton,		12/01/2021	Hearn, Scott Raymond	Corrective Action Plan Given				
10872	Mohawk Carpets	431 S Green ST Dalton, GA 30720	12/02/2021	Hearn, Scott Raymond	Passed				
11418	Gordon Brown personal storage	1212 New East Morris ST Dalton, GA 30721	12/02/2021	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.			
11300 - 3	Product Factory	1309 E Morris ST #3 Dalton, GA 30721	12/02/2021	Stratton, Dale Lee	Passed				
11300 - 2	Vacant	1309 E Morris ST #2 Dalton, GA 30721	12/02/2021	Stratton, Dale Lee	Passed				
11300 - 1	Frank Cronan	1309 E Morris ST #1 Dalton, GA 30721	12/02/2021	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.			
10202	Reformation Baptist Church of Dalton	244 N Hamilton ST Dalton, GA 30720	12/02/2021	Hearn, Scott Raymond	Passed				

Includes LOCKED inspections for both archived and unarchived occupancy records.



ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
Inspection Typ	oe: Annual					
11056	AC Delco	415 S Spencer ST Dalton, GA 30721	12/06/2021	Hearn, Scott Raymond	Corrective Action Plan Given	Add Knox Box to building.
10840	Shaw Plant # 3	715 S Glenwood AVE Dalton, GA 30721	12/09/2021	Hearn, Scott Raymond	Corrective Action Plan Given	
10841	Shaw Plant # 1	601 1st AVE Dalton, GA 30721	12/09/2021	Hearn, Scott Raymond	Corrective Action Plan Given	
11055	Advanced Adhesive Technology	424 S Spencer ST Dalton, GA 30721	12/09/2021	Hearn, Scott Raymond	Corrective Action Plan Given	
11415	Advanced Adhesive Technology	421 S Spencer ST Dalton, GA 30721	12/09/2021	Hearn, Scott Raymond	Corrective Action Plan Given	
11421	Felker Construction	300 Fernwood AVE Dalton, GA 30721	12/10/2021	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
11300 - 4	Providence Ministries	1309 E Morris ST #4 Dalton, GA 30721	12/10/2021	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
11300 - 5	Providence Ministries	1309 E Morris ST Dalton, GA 30721	12/10/2021	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
10853	Dalton Metal Fabricating.	615 Fourth AVE Dalton, GA 30720	12/13/2021	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
10852	Hill & Williams Brothers Inc.	434 Fourth AVE Dalton, GA 30720	12/14/2021	Stratton, Dale Lee	Corrective Action Plan Given	A corrective action plan has been provided.
10851	Blanca's Furniture	406 Fourth AVE Dalton, GA 30720	12/14/2021	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
10276 - 1	Wells Fargo Bank	201 S Hamilton ST Dalton, GA 30720	12/21/2021	Hearn, Scott Raymond	Passed	

Total # Inspections for Annual: 25

Inspection Type	Inspection Type: Complaint								
11205 - 9	Delicias Reinita Restaurante y Buffet Mexicano	101 W Walnut AVE #19 Dalton, GA 30720	12/02/2021	Stratton, Dale Lee	Failed	A corrective action plan has been provided. A re-inspection will be conducted in 30 days.			

Total # Inspections for Complaint:





ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
Inspection Typ	e: Kitchen Hood Installation	on		-	-	
11142	Krystal	1909 E Walnut AVE Dalton, GA 30721	12/07/2021	Blankenship, Donnie	Corrective Action Plan Given	Kitchen Hood Inspection was conducted by Inspectors Blankenship and Stratton, to observe final testing of the hood suppression system and the hood system installation. During testing, an electrical shunt failed to operate. The hood installment contractor stated that he would have the electrician make the appropriate repairs and that the system would be operable by 12/08/2021. The paper work finalizing the installation was not signed.
11142	Krystal	1909 E Walnut AVE Dalton, GA 30721	12/08/2021	Blankenship, Donnie	Passed	
			Total #	Inspections for Kite	chen Hood Installation:	2
Inspection Typ	e: New Construction					
10325	Cuyler Triplex	402 W Cuyler ST Dalton, GA 30720	12/17/2021	Blankenship, Donnie	Corrective Action Plan Given	
10325	Cuyler Triplex	402 W Cuyler ST Dalton, GA 30720	12/20/2021	Blankenship, Donnie	Corrective Action Plan Given	Previously discussed issues remain. The owner was advised to contact us once the remaining issues were corrected.
				Total # Inspections	for New Construction:	2
Inspection Typ	oe: OTC					
11419	Allergy & Asthma Group of Galen	1011 Professional BLVD Dalton, GA 30720	12/06/2021	Hearn, Scott Raymond	Corrective Action Plan Given	
10073 - 2	Danny's Cafe`	617 E Morris ST Dalton, GA 30720	12/07/2021	Hearn, Scott Raymond	Passed	
11127 - 1	Reyna Rosalinda	1137 Walnut (East) AVE Dalton, GA 30720	12/10/2021	Hearn, Scott Raymond	Passed	
10525	JRG Space, LLC	909 Trammell ST Dalton, GA 30720	12/16/2021	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
10456 - 5	My Tech Bench	1209 N Glenwood AVE Dalton, GA 30721	12/16/2021	Hearn, Scott Raymond	Passed	
11265	Allan's Tires	1104 S Thornton AVE Dalton, GA 30720	12/16/2021	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
10340 - 1	Nizzie Package Store	1902 Chattanooga RD Dalton, GA 30720	12/20/2021	Blankenship, Donnie	Corrective Action Plan Given	
10736 - 15	Mistika	1001 Market ST #Suite 25 Dalton, GA 30720	12/20/2021	Hearn, Scott Raymond	Corrective Action Plan Given	

Includes LOCKED inspections for both archived and unarchived occupancy records.



ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES				
Inspection Typ	nspection Type: OTC									
11136 - 5	Delta Nails #2	2514 E Walnut AVE #Suite 6 Dalton, GA 30721	12/29/2021	Hearn, Scott Raymond	Passed					
	9									

Inspection Typ	Inspection Type: Plan Review								
10432	Christian Heritage High School	1601 MLK Jr. BLVD Dalton, GA 30720	12/06/2021	Blankenship, Donnie	Passed with Comments	Reviewed fire alarm requirements for the baseball facility.			
10084	Lofts over Cherokee Under Construction	207 W Cuyler ST Dalton, GA 30720	12/06/2021	Blankenship, Donnie	Passed with Comments	I reviewed the community cooking facilities, including requirements for the cooking appliances.			
10084	Lofts over Cherokee Under Construction	207 W Cuyler ST Dalton, GA 30720	12/07/2021	Blankenship, Donnie	Passed with Comments	I reviewed fire alarm plans for the entire building.			
10826	Vacant	1520 W Walnut AVE Dalton, GA 30720	12/08/2021	Daniel, Matthew T.	Passed	Walnut Avenue Project. Fire Department Access Issues			
11107	Shaw Plant # 72	900 V.D.Parrott PKY Dalton, GA 30720	12/08/2021	Daniel, Matthew T.	Passed	Sprinkler Plan Review.			
11420	Foggy Mountain Event and Beverage Center	125 Beulah DR Dalton, GA 30721	12/09/2021	Daniel, Matthew T.	Passed	Site plan review.			
10332	Christian Heritage Elementary School	1600 MLK Jr. BLVD Dalton, GA 30720	12/09/2021	Daniel, Matthew T.	Passed	Plan review new baseball training building.			
	Total # Inspections for Plan Review: 7								

Inspection Typ	nspection Type: Reinspection									
11205 - 5	Dollar Gereral Store	101 W Walnut AVE #1 Dalton, GA 30720	12/02/2021	Blankenship, Donnie	Corrective Action Plan Given					
11333 - 2	Regional Medical Group	1503 Professional CT #2 Dalton, GA 30720	12/09/2021	Blankenship, Donnie	Passed	Business appears to have ceased operations, the building was locked and the phone was disconnected. Prior to opening the fire alarm system needs to be operational.				
			Total # Inspec	tions for Reinspection:	2					

Inspection Type: Site Visit								
00001 - 8	Single Family Dwelling	522 Straight ST Dalton, GA 30721	12/01/2021	Daniel, Matthew T.	Failed	The building is not secure. Inspector Blankenship is following up with owner.		
11205 - 9	Delicias Reinita Restaurante y Buffet Mexicano	101 W Walnut AVE #19 Dalton, GA 30720	12/03/2021	Stratton, Dale Lee	Passed with Comments	Issued an occupancy load limit sign for display in the dining area.		



ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
Inspection Typ	e: Site Visit					
11288	Home 2 Suites	865 Holiday Inn DR Dalton, GA 30720	12/03/2021	Blankenship, Donnie	Passed with Comments	Due to multiple alarms to the structure, I met with Mr. Patel the owner and advised him to have the system put on test while workers are present.
11380	John's Bar-B-Q	411 N Glenwood AVE Dalton, GA 30721	12/03/2021	Stratton, Dale Lee	Passed	Issued an occupancy load limit sign for 54 patrons in the dining area.
11079	Budgetel	609 S Thornton AVE Dalton, GA 30720	12/06/2021	Stratton, Dale Lee	Failed	Replace fire alarm system as indicated by the Georgia licensed fire alarm contractor. Contact Inspector Stratton with the replacement plan and schedule no later than 12/13/2021.
10073 - 1	Vape Plug Exotic Snacks & Drinks	617 E Morris ST Dalton, GA 30720	12/06/2021	Hearn, Scott Raymond	Passed with Comments	Add Knox Box to building.
10073 - 2	Danny's Cafe`	617 E Morris ST Dalton, GA 30720	12/07/2021	Hearn, Scott Raymond	Passed	
10406	Core Scientific	201 Boring DR Dalton, GA 30721	12/07/2021	Blankenship, Donnie	Passed	I performed a fire and life safety walk through of the building.
11142	Krystal	1909 E Walnut AVE Dalton, GA 30721	12/07/2021	Stratton, Dale Lee	Passed with Comments	Site visit conducted by Inspectors Blankenship and Stratton, to observe final testing of the hood suppression system and the hood system installation. During testing, an electrical shunt failed to operate. The hood installment contractor stated that he would have the electrician make the appropriate repairs and that the system would be operable by 12/08/2021. The paper work finalizing the installation was not signed.
11288	Home 2 Suites	865 Holiday Inn DR Dalton, GA 30720	12/09/2021	Blankenship, Donnie	Corrective Action Plan Given	
11079	Budgetel	609 S Thornton AVE Dalton, GA 30720	12/09/2021	Stratton, Dale Lee	Passed with Comments	Site visit conducted to meet with sprinkler contractor from ASA. Sprinkler contractor recommended complete replacement of the alarm system and placement of a FACP in the main office. These recommendations were made because the current alarm system is comprised of two separate panels in an antiquated system. Neither panel has a battery backup and the alarm system in the furthest building is inoperable.
00001 - 8	Single Family Dwelling	522 Straight ST Dalton, GA 30721	12/13/2021	Daniel, Matthew T.	Passed	Building secure.
10289	Belk-Gallant Lofts	307 S Hamilton ST Dalton, GA 30721	12/13/2021	Stratton, Dale Lee	Passed with Comments	Assisted DFD preventions division with inspection of alarm system, sprinkler system, emergency lighting systems.

Includes LOCKED inspections for both archived and unarchived occupancy records.



ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
Inspection Typ	e: Site Visit			-		
10289	Belk-Gallant Lofts	307 S Hamilton ST Dalton, GA 30721	12/13/2021	Blankenship, Donnie	Passed with Comments	Assisted DFD Preventions Division with inspection of the fire alarm system, sprinkler system, and emergency lighting system.
11163	Fifth Ave. Apartments	622 Fifth AVE Dalton, GA 30720	12/13/2021	Blankenship, Donnie	Passed with Comments	Spoke with an employee in regards to the fire that happened on a previous date. I advised her that no one could be staying at 710 5th Ave. in apartments 8 and 9 due to the power being disconnected. I also advised her that they would have to pull permits with the building inspectors office prior to the power being reconnected.
10688	Stubbs Prosthetics & Orthotics Inc.	1213 Broadrick DR Dalton, GA 30720	12/13/2021	Blankenship, Donnie	Passed with Comments	Installed the front door key in the Knox Box.
11079	Budgetel	609 S Thornton AVE Dalton, GA 30720	12/13/2021	Stratton, Dale Lee	Passed with Comments	A site visit was conducted via phone with the building owner, Edward Fernandez. The call was conducted to verify that an actionable plan to replace the current alarm system, had been emplaced. Inspector Stratton met with ASA personnel on 12/09/2021 to discuss the replacement of the alarm system. Mr. Fernandez verified that ASA would be replacing the system and would be submitting plans within the next two weeks.
10101	N.P.C. South Plant #1	203 S Easterling ST Dalton, GA 30720	12/14/2021	Hearn, Scott Raymond	Passed	
10675	The Cliffs Apartments	816-826 Shugart RD Dalton, GA 30720	12/14/2021	Blankenship, Donnie	Corrective Action Plan Given	
10344 - 2	Twisted Sisters	906 S Thornton AVE #Suite A Dalton, GA 30720	12/16/2021	Stratton, Dale Lee	Passed with Comments	A medical questionnaire was provided. A copy of the document was attached to this report.
10677	Park Canyon Apartment Homes	284 Park Canyon DR Dalton, GA 30720	12/16/2021	Stratton, Dale Lee	Passed with Comments	Inspectors Stratton and Blankenship met with Park Canyon manager and the sign contractor. The site visit was conducted at the request of the sign contractor to clarify final details on the address sign installation.
11410 - 1	La Esperanza Apartments	1702 E Morris ST Dalton, GA 30720	12/16/2021	Stratton, Dale Lee	Passed with Comments	Site visit conducted by inspectors Blankenship and Stratton, accompanied by Whitfield County Building Inspector Mike Fowler. The visit was conducted to evaluate the installment of secondary means of escape via new window installment.

Includes LOCKED inspections for both archived and unarchived occupancy records.



ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
Inspection Typ	e: Site Visit					
10998 - 2	Signs And Signs	409 North Park DR #Suite B Dalton, GA 30720	12/17/2021	Stratton, Dale Lee	Passed with Comments	Site visit conducted at the request of the business owner. The owner changed the locks and needed to exchange the new keys with the old keys located in the Knox Box.
10658	Taqueria El Rey #2	1215 N Thornton AVE Dalton, GA 30720	12/20/2021	Hearn, Scott Raymond	Passed	
10371	Supreme Restaurant Supply	401 E Morris ST Dalton, GA 30720	12/30/2021	Hearn, Scott Raymond	Passed	
				Total # In:	spections for Site Visit:	25

TOTAL # INSPECTIONS: 74

Includes LOCKED inspections for both archived and unarchived occupancy records.



emergencyreporting.com Doc Id: 1026 Page # 7 of 7

Dalton, GA

This report was generated on 1/3/2022 11:59:32 AM



Occupancy Inspection History per Occupancy with Violations

Inspection Observations: CORRECTIVE ACTION PLAN, FAIL | Occupancy Categories: All Categories | Start Date: 12/01/2021 | End Date: 12/31/2021

INSPECTION DATE	INSPECTION TYPE	RESULT	NOTES	QUESTION	REMARKS	OBSERVATION
Engine 1 B Sh	ift					
Cuyler Triplex	- 402 W Cuyle	r ST				
12/17/2021	New Construction	Corrective Action Plan Given		Have all applicable code requirements been met?	Fire caulk areas as discussed.	CORRECTIVE ACTION PLAN
				Are approved automatic closures code compliant?	Doors opening into a fire rated assembly shall be self closing.	CORRECTIVE ACTION PLAN
				Are normally open valves properly secured?	Secure riser room door with breakaway lock.	CORRECTIVE ACTION PLAN
				Has an annual inspection of the spare sprinkler supply been completed?	Install inspection tag on sprinkler system.	CORRECTIVE ACTION PLAN
12/20/2021	New Construction	Corrective Action Plan Given	Previously discussed issues remain. The owner was advised to contact us once the remaining issues were corrected.	Have all applicable code requirements been met?	Fire caulk areas as discussed.	CORRECTIVE ACTION PLAN
				Are approved automatic closures code compliant?	Doors opening into a fire rated assembly shall be self closing.	CORRECTIVE ACTION PLAN
				Are normally open valves properly secured?	Secure riser room door with breakaway lock.	CORRECTIVE ACTION PLAN
				Has an annual inspection of the spare sprinkler supply been completed?	Install inspection tag on sprinkler system.	CORRECTIVE ACTION PLAN
Shaw Plant # 1	I - 601 1st AVE					
12/09/2021	Annual	Corrective Action Plan Given		Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN



Shaw Plant #	3 - 715 S Glenv	wood AVE							
12/09/2021	Annual	Corrective Action Plan Given		Have all applicable code requirements been met?	Insure all escutcheons are in place.	CORRECTIVE ACTION PLAN			
				Are the means of egress free of obstructions or impediments?	Insure all exits have approved signage.	CORRECTIVE ACTION PLAN			
United Groce	ry Outlet - 912	N Glenwood AV	E						
12/01/2021	Annual	Passed with Comments	Replace ceiling tiles.	Have all applicable code requirements been met?	Replace ceiling tiles.	CORRECTIVE ACTION PLAN			
Engine 1 C Sh	nift								
Danny's Cafe` - 617 E Morris ST									
12/07/2021	ОТС	C Passed		Are there any identifiable electrical hazards?	Add blanks	CORRECTIVE ACTION PLAN			
				Is address signage correct and in place?	Change address to 617 - 2	CORRECTIVE ACTION PLAN			
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN			
Engine 2 A Sh	nift								
Allan's Tires -	1104 S Thornt	ton AVE - 706.31	13.4483						
12/16/2021	ОТС	FC Passed with Comments	A corrective action plan has been provided.	Are there any identifiable electrical hazards?	1) Install a new cover on the electrical panel. 2) Install outlet covers. 3) Extension cords shall not substitute permanent electrical wiring. 4) Maintain 36" clearance in front of and around electrical panels. 5) Electrical wiring must be installed in conduit.	CORRECTIVE ACTION PLAN			
				Are compressed gas cylinders properly secured?	Gas cylinders should be properly secured at all times to prevent tipping, falling or rolling. They can be secured with straps or chains connected to a wall bracket or other fixed surface, or by use of a cylinder stand.	CORRECTIVE ACTION PLAN			
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install and mount a fire extinguisher in the office area. All fire extinguishers must be inspected and tagged by a Georgia licensed contractor.	CORRECTIVE ACTION PLAN			



Budgetel - 60	9 S Thornton A	VE - 706.226112	22			
12/06/2021	Site Visit	Failed	Replace fire alarm system as indicated by the Georgia licensed fire alarm contractor. Contact Inspector Stratton with the replacement plan and schedule no later than 12/13/2021.	Have all applicable code requirements been met?	Replace fire alarm system as indicated by the Georgia licensed fire alarm contractor. Contact Inspector Stratton with the replacement plan and schedule no later than 12/13/2021.	FAIL
12/09/2021	Site Visit	Passed with Comments	Site visit conducted to meet with sprinkler contractor from ASA. Sprinkler contractor recommended complete replacement of the alarm system and placement of a FACP in the main office. These recommendations were made because the current alarm system is comprised of two separate panels in an antiquated system. Neither panel has a battery backup and the alarm system in the furthest building is inoperable.	Have all applicable code requirements been met?	Site visit conducted to meet with sprinkler contractor from ASA. Sprinkler contractor recommended complete replacement of the alarm system and placement of a FACP in the main office. These recommendations were made because the current alarm system is comprised of two separate panels in an antiquated system. Neither panel has a battery backup and the alarm system in the furthest building is inoperable.	CORRECTIVE ACTION PLAN
12/13/2021	Site Visit	Passed with Comments	A site visit was conducted via phone with the building owner, Edward Fernandez. The call was conducted to verify that an actionable plan to replace the current alarm system, had been emplaced. Inspector Stratton met with ASA personnel on 12/09/2021 to discuss the replacement of the alarm system. Mr. Fernandez verified that ASA would be replacing the system and would be submitting plans within the next two weeks.	Have all applicable code requirements been met?	A site visit was conducted via phone with the building owner, Edward Fernandez. The call was conducted to verify that an actionable plan to replace the current alarm system, had been emplaced. Inspector Stratton met with ASA personnel on 12/09/2021 to discuss the replacement of the alarm system. Mr. Fernandez verified that ASA would be replacing the system and would be submitting plans within the next two weeks.	CORRECTIVE ACTION PLAN
Industrial Aut	omation Produ	ucts - 205 E Eme	ery ST - 706-229-3176			
12/01/2021	Annual	Corrective Action Plan Given		Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Have extinguishers inspected by a licensed Georgia contractor.	CORRECTIVE ACTION PLAN



Engine 2 B	Shift					
Advanced A	Adhesive Tech	nology - 421 S S	pencer ST			
12/09/2021	Annual	Corrective Action Plan Given		Is address signage correct and in place?	Add address to building.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
Engine 2 C	Shift					
Felker Cons	struction - 300	Fernwood AVE				
12/10/2021	Annual Passed with Comments		Are exit signs visible?	Install exit signs in the office area. Repair or replace all exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN	
				Are there any identifiable electrical hazards?	Install blanks in open spaces in electrical panels. Junction box covers must be installed on junction boxes containing electrical wire splices. Electrical wiring must be covered with approved materials or installed in conduit.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install address sign on the Fernwood side of the building.	CORRECTIVE ACTION PLAN
				Are proper clearances of combustible materials from ignition sources being maintained?	Remove combustibles from around electrical panels. Maintain 36" of access clearance around electrical panels.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Means of egress must remain free and clear of obstructions.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	1)Install properly mounted fire extinguishers in the office area. The fire extinguishers must be inspected and tagged by a Georgia licensed contractor. 2)Fire extinguishers require a current annual inspection. The inspection must be conducted by a Georgia licensed contractor.	CORRECTIVE ACTION PLAN



		nc 434 Fourth A			B	
2/14/2021	Annual	Corrective Action Plan Given	A corrective action plan has been provided.	Is required emergency lighting in place?	Repair or replace all emergency lighting that does not operate as designed.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Install lighted exit signs in the discussed locations.	FAIL
				Are doors, passages, or stairways that could be mistaken as an exit marked NO EXIT?	Install NO EXIT sign.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	1) Full Hyster tanks must be stored in a rack on the exterior of the structure at least 10' from any exit. 2) Compressed gas bottles must be secured with straps or chains connected to a wall bracket or secured to device designed to secure the bottle.	CORRECTIVE ACTION PLAN
				Is a fire alarm installed where required by the Code?	All smoke alarms must operate as designed. Smoke alarms greater than 10 years old must be replaced.	FAIL
				Are there any identifiable electrical hazards?	install blanks in open spaces in electrical panels. install junction box covers on all junction boxes containing electrical wire splices.	CORRECTIVE ACTION PLAN
			Is address signage correct and in place?	Install address signage.	FAIL	
			Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN	
				Has equipment been maintained in proper working condition?	Install a residential hood vented to the exterior of the structure or remove the residential stove.	FAIL



12/01/2021	Annual	Failed		Is required emergency lighting		CORRECTIVE
12/01/2021	7 1111001	i anou		in place?	Add emergency lighting.	ACTION PLAN
				Are exit signs visible?	Add lighted exit signage.	CORRECTIVE ACTION PLAN
				Are required smoke detectors for elevators installed correctly?	Smoke detectors should be interconnected within the apartment in which they service.	CORRECTIVE ACTION PLAN
				Is the number of means of egress correct?	All bedrooms shall have an approved secondary means of escape.	FAIL
_a Esperanza	Bakery - 1702	E Morris ST - 70	06-270-0178			
12/01/2021	Annual	Corrective Action Plan Given		Have all applicable code requirements been met?	Keep lint cleaned from behind dryer and keep dryer vent from getting kinked so that it works as designed. Install CO detector due to the use of gas fired equipment.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Extension cords should only be used for temporary power. Install electrical room signage on electrical room.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install code compliant address signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
				Has the appropriately scheduled inspection of the entire exhaust system for grease buildup been conducted by a Georgia licensed contractor?	Clean grease filters daily, and have duct cleaned every 3 months.	CORRECTIVE ACTION PLAN
Engine 4 A SI	nift					
Dalton Bearin	g - 601 S Glen	wood AVE - 706	5-278-2804			
12/01/2021	Annual	Corrective Action Plan Given	Add Knox Box to building.	Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN



12/13/2021	Annual	Passed with	A corrective action plan has been	Is required emergency lighting		CORRECTIVE
2/10/2021	, unidai	Comments	provided.	in place?	Install emergency lighting.	ACTION PLAN
			Are exit signs visible?	Install lighted exit signs.	CORRECTIVE ACTION PLAN	
				Have all applicable code requirements been met?	Remove electrical wiring from gas supply lines.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Electrical wiring must be installed in conduit. Wire splices must be installed in a covered junction box.	CORRECTIVE ACTION PLAN
			Are the means of egress free of obstructions or impediments?	Replace hasps with a locking system that does not have the potential to lock occupants inside the structure.	CORRECTIVE ACTION PLAN	
		Does the selection, distribution installation, and maintenance of portable fire extinguishers	Fire extinguishers require a current annual inspection. The inspection must be conducted by a Georgia licensed contractor.	CORRECTIVE ACTION PLAN		
				comply with NFPA 10?	Fire extinguishers must remain accessible and free of obstructions.	
Engine 4 B S	hift					
listika - 100	1 Market ST	#Suite 25				
2/20/2021	отс	Corrective Action Plan Given		Is required emergency lighting in place?	Replace emergency lighting.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace exit signs.	CORRECTIVE ACTION PLAN
			Has a Knox Box containing the property access keys been installed?	Add Knox Box to building	CORRECTIVE ACTION PLAN	
			Are the means of egress free of obstructions or impediments?	Add panic hardware to rear exit. Remove mirror from door.	CORRECTIVE ACTION PLAN	
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Add extinguishers to building.	CORRECTIVE ACTION PLAN



12/20/2021	Alcohol	Corrective Action Plan Given		Is required emergency lighting in place?	Add emergency lighting.	CORRECTIVE ACTION PLAN
				Are exits, other than main exits properly marked?		CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace exit lights.	CORRECTIVE ACTION PLAN
				Are doors, passages, or stairways that could be mistaken as an exit marked NO EXIT?		CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Add panic hardware to rear exit. Remove mirror from exit door.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Add three 3 extinguishers to space.	CORRECTIVE ACTION PLAN
Engine 5 A S	Shift					
AC Delco - 4	15 S Spencer	ST - 7062263126				
12/06/2021	Annual	Corrective Action Plan Given	Add Knox Box to building.	Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
Advanced A	dhesive Tech	nology - 424 S Sp	encer ST - 7062260610			
12/09/2021	Annual	Corrective Action Plan Given		Have all applicable code requirements been met?	Add emergency lighting. Add riser room sign on door.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Add address numbers to building.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN



Blanca's Furn	iture - 406 Fou	urth AVE - 7062	172577			
12/14/2021	Annual	Passed with Comments	A corrective action plan has been provided.	Are there any identifiable electrical hazards?	Install outlet covers and switch plate covers. Install junction box covers.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Sprinkler systems require a current annual inspection. The inspection must be conducted by a Georgia licensed contractor.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Fire extinguishers require a current annual inspection. The inspection must be conducted by a Georgia licensed contractor.	CORRECTIVE ACTION PLAN
Krystal - 1909	E Walnut AVE	- 7066717136				
12/07/2021	Site Visit	Passed with Comments	Site visit conducted by Inspectors Blankenship and Stratton, to observe final testing of the hood suppression system and the hood system installation. During testing, an electrical shunt failed to operate. The hood installment contractor stated that he would have the electrician make the appropriate repairs and that the system would be operable by 12/08/2021. The paper work finalizing the installation was not signed.	Have all applicable code requirements been met?	Site visit conducted by Inspectors Blankenship and Stratton, to observe final testing of the hood suppression system and the hood system installation. During testing, an electrical shunt failed to operate. The hood installment contractor stated that he would have the electrician make the appropriate repairs and that the system would be operable by 12/08/2021. The paper work finalizing the installation was not signed.	CORRECTIVE ACTION PLAN
12/07/2021	Kitchen Hood Installation	Corrective Action Plan Given	Kitchen Hood Inspection was conducted by Inspectors Blankenship and Stratton, to observe final testing of the hood suppression system and the hood system installation. During testing, an electrical shunt failed to operate. The hood installment contractor stated that he would have the	Upon activation of the fire- extinguishing system, do all sources of fuel and electrical power to all heat producing equipment automatically shut off?	During testing, an electrical shunt failed to operate. The hood installment contractor stated that he would have the electrician make the appropriate repairs and that the system would be operable by 12/08/2021.	CORRECTIVE ACTION PLAN
Engine 5 B Sh			electrician make the appropriate repairs and that the system would be operable by 12/08/2021. The paper work finalizing the installation was not signed.			

Engine 5 B Shift



2/02/2021	Complaint	Failed	A corrective action plan has been provided. A re-inspection will be conducted in 30 days.	Is required emergency lighting in place?	Repair or replace all emergency lighting that does not operate as designed.	FAIL
				Are exit signs visible?	Repair or replace all exit signs that do not operate as designed.	FAIL
				Have all applicable code requirements been met?	The corrected occupancy load limit is 50.	CORRECTIVE ACTION PLAN
				If a change of occupancy has occurred, does the building comply with current code requirements?	Business name does not match the name on the Occupational Tax Certificate. City hall must be contacted to correct this discrepancy.	FAIL
				Are there any identifiable electrical hazards?	1) Extension cords shall not be plugged into multi plug adapters. 2) Light fixtures and damaged electrical outlets must be repaired or properly installed by a Georgia licensed electrician. 3) Install outlet covers and switch plate covers on all electrical switches and electrical outlets. 4) Electrical wiring must be installed in conduit and electrical wire splices must be installed in junction boxes.	FAIL
			Are the means of egress free of obstructions or impediments?	All means of egress must remain readily operable and free obstructions. Repair all damaged egress components.	FAIL	
			Are Class K fire extinguishers provided in cooking areas?	Class K fire extinguisher requires a current annual inspection. The inspection must be conducted by a Georgia licensed contractor.	FAIL	
			Has equipment been maintained in proper working condition?	Ensure that the vent fan is in operation when cooking operations are taking place.	CORRECTIVE ACTION PLAN	



Dollar Gerera	al Store - 101 W	/ Walnut AVE #1	- 706-275-9039			
12/02/2021	Reinspection	Corrective Action Plan Given		Have all applicable code requirements been met?	Mark riser room with riser room signage.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Extension cords should only be used for temporary power.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Keep egress paths clear of obstructions.	CORRECTIVE ACTION PLAN
Gordon Brov	wn personal sto	orage - 1212 New	East Morris ST			
12/02/2021	Annual	Passed with Comments	A corrective action plan has been provided.	Are there any identifiable electrical hazards?	Install blanks in open spaces in electrical panels. Extension cords shall not substitute permanent electrical wiring.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install Knox Box.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install fire extinguishers throughout. Extinguishers must be inspected and tagged by a Georgia licensed contractor.	CORRECTIVE ACTION PLAN
Engine 5 C S	Shift					
Frank Crona	n - 1309 E Morr	ris ST #1- 706-50	8-9304			
12/02/2021	Annual	Passed with Comments	A corrective action plan has been provided.	Are exit signs visible?	Repair or replace all exit signs that do not operate as designed	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Install blanks in open spaces in the electrical panel.	CORRECTIVE ACTION PLAN
Providence I	Ministries - 130	9 E Morris ST				
12/10/2021	Annual	Passed with Comments	A corrective action plan has been provided.	Are exit signs visible?	Repair or replace all exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Install blanks in open spaces in the electrical panel.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Fire extinguishers require a current annual inspection. The inspection must be conducted by a Georgia licensed contractor.	CORRECTIVE ACTION PLAN



Providence Mi	inistries - 1309	E Morris ST #4				
12/10/2021	Annual	Passed with Comments	A corrective action plan has been provided.	Are exit signs visible?	Repair or replace all exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN
				Are proper clearances of combustible materials from ignition sources being maintained?	Maintain 36" clearance around electrical panels.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Fire extinguishers require a current annual inspection. The inspection must be conducted by a Georgia licensed contractor.	CORRECTIVE ACTION PLAN
Ladder 3 B Sh	ift					
Allergy & Asth	nma Group of (Galen - 1011 Pro	ofessional BLVD			
12/06/2021	ОТС	Corrective Action Plan Given		Have all applicable code requirements been met?	Have all exit and emergency lights are in working condition.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
Home 2 Suites	s - 865 Holiday	Inn DR				
12/09/2021	Site Visit	Corrective Action Plan Given		Have all applicable code requirements been met?		CORRECTIVE ACTION PLAN
				If a change of occupancy has occurred, does the building comply with current code requirements?		CORRECTIVE ACTION PLAN
The Cliffs Apa	rtments - 816-	826 Shugart RD	- 706-271-7265			
12/14/2021	Site Visit	Corrective Action Plan Given		Have all applicable code requirements been met?	I assisted Building Official Mike Fowler with an inspection of the attic smoke partitions. The smoke partitions didn't meet the requirements of resisting the passage of smoke. The contractor was advised by myself and Mr. Fowler on how to meet the requirements.	CORRECTIVE ACTION PLAN
Ladder 3 C Sh	ift					



12/20/2021	OTC	Corrective Action			E to a la companie de la lacel de lacel de lacel de la lacel de	
12/20/2021	OIC	Plan Given	Are there any identifiable electrical hazards?	Extension cords should only be used for temporary power. Repair electrical wiring. Keep access to electrical panel clear, and remove combustibles near electrical panel.	CORRECTIVE ACTION PLAN	
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
Squad 1 C SI	hift					
JRG Space, l	LLC - 909 Tram	mell ST - 706278	39650			
12/16/2021	ОТС	TC Passed with A corrective action plan has been provided.	Are there any identifiable electrical hazards?	Electrical wiring must be installed in conduit. All electrical wiring no longer in service must be removed. All junction boxes containing electrical wiring must be covered with the appropriate junction box cover.	CORRECTIVE ACTION PLAN	
				Has a Knox Box containing the property access keys been installed?	Contact this office when the Knox Box has been installed. Have a set of keys that access the building prepared for placement. Have thumb drive containing MSDS documentation prepared for placement in the Knox Box.	CORRECTIVE ACTION PLAN
				Are LP-gas containers located in code compliant locations?	Full LP tanks must be stored in a storage rack outside of the structure and a minimum of 10' from building entrances.	CORRECTIVE ACTION PLAN

