

## PREVENTION DIVISION

September, 2018

### **C/O INSPECTIONS EXISTING BUILDINGS: TOTAL OF 14**

- 1205 E. Morris St. – La Esquinita: Deficiencies found during inspection include: address needs to be posted, Knox Box needs to be installed, and add emergency lighting.
- 1008 Professional Blvd. Suite 4B – Northwest Georgia Home Health LLC: Deficiencies found during inspection include: Knox Box needs to be installed on building, and emergency lights not working.
- 825 Chattanooga Ave. – Southern Reflexion LLC: No deficiencies found during inspection.
- 816 Walnut Square Blvd. – T-Mobile: Deficiencies found during inspection include: exit blocked, combustibles stored near electrical panel, and fire extinguisher needed.
- 1247 Broadrick Dr. – Hamilton Medical Center Parking Deck: Deficiencies found during inspection include: Knox Box needs to be installed, Fire alarm annunciator needs to be installed on Division 1, stairwell door needs panic bar, address needs to be posted, and exit signage needs directional arrows to point towards emergency exits.
- 240 N. Hamilton St. – Café Ostro: No deficiencies found during inspection.
- 300 Smith Industrial Blvd. – Dunkin Donuts: No deficiencies found during inspection.
- 310 N. Selvidge St. – Paula Plott Gregg Art Studio: Deficiencies found during inspection include: Exposed electrical wiring, extension cords used as permanent power, address needs to be posted, and fire extinguishers need current inspection tag.
- 913 N. Glenwood Ave. – North and South Towing: Deficiencies found during inspection include: fire extinguishers need serviced, and address needs to be posted.
- 825 Chattanooga Ave. Suite 12 – Southern Reflexion LLC.: Deficiencies found during basic inspection include: Sprinkler heads need to be moved due to being obstructed.

- 1247 Broadrick Dr. – Hamilton Medical Center Parking Deck: Deficiencies found during inspection include: Knox Box needed, fire alarm annunciator panel needs to be added, breaker locks needed on fire alarm, and emergency lights breakers, panic hardware needs to be install on stairwell exits, address signage needed, and exit signs should direct to nearest exit.
- 1205 E. Morris St. – La Esquinita: Deficiencies found during inspection include: Address needs to be posted, Knox Box needed, and emergency lights needed.
- 1008 Professional Blvd. – Northwest Georgia Home Health LLC: Deficiencies found during inspection include: Knox Box needed, and emergency light in stairwell needs to be repaired.
- 816 Walnut Square Blvd. – T-Mobile: No deficiencies found during inspection.

### **BASIC INSPECTIONS TOTAL OF 21**

- 2222 Hamilton St. Ext. – Signature Carpets: Deficiencies found during basic inspection include: Repair or replace exit signs and emergency lighting, escutcheon plates missing, need hydrants serviced and flowed, sprinkler head wrench missing and add address numbers to building.
- 2224 Hamilton St. Ext. – Integrated Tufting Center: Deficiencies found during basic inspection include: Exits blocked or not visible, exit pathways not proper size, no sprinkler wrench in box, need hydrant serviced and flowed, cannot see exit signs, exit lights and emergency lights need repaired or replaced, propane tanks need to be secured and maintain clearance around electrical panels.
- 316 Northgate Dr. – Lifetime Muffler & Brake: No deficiencies found during basic inspection. Need to add a Knox Box.
- 324 Northgate Dr. – One Main Financial: One deficiency found during basic inspection: Have extinguishers serviced. Need to add a Knox Box.
- 362 Northgate Dr. – First National Community Bank: No deficiencies found during basic inspection. Need to add a Knox Box.
- 1300 Veterans Dr. – Shiroki: No deficiencies found during basic inspection. Need to add a Knox Box.

- 1205 Royal Dr. – Green Vulture LLC: Deficiencies found during basic inspection include: Repair or replace exit and emergency lights, ensure all junction boxes are covered, have private hydrants flow tested. Need to add a Knox Box.
- 311 Smith Industrial Blvd. – Tandus: No deficiencies found during basic inspection. Need to add a Knox Box.
- 1406 Coronet Dr. – Avanti Environmental Group: Deficiencies found during basic inspection include: Have sprinkler heads cleaned, add numbers to front of building, put cover on electrical panel, add exit sign to rear of building, raise exit signs, keep areas around machines clean and ensure all extinguishers are mounted.
- 2738 Underwood Rd. – Cross Plains Community Center: Deficiencies found during basic inspection: Replace fire door at top of stairs. Add a Knox Box.
- 1060 Vista Dr. – All Seasons Self Storage: Deficiencies found during basic inspection include: Repair or replace exit signs and emergency lighting, have extinguishers serviced, mark riser room and add a Knox Box.
- 908 Elk St. – Servicios Latinos: Deficiencies found during basic inspection include: Sprinkler heads coated with overspray, extension cords used as permanent power, Knox Box needed, not enough exits, stairs didn't meet code, sprinkler system needs inspection, riser room should be marked, multiple areas throughout not sprinkled, FDC signage needed, sprinkler control valves not marked, fire alarm devices need to be added, fire alarm need serviced, fire alarm system in trouble mode, exit doors swing the wrong way, address not posted, exposed electrical wiring, exit signage needed, emergency lights needed, fire extinguishers need to be tagged, and additional fire extinguishers needed.
- 4410 Mitchell Bridge Rd. – Dalton Utilities: No deficiencies found during inspection.
- 403 Flemming St. – Dalton Golf and Country Club: Deficiencies found during basic inspection include: Sprinkler heads needed in freezers, cooking equipment and space around it should be cleaned on a regular basis, cooking equipment outside of hood, extension cords used as permanent power, exit path blocked, high piled storage, riser room needs to be marked, FDC sign needed, sprinkler control valves need to be chained or supervised, fire alarm inspection needed, smoke detector required above fire alarm panel, and 3ft clearance needed around electrical panel.

- 1310 C&L Dr. – Warehouse One: Deficiencies found during basic inspection include: Carpet racks damaged and need to be repaired due to risk of collapse, extension cords used as permanent power, Knox Box needed, means of egress blocked, riser unprotected, storage exceeds 18" clearance to sprinkler heads, no sprinkler wrench in box, riser is blocked, and panic hardware required on exits.
- 801 Legion Dr. – Duvall Chemical: Deficiencies found during basic inspection include: Knox Box needed.
- 813 Legion Dr. – Accurate Mechanical: Deficiencies found during basic inspection include: Compressed gas cylinders should be secured, extension cords used as permanent power, Knox Box needed, exit doors should be unlocked during business hours, address needed, flammable liquids should be stored in an approved manor, remove combustibles near electrical panel, exposed wiring should be in conduit, emergency lights and exit signs need to be repaired or replaced.
- 815 Legion Dr. – Ace Transportation: Deficiencies found during basic inspection include: Secure compressed gas cylinders, extension cords used as permanent power, Knox Box needed, open spaces in electrical panel, exposed electrical wiring, exit signage and emergency lights needed, fire extinguishers need serviced, and remove items on fire extinguishers.
- 1018 Vista Dr. – Vacant – Inspection cleared due to building being vacant.
- 1301 C & L Dr. – U.S. Floors: Deficiencies found during basic inspection include: Knox Box needed, means of egress blocked, no replacement heads ins sprinkler box, sprinkler head wrench needed, FDC Sign needed, sprinkler control valves need to be locked or supervised, hydrant inspection needed, fire alarm needs inspection, smoke detector above fire alarm needs to be repositioned, additional exit signage needed, panic hardware needed on exit doors, additional fire extinguishers needed, and fire extinguisher placement should be marked so to be visible throughout building.
- 412 School St. – M & M Building: Deficiencies found during basic inspection include: Knox Box needed, means of egress blocked, fire alarm needs to be inspected/updated, address signage needed, flammable liquids should be stored in an approved manner, exposed electrical wiring, exit signage and emergency lighting needs to be repaired, and fire extinguishers need serviced.

## **RESTURANTS/BARS: TOTAL OF 1**

- 501 Legion Dr. – Western Sizzlin: Deficiencies found during basic inspection include: Sprinkler head needed in electrical room, cooking equipment needs to be serviced, cooking equipment and are around equipment need to be cleaned on a regular basis, cooking equipment outside hood, extension cords used as permanent power, Knox Box needed, kitchen hood filters need to be cleaned, high piled storage, FDC signage needed, fire alarm inspection due, smoke detector needed at alarm panel, and electrical panel needs 3ft clearance to combustibles.

## **SITE VISITS: TOTAL OF 41**

- 240 N. Hamilton – Café Ostra: Site visit. Discussed hood duct work.
- 304 Tuftco Dr. – Tuftco: Burn permit issued.
- 500 E. Walnut Ave – Ken White: Added keys to Knox Box.
- 330 Brickyard Rd. – Shaw: Added key to Knox Box.
- 2207 S. Hamilton Ext. – Shaw: Added key to Knox Box.
- 2208 S. Hamilton Ext. – Shaw: Added key to Knox Box.
- 825 Chattanooga Ave. – The Mill: Added keys to Knox Box.
- 501 Central Ave. – Brookwood Elementary School: Inspected rooms 244, 242, 247, and 245 for remodel work.
- 411 N. Thornton Ave. - Roxbury Luxury Condos: Post fire investigation with private investigator.
- 300 Smith Industrial Blvd. – Dunkin Donuts: 80% inspection.
- 300 Smith Industrial Blvd. – Dunkin Donuts: 100% inspection.
- 1020 Riverbed Dr. – Shaw Plant 20: New sprinkler pipe inspection.
- 240 N. Hamilton St. – Café Ostro: Hood inspection (complete).
- 1406 Coronet Dr. – Avanti Environmental Group: Site visit.
- 1525 E. Morris St. – Dago's Place: Initial hood inspection.
- 801 E. Walnut Ave. Ste. A – Dalton RV: Knox box installed, put key in box. (2)

- 801 E. Walnut Ave. Ste. C – Vallarta: Knox box installed, put key in box. (2)
- 801 E. Walnut Ave. Ste. L – Veritas: Knox box installed, put key in box. (2)
- 801 E. Walnut Ave. Ste. N – Select Staffing: Knox box installed, put key in box. (2)
- 201 W. Waugh St. – BB&T: Site visit, updated contact information.
- 801 E. Walnut Ave. Suite O – Executive Management: Knox box installed, put key in box. (2)
- 801 E. Walnut Ave. Suite J – Fortune Cookie: Knox box installed, put key in box. (2)
- 801 E. Walnut Ave. Suite H – Groomingtails: Knox box installed, put key in box. (2)
- 801 E. Walnut Ave. Suite F – Cosmo Prof: Knox box installed, put key in box. (2)
- 801 E. Walnut Ave. – Carneceria Loa #3: Re-inspection and added key to Knox Box.
- 825 Chattanooga Ave. – Native: Light test on hood system duct work.
- 543 Callahan Rd. – ProFab: Placed key in Knox Box. (2)
- 500 Commerce St. – Gateway Apartments: Roof leaking.
- 913 N. Glenwood Ave. – North and South Towing: Follow up inspection.
- 825 Chattanooga Ave. Suite 12 – Southern Reflexion LLC: Follow up inspection.
- 825 Chattanooga Ave. – The Mill: Automatic alarm.
- 1247 Broadrick Dr. – Hamilton Medical Center Parking Deck: Follow up inspection.
- 1201 Burleyson Rd. – Anna Shaw Children’s Institute: Site visit.
- 1020 Riverbend Rd. – Shaw Plant 20: Sprinkler pipe inspection.
- 411 N. Thornton – Roxbury Apartments: Fire investigation.
- 300 Smith Industrial Blvd. – Dunkin Donuts: 80% inspection.
- 2116 S. Hamilton St. – Mayberry Carpet and Rug: Automatic alarm.
- 300 Smith Industrial Blvd. – Dunkin Donuts: 50% inspection.
- 501 Central Ave. Brookwood Elementary: Remodel inspection.
- 825 Chattanooga Ave. – The Mill: Knox Box installation.
- 310 Brookhollow Industrial Blvd. – Plaze Georgia: Fire hydrant leaking.

## **PUBLIC RELATIONS: TOTAL OF 14**

- Fire Safety Education – 14 events, 77 staff members, 153 staff hours, 1226 adults and 938 children reached, total of 2164 residents received Fire Safety Education.