



- Visually inspect the cylinder for proper hydrostatic test information and visual inspection permit (VIP) sticker
  - SCUBA cylinders must be hydrostatically tested every five (5) years by a D.O.T. certified testing facility
  - SCUBA cylinders must have a visual inspection test every year by an authorized diving facility and must have a current visual inspection sticker
  - Cylinders must have a D.O.T. hydrostatic test stamp, example: B7  
10 21 91
  - No other testing will be accepted.
  
- Visually inspect the cylinder for deep nicks, cuts, or damage to the cylinder valve
  
- Should the cylinder fail any of the above inspections or found to be out of test date, the cylinder will not be refilled. Refusal to refill for any reason is at the discretion of the personnel performing the refill.