



GRIMM'S PUMP AND INDUSTRIAL SUPPLY

1002 E. OMAHA ST
PO BOX 3028
RAPID CITY, SD 57709-3028
605-343-3629

Invoice

Date	Invoice #
9/17/2024	59415

Bill To
CITY OF DEADWOOD 108 SHERMAN DEADWOOD, SD 57732

Ship To
CITY OF DEADWOOD 105 SHERMAN DEADWOOD, SD 57732

P.O. Number	SO / WO #	Rep	Terms
RANDY	90522	DK	Net 30

Description	Quantity	Price Each	Amount
EQUIPMENT - PENTAIR AP AURORA PUMP	1	0.00	0.00T
M/N - A810-13800	1	0.00	0.00T
S/N - 341-FF	1	0.00	0.00T
WORK REQUESTED - REPLACE SEAL KIT PER RANDY 578-2082	1	0.00	0.00T
AURORA SEAL KIT 0250	1	549.45	549.45T
SHIPPING & HANDLING	1	16.82	16.82T
AURORA PUMP BRACKET	1	745.50	745.50T
SHIPPING & HANDLING	1	20.87	20.87T
SERVICE T	1	59.62	59.62T
INDUSTRIAL LABOR	16	100.00	1,600.00T
SHOP FEE	1	15.50	15.50T
INDUSTRIAL MILEAGE	232	3.75	870.00T
WORK PERFORMED: 9/5/24 PULLED PUMP APART, IMPELLOR AND INSIDE PUMP CASE ARE COATED WITH EPOXY. PULLED SEAL FROM PUMP CASE, IT IS BAD, NEW SEAL WON'T FIX, CUSTOMER WANTS A PRICE ON PARTS AND PRICE ON THE WHOLE PUMP. SAID THEY WOULD KEEP AN EYE ON THE WATER IN THE MOTOR PIT. 9/6/24 INSTALLED PLATE OVER PUMP VOLUTE IN CASE WATER DOESN'T TURN OFF ALL THE WAY. 9/13/24 REMOVED DATA TAG FROM OLD CASE AND INSTALLED NEW CASE, CLEANED UP PARTS. 9/16/24 INSTALLED PARTS ON MOTOR, CUSTOMER HAD REMOVED MOTOR, I PUT BACK. PUT NEW SEAL AND SLEEVE IN PUMP, PUT BACK TOGETHER. COULDN'T TEST, THEY HAD A PART FOR THE BASKET SCREEN THAT HADN'T BEEN ORDERED YET. THEY SAID THEY WILL RUN WHEN THEY GET THE PART. TOLD THEM TO MAKE SURE ROTATION IS CORRECT.	1	0.00	0.00T

Subtotal \$3,877.76

EXCISE (2.041%) \$79.15

Total \$3,956.91

- *No returns or refunds on special orders.
- *No return after 30 days or without receipt.
- *NET 30 invoices, if paying by credit card will incur a 3% fee if paid more than 10 day after invoice date.
- *Service charge of 2% per month 24% ann will be charged on past due.