

			Benson Landscaping & Lawn Maintenance, LLC	King Tree Experts, Inc	Pro Tree Inc.
Line Item	Description	Unit of Measure	Unit Cost	Unit Cost	Unit Cost
1	Berm to the new designated area, per the SOW and pictures provided.	Lump Sum	\$56,000.00	\$65,000.00	\$80,000.00
2	Removal of existing chain link fence and trees located in the relocation areas for the Dirt Berm, per the SOW and pictures provided.	Lump Sum	\$23,800.00	\$19,500.00	\$27,000.00
3	Removal of existing interior chain link fence located in the parking area for the installation of a L-shaped barrier wall, per SOW and	Lump Sum	\$9,550.00	\$7,300.00	\$10,500.00
4	Installation of a L-shaped Barrier Wall, per SOW and pictures provided.	Lump Sum	\$24,880.00	No Bid	No Bid
<b>Total Items 1 and 2</b>			<b>\$79,800.00</b>	\$91,800.00	\$117,500.00
<b>Total All Items</b>			<b>\$114,230.00</b>		