

Book Return front door rusted completely from hinges





Book Return side door badly warped



Cigarette receptacle fire damage



Cigarette receptacle bucket bottom completely rusted out and missing