

Building Maintenance

Building maintenance performed routine maintenance on north side window 2.2 on courthouse. The window seal base was repaired with (1) 2x6 and (1) 1x6. The window was caulked and resealed. Paint was matched exactly with no change in appearance.