

Cyncon Equipment, LLC

7494 West Henrietta Road

P.O. BOX 30

Rush, NY 14543

Estimate

10656

Bill To: 3545

Town of Halfmoon

2 Halfmoon Town Plaza

Halfmoon, NY 12065

Ship To: 3545

Town of Halfmoon Highway Dept.

322 Route 46

Halfmoon, NY 12065

Date	Ship Via			F.O.B.	Terms		
09/04/2026	Customer Pick Up				Net 30		
Purchase Order Number			Required Date	Sales Person		Description	
			09/04/2026	Emma Miles		S23038	
Quantity			Item Number	Description	Unit Price	Amount	
Required	Shipped	B.O.					

Repairs to Envirosight RCX90 Camera head SN:5613229.

Camera Complaint: Camera head loses air quickly.

Tech Diagnosis: Found air to be leaking from all around the glass and around the edges of the casing. Unfortunately we cant get the lens cover parts for this current round window lens as it has been discontinued, and upgraded to a newer model. The software version of this camera is out of date and will need an update. All other camera components will need to be brought to Cyncon for a software update in order to be compatible with the camera head.

***Estimate includes the cost of the software updates to the following peices, to be brought to Cyncon.

Elevator, Cable Reel, Controller and Crawler

1	E-561-3120-02-AO	FRONT COVER ASSY	3623.03	3623.03
10.000	LABOR - TECH JR	LABOR PER HOUR - TECH JR	170.00	1700.00

Please note that we try to issue an accurate quote based on diagnosis of visible repairs needed and equipment tests. Unfortunately, sometimes upon our final check after performing work quoted, other issues may manifest themselves. In those cases, you may notice a difference in the final invoice if the amount is minimal or we will issue a final quote for larger amounts.

Order Subtotal	5323.03
Misc Hardware/Materials	159.69
Order Total	5482.72

Thank You