



10405 Merrill Road ♦ P.O. Box 157  
Hamburg, MI 48139  
Phone: 810.231.1000 ♦ Fax: 810.231.4295  
[www.hamburg.mi.us](http://www.hamburg.mi.us)

---

## EXCERPT FROM HAMBURG TOWNSHIP MUNICIPAL UTILITIES COMMITTEE MEETING MINUTES

To the attention of: Jason B. Negri, Supervisor  
Hamburg Township Board of Trustees

Re: **DPW Monthly Report – November 2025 Statistics**

Please be apprised of this excerpt from the Unapproved Approved Minutes of the Meeting of the Hamburg Township Sewer Committee:

Date of Meeting: December 9<sup>th</sup>, 2025

Sewer Committee Members Present: Negri, Menzies, Daniels

Sewer Committee Members Absent: None

Text of Motion: MOTION BY NEGRI, SECONDED BY MENZIES TO NOTE THE DPW MONTHLY REPORT AS RECEIVED AND TO BE FILED AND TO ALSO FORWARD A COPY TO THE TOWNSHIP BOARD AS AN AGENDA ITEM FOR THEIR REVIEW.

Ayes: Negri, Menzies, Daniels Absent: None Nays: None

MOTION CARRIED.

State of Michigan }  
County of Livingston }  
Township of Hamburg}

I, BRITTANY K. CAMPBELL, Hamburg Township Utilities Coordinator and recording secretary to the Municipal Utilities Committee, do hereby certify that the foregoing is a true and correct excerpt of the Minutes of the aforementioned Regular/Special Meeting of the Hamburg Township Municipal Utilities Committee.

Brittany K. Campbell Date: December 9<sup>th</sup>, 2025  
BRITTANY K. CAMPBELL  
HAMBURG TOWNSHIP UTILITIES COORDINATOR



10405 Merrill Road ♦ P.O. Box 157  
Hamburg, MI 48139  
Phone: 810.231.1000 ♦ Fax: 810.231.4295  
[www.hamburg.mi.us](http://www.hamburg.mi.us)

To: Municipal Utilities Committee  
From: Tony Randazzo  
Date: 12-04-2025  
Re: DPW Monthly Report

---

1. The daily testing at the wastewater treatment plant was in compliance for the month of November.
2. Pipe replacement was completed at Hamburg Pump Station. This had to be done due to the corrosion caused by hydrogen sulfide which made holes appear in the pipe. The job ended up being more involved than originally planned due to a valve failure and additional pipe replacement because of the extensive corrosion.
3. We received the PFAS results for twenty more wells in the Buck Lake area. There was one exceedance for PFOA, and eight other wells showed low levels of different PFAS analytes. Eleven wells were non detect for all twenty-five analytes.



## **Hamburg Township Monthly Field Report**

**November 2025**

**Ryan Ward**

**Grinder Calls: 52 Total / 47 OT**

**Plant Calls: 0 OT**

**Station Calls: 1 Hamburg/ 1 Portage**

**Pump Rebuilds: 38 Hamburg / 0 Portage / 0 Highland / 8 Scrapped**

**Miss Digs: 153 Hamburg / 28 Portage**

**Startups: 1**

**Deactivations/Reactivations: 0**

**Replacements: 0**

**Grinder Stations in Stock: 16 simplex / 2 duplex**

**Grinder Locations: 1**

**Grinder Pump Cores in Stock: 22 + 2 for Duplex**

**WWTP Average Influent Flow: 280826 Gallons**

**Field Jobs for the Month:** This month we have completed our normal monthly checks along with monitoring well sampling. Hamburg station has had multiple issues with one of the bypass valves not working. The inlet pipe from Winans station was so deteriorated it

could not support a plug to block flow and the discharge piping/ guide rails for the pump were so bad it was turned into an emergency job to replace all piping by Midwest Power Systems. Comprehensive Contracting replaced the bypass valve and Winans station inlet pipe. A new influent flow meter was installed in the Hamburg plant by Kerr Pump.

