Homer Public Safety Building

Grubstake Avenue Homer, Alaska 99603

Date Fri 12/13/2019

Prepared By Carl Brinkerhoff

CORNERSTONE GENERAL CONTRACTORS





Work Logs						
Name	Description	Quantity	Hours	Hours To Date		
Accel Fire		0	0	14		
Alasco Insulation		0	0	11		
Consolidated Roofing		0	0	477		
Duct or Sheet Metal	Onsite laying out duct work. More changes in framing to accommodate. Coordinated RTU-1 hoisting. Carl Brinkerhoff 12/14/19 09:55AM	2	4	36		
East Road Services		0	0	944		
Eayrs Plumbing	Onsite working at upper level domestic water. Showers are not in town and it's doubtful they will be here prior to new year without air freight. This will prohibit. Last exterior door frame to be installed at lower level and will delay Sheetrock at walls in locker room. Carl Brinkerhoff 12/14/19 09:59AM	2	6	580		
Matt Hanson, Ron Frazier, Tanner Stengel, Chad Albertsons, Ryan Fox, Jim Pollack, Tod Shar	Supervision, coordination and documentation. Began installing exterior door frames at lower level. Continued interior blocking. Completed grinding fins at lower level exposed concrete walls. Marked all framed walls for type of insulation and Sheetrock. Carl Brinkerhoff 12/14/19 10:03AM	6	0	0		
Puffin Electric	2 journeyman and an apprentice onsite continuing com. Electrical and data rough in at upper level and lower level exterior door frames Carl Brinkerhoff 12/14/19 10:05AM	3	8	1025.5		
Total		13	44	11190		



2 of 4 | Homer Public Safety Building

Materials

Time Cards

General Notes

1. Crane moved up to next Wednesday 12/18/19. Solo tube arrived onsite at end of shift today. Carl Brinkerhoff | 12/14/19 | 10:12AM

Site Safety Observations

Quality Control Observations

1. Site safety protocols were observed onsite today. Carl Brinkerhoff | 12/14/19 | 10:12AN

Powered by


	Survey	
Questions	N/A No Ye	s Description
1. Any accidents on site today?		
2. Any schedule delays occur?		Showers for lower level locker rooms not ordered by mechanical sub in time to be onsite prior to framing and now are preventing exterior door frame completion and sheet rock installation Carl Brinkerhoff 12/14/19 10:10AM
3. Did weather cause any delays?		
4. Any visitors on site?		Jacko the crane opperator was onsite today. Went with him to Eyres storage to determine rigging needs. Carl Brinkerhoff 12/14/19 10:18AM
5. Any areas that can't be worked on?		Showers at locker room not onsite. Exterior doors and hard ware not on site. Neither type of siding on site. Bat type insulation not onsite. Carl Brinkerhoff 12/14/19 10:18AM
6. Any equipment rented on site?		All terrain scissor lift. Carl Brinkerhoff 12/14/19 10:18AM

Attachments

No entry

No entry

No entry



[ml Bh

I, Carl Brinkerhoff, have reviewed and completed this report.

Carl Brinkerhoff | 12/14/19 | 10:18AM



Homer Public Safety Building: Grubstake Avenue Homer, Alaska 99603

Name	Description	Quantity	Hours	Hours To Date
1. Puffin Electric	No Entry	0	0.0	0.0
2. Eayrs Plumbing and Mechanical	No Entry	0	0.0	0.0
3 . PEI	No Entry	0	0.0	136.0
Subtotal		0	0	136.0
Grand Total (Includes Cornerstone General Contractors Work Log Total)		13	44	11326.0