

VEHICLE/EQUIPMENT EVALUATION FORM

Date of Evaluation: 6/6/2024

Vehicle Number: 400B 2
Year: 1997
Make: Thompson
Model: 6" Tow Behind pump
Usage Type: Public Works

Life-to-date usage Hours: 3,851
Years in service: 27 years
Year scheduled for replacement:

Drivetrain Condition:

Engine	Average for miles/hours:	<input checked="" type="checkbox"/>	Needs work:	<input type="checkbox"/>
Transmission	Average for miles/hours:	<input type="checkbox"/>	Needs work:	<input type="checkbox"/>
Differential	Average for miles/hours:	<input type="checkbox"/>	Needs work:	<input type="checkbox"/>

Body Condition:

Undercarriage	Average for mileage/year:	<input type="checkbox"/>	Fair:	<input type="checkbox"/>	Poor:	<input type="checkbox"/>
Sheet Metal	Average for mileage/year:	<input type="checkbox"/>	Fair:	<input type="checkbox"/>	Poor:	<input type="checkbox"/>
Interior	Average for mileage/year:	<input type="checkbox"/>	Fair:	<input type="checkbox"/>	Poor:	<input type="checkbox"/>

Alternatives:

Retain

- keep as is/evaluate annually
- partially rebuild
- completely rebuild
- modify w/attachments and options
- shift to lighter duty application

Dispose

- Trade-in
- Sell by Village or auction
 - As is/no sale prep costs
 - Incur minimum sale prep. Costs
 - Disassemble/sell components

Replacement

- replace w/updated similar vehicle/equipment
 - replace w/rented vehicle equipment as needed
 - replace w/multi-functional vehicle/equipment
 - replace with Fleet recycled vehicle
-

Notes:

This pump has had a Volute and Impeller failure with no replacement parts available and would require complete pump replacement

Joe Mancini
Vehicle Maintenance Supervisor

