## **PURCHASE ORDER**

# **Huerfano County**

Purchase Order#:

110

Purchase OrderDate:

6/8/2023

Vendor: EATON SALES & SERVICE LLC-007 / 5629

**610 EAST BROOKSIDE** 

COLORADO SPRINGS, CO 80905

Ship To: 401 Main Street -

Walsenburg CO, 81089

### Order Description:

DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL COST	LEDGER
Fuel Pumps	1	\$2,272.00	\$2,272.00	002-43040-51507
-		TOTAL:	\$2,272.00	

Repair to Fule Pumps at Road and Bridge

#### **APPROVALS:**

Approving Authority:

Budget Officer:

Since 1919.



100 Years of Service

EATON SALES & SERVICE LLC

610 E. BROOKSIDE

COLORADO SPRINGS, CO 80905

719-475-9440

**INVOICE NUMBER:** 0143797-IN **INVOICE DATE:** 5/30/2023

**ORDER NUMBER:** 0210725

**ORDER DATE:** 4/11/2023

PAGE: 1

SERVICE NO: 0

CUSTOMER NO: 7207120

SOLD TO:

HUERFANO COUNTY 401 MAIN ST

WALSENBURG, CO 81089

CONFIRM TO

HUERFANO COUNTY

SHIP TO:

HUERFANO COUNTY ROAD BRIDGE

1010 S MAIN STREET

WALSENBURG, CO 81089

CUSTOMER P.O. DUSTIN HRIBAR SHIP VIA DELIVER

F.O.B.

TERMS

Net 30

ITEM NO. UNIT ORDERED SHIPPED BACK ORD PRICE **AMOUNT** /BE SAFE-INS EACH 1.00 1.00 0.00 0.00 0.00

Pre-work Safety Checklist

RP: Petrovend controller offline.

4-11-23: Arrived on site and spoke to IT guys. Upon arrival the system was up and someone was getting fuel. While on site we seen the system go down showing loading on FIT. I contacted OPW and spoke to Emanuel case 35572. They dialed in and see the times when FIT was offline. It appears the wireless Petro net modems are rebooting or loosing communication. I tried connecting to the FIT sidebone with no success. Need to follow up with OPW tomorrow on issue.

5-18-23: Arrived on site and met with IT guys. The system happened to be up upon arrival. I installed the new modems and performed a signal test at -53 to -81db. We messed with the antennas and could not get any improvement but there are no packet losses. Site will keep us posted if they have any more issues.

/LABS	HOUR	8.00	8.00	0.00	120.00	960.00
LABOR-SERVICE						
/LABOR TRAV	EACH	8.00	8.00	0.00	120.00	960.00
TRAVEL TIME TO & FROM	JOB					

CONTINUED

Since 1919



100 Years of Service

EATON SALES & SERVICE LLC

610 E. BROOKSIDE

COLORADO SPRINGS, CO 80905

719-475-9440

INVOICE NUMBER: 0143797-IN

**INVOICE DATE:** 5/30/2023

PAGE: 2

**ORDER NUMBER:** 0210725

**ORDER DATE:** 4/11/2023

SERVICE NO: 0

**CUSTOMER NO:** 7207120

SOLD TO:

HUERFANO COUNTY 401 MAIN ST

WALSENBURG, CO 81089

CONFIRM TO

HUERFANO COUNTY

SHIP TO:

HUERFANO COUNTY ROAD BRIDGE

1010 S MAIN STREET

WALSENBURG, CO 81089

CUSTOMER P.O. DUSTIN HRIBAR SHIP VIA DELIVER F.O.B.

TERMS

Net 30

ITEM NO.	UNIT	ORDERED	SHIPPED	BACK ORD	PRICE	AMOUNT
/MILS MILEAGE	EACH	180.00	180.00	0.00	1.70	306.00
/FUELSC FUEL SURCHARGE	EACH	1.00	1.00	0.00	36.00	36.00
/EPA ENVIRONMENTAL CHARGE	EACH	1.00	1.00	0.00	10.00	10.00

002.43040,51507 Repair to pumps at Read & Bridge

PLEASE REMIT TO: EATON SALES & SERVICE LLC PO BOX 16405 DENVER, CO 80216-0405

A SERVICE CHARGE OF 2% PER MONTH (24% ANNUAL PERCENTAGE RATE) BUT IN NO EVENT HIGHER THAN THE HIGHEST LAWFUL RATE WILL BE ASSESSED ON ALL PAST DUE ACCOUNTS, MINUMUM CHARGE OF  $50\epsilon_{\rm s}$ 

 NET INVOICE:
 2.272.00

 LESS DISCOUNT:
 0.00

 SALES TAX:
 0.00

 INVOICE TOTAL:
 2,272.00

To cover the cost of processing a credit or charge card transaction, and pursuant to Section 5-2-212, Colorado Revised Statutes, a seller or lessor may impose a processing surcharge in an amount not to exceed 2% of the total payment made for goods or services purchased or leased by use of a credit or charge card, A seller or lessor shall not impose a processing surcharge on payments made by use of cash, a check, or a debit card or redemption of a gift card.

Beginning July 1, 2022 if this invoice is paid by credit card, a surcharge of \$45.44 will be added for a total charge o \$2,317.44.

Pay on our website - www.eatonsalesservice.com

Direct Link Payment Option - https://securepayment.link/eatonsalesservice/