



Governor Kim Reynolds
Lt. Governor Adam Gregg
Adam Steen, Director

Date: March 3, 2021

To: Tammy Hollingsworth, Auditor of State
Victoria Newton, Treasurer of State
Executive Council

From: Mariah Flowers, Fleet Manager
DAS Fleet Services
Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	# 1209/Deer
Event Date	December 19, 2021
Summary	Vehicle #1209 struck a deer. (231183)
Amount Requested	\$3,393.80 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager
DAS Fleet Services
Mariah.Flowers@iowa.gov
515-414-6582



Risk, DAS <das.risk@iowa.gov>

29C20 - #1209

1 message

Risk, DAS <das.risk@iowa.gov>

Mon, Dec 20, 2021 at 10:06 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil
<executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle struck a deer on 12/19/21. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

**DAS Fleet Services, Risk**

Iowa Department of Administrative Services
Division of Business and Property Services
Office: 515-725-2243
Das.Risk@iowa.gov
<https://das.iowa.gov>

3200

1600

Vehicle Accident Report

Time and location of accident

Accident Date (Mo/Day/Year)	Time	No. of Vehicles
12-19-2021	5:35 pm	1
County	State	
Taylor	IA	

Vehicle 1 (State vehicle)

Driver's Name		Work Street Address	
Andrea Bevington		Cold Springs District Office	
Driver's License No./State		City, State, Zip	
756YY1301 / IA		Lewis, IA 51544	
Date of Birth	Department	Work Phone	Home Phone
02/08/1971	DNR	712-520-0508	641-418-0173
License Plate No.	VIN	Year, Make, Model	
1209	1C6RR7XTXGS324844	2016 Dodge Ram 1500	
Estimate (\$) of Damage		Description of Damage	
		Front bumper and Left front corner panel dented	

Vehicle 2 (other vehicle) if more than two vehicles-use additional forms

Driver's Name		Street Address	
N/A			
Driver's License No./State		City, State, Zip	
Date of Birth	Work Phone	Home Phone	License Plate No.
Description of Damage			

Property Damage other than vehicle (fence, utility pole, etc)	
Owner's Name, Address and Phone	Description of Property Damaged
N/A	
Injured Persons (attach additional sheets if necessary)	
Vehicle No. 1/ Name and Address	Describe Injuries
N/A	
Vehicle No. 2/ Name and Address	Describe Injuries
N/A	
Witness	
Name	Address/Phone
N/A	
Name	Address/Phone

Accident Diagram	
<p>Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle.</p>	
<p>State Hwy 2</p> <p>Newport Ave</p>	<p>I was driving west bound on Highway 2 approximately 1/4 mi west of Newport Ave when a two deer ran out of the ditch from the south heading north in front of me. I was able to slow down to miss the first deer, but the second deer running behind it ran into my front left corner panel and bumper.</p>

Date: 1/ 5/2022 04:28 PM
Estimate ID: 1022010008
Estimate Version: 0
Committed
Profile ID: * PDA IA

Property Damage Appraisers (PDA Omaha)

PO Box 241006, Omaha, NE 68124
(402) 552-0899
Fax: (402) 552-0898
Email: pdaomaha@pdaorg.net

Not An Authorization For repair
Read disclaimers following appraisal calculations.

Damage Assessed By: Cary Sommerla
Classification: Field

Appraised For: JESSICA HACKBARTH

Condition Code: Good
Date of Loss: 12/19/2021
Contact Date: 1/ 5/2022
Deductible: 0.00
File Number: 1022010008
Claim Number: APDSOI0231183-001

Type of Loss: Comprehensive

Insured: State of Iowa
Owner: State of Iowa
Telephone: Work Phone: (712) 520-0508

Mitchell Service: 911579

Description: 2016 Ram Pickup 1500 Outdoorsman
Body Style: 4D PkUpCrw 6' Bed 140" WB
VIN: 1C6RR7XTXGS324844
Mileage: 112,212
OEM/ALT: A
Color: Gray
Options: PASSENGER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING, AIR CONDITION
CRUISE CONTROL, TILT STEERING COLUMN, DRIVER AIRBAG, HEATED EXTERIOR MIRROR
FRONT SIDE AIRBAG WITH HEAD PROTECTION, SKID PLATES, ANTI-LOCK BRAKE SYS.
TRACTION CONTROL, FOG LIGHTS, ALUM/ALLOY WHEELS, REMOTE IGNITION
TIRE INFLATION/PRESSURE MONITOR, ANTI-THEFT SYSTEM, AUXILIARY INPUT
BLUETOOTH WIRELESS CONNECTIVITY, LEATHER STEERING WHEEL, SATELLITE RADIO
TOW HITCH RECEIVER, POWER ADJUSTABLE EXTERIOR MIRROR, 4WD OR AWD, PRIVACY GLASS
TRIP COMPUTER, FIRST ROW SPLIT BENCH SEAT, TELEMATIC SYSTEMS
UNIVERSAL GARAGE DOOR OPENER, 4 WHEEL DRIVE, SIDE AIRBAGS, AUTOMATIC HEADLIGHTS
SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION
INTERIOR AUTOMATIC DAY/NIGHT OR ELECTROCHROMATIC MIRROR, MP3 PLAYER
ELECTRONIC STABILITY CONTROL, KEYLESS ENTRY SYSTEM, LIMITED SLIP DIFFERENTIAL
POWER FOLDING EXTERIOR MIRRORS, REAR BENCH SEAT, SMART KEY SYSTEM
STEERING WHEEL AUDIO CONTROLS

Vehicle Production Date: 4/16
Drive Train: 5.7L Inj 8 Cyl 4WD
License: C-387 IA
Search Code: 102

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	101832	BDY	OVERHAUL	Frnt Bumper Assy			3.5 #
2	101263	BDY	REMOVE/REPLACE	Frnt Upr Bumper Fascia	** QUAL REPL PART	144.00	INC #
3	101266	BDY	REMOVE/REPLACE	L Frnt Upr Bumper Bracket	** QUAL REPL PART	45.00	INC #
4	AUTO	BDY	REMOVE/INSTALL	Frnt Upr Fascia			INC #
5	101268	BDY	REMOVE/REPLACE	L Frnt Upr Bumper Side Bracket	55277481AD	29.75	INC
6	103035	BDY	REMOVE/REPLACE	Frnt Bumper Assembly	** QUAL REPL PART	499.00	INC #
7	101269	BDY	REMOVE/REPLACE	Frnt Bumper Bracket	68232485AA	80.20	INC
8	101270	BDY	REMOVE/REPLACE	Frnt Bumper Bracket Kit	** QUAL REPL PART	31.00	INC
9	101766	BDY	REMOVE/REPLACE	L Frnt Combination Lamp	** QRP Certified	305.00	0.3 #
10	AUTO	BDY	CHECK/ADJUST	Headlamps			0.4
11	102215	BDY	REMOVE/REPLACE	L Fender Panel	** QRP Certified	400.00	1.7 #
12	AUTO	BDY	REMOVE/INSTALL	L Front Combination Lamp			INC #
13	AUTO	REF	REFINISH	L Fender Outside			C 2.2

ESTIMATE RECALL NUMBER: 01/05/2022 16:28:27 1022010008

Mitchell Data Version: OEM: DEC_21_V

MAPP:DEC_21_V

Copyright (C) 1994 - 2021 Mitchell International

Software Version: 7.1.242

All Rights Reserved

Page 1 of 4

Date: 1/ 5/2022 04:28 PM
 Estimate ID: 1022010008
 Estimate Version: 0
 Committed
 Profile ID: * PDA IA

14	AUTO	REF	REFINISH	L Add To Edge Fender				C 0.5
15	102221	BDY	REMOVE/REPLACE	L Fender Liner	** QUAL REPL PART	86.00	INC	
16	102252	BDY	REMOVE/INSTALL	L Fender Splash Guard			0.4	
17	102269	BDY	REMOVE/REPLACE	L Fender Adhesive Nameplate	68149700AB	90.65	0.1	
18	102626	BDY	REPAIR	L Frt Door Shell	Existing		1.5*#	
19	AUTO	REF	REFINISH	L Frt Door Outside			C 2.2	
20	101099	BDY	REMOVE/INSTALL	L Frt Otr Door Belt Moulding			0.3	
21	101101	BDY	REMOVE/INSTALL	L Frt Rear View Mirror			0.3 #	
22	104118	BDY	REMOVE/REPLACE	L Frt Door Adhesive Nameplate	68149702AA	116.00	0.2	
23	101913	BDY	REMOVE/INSTALL	L Frt Door Trim Panel			INC	
24	101923	BDY	REMOVE/INSTALL	L Frt Otr Door Handle			0.3 #	
25	AUTO	BDY	REMOVE/INSTALL	L Frt Door Carrier			2.0 #	
26	101448	BDY	REMOVE/INSTALL	L Frt Door Glass Run	Existing		0.2 r	
27	936012		ADD'L COST	Hazardous Waste Disposal		5.00	*	
28	AUTO	REF	ADD'L OPR	Clear Coat			1.5	
29	933003	REF	ADD'L OPR	Tint Color			0.5*	
30	933005	BDY	ADD'L OPR	Restore Corrosion Protection		10.00	* 0.3*	
31	933018	REF	ADD'L OPR	Mask For Overspray		7.50	* 0.3*	
32	AUTO		ADD'L COST	Paint/Materials		310.50	*	

* - Judgment Item
 # - Labor Note Applies
 ** QRP Certified - Quality Replacement Parts - Certified
 ** QUAL REPL PART - Quality Replacement Parts
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

KEYSTONE-INS QUALITY PRT
 8206 J ST.
 OMAHA
 NE 68127
 (402) 553-0230 (800) 642-1432

2	** CH1014107	144.00
3	** CH1042121	45.00
6	** CH1002397	499.00
8	** CH1061118	31.00
9	** CH2502282C	305.00
11	** CH1240269PP	400.00
15	** CH1248188	86.00

Remarks

Estimate is for damages due to deer impact only.

Estimate Totals

				Add'l Labor Amount	Sublet Amount	Totals				
I.	Labor Subtotals	Units	Rate				II.	Part Replacement Summary		Amount
	Body	11.5	66.00	10.00	0.00	769.00 T		Taxable Parts		1,826.60
	Refinish	7.2	66.00	7.50	0.00	482.70 T				
		Taxable Labor				1,251.70		Total Replacement Parts Amount		1,826.60
	Labor Summary	18.7				1,251.70				

ESTIMATE RECALL NUMBER: 01/05/2022 16:28:27 1022010008

Mitchell Data Version: OEM: DEC_21_V

MAPP:DEC_21_V

Software Version: 7.1.242

Copyright (C) 1994 - 2021 Mitchell International
 All Rights Reserved

Page 2 of 4

Date: 1/ 5/2022 04:28 PM
Estimate ID: 1022010008
Estimate Version: 0
Committed
Profile ID: * PDA IA

III. Additional Costs	Amount	IV. Adjustments	Amount
Taxable Costs	315.50	Insurance Deductible	0.00
Total Additional Costs	315.50	Customer Responsibility	0.00

Paint Material Method: Rates

Init Rate = 45.00 , Init Max Hours = 99.9, Addl Rate = 0.00

I.	Total Labor:	1,251.70
II.	Total Replacement Parts:	1,826.60
III.	Total Additional Costs:	315.50
	Gross Total:	3,393.80
IV.	Total Adjustments:	0.00
	Net Total:	3,393.80

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Point(s) of Impact

11 Left Front Corner (P)

Insurance Co: DAS FLEET SERVICES
DES MOINES, IA 50139
Work Phone: (877) 544-7843

Inspection Site: Residence
Address: 2085 110th
Corning, IA 50841
Inspection Date: 1/ 5/2022

Body Shop: Don's Body Shop
Address: 509 S. Brooks
Lenox, IA 50851
Telephone: (641) 333-2551
Fax Phone: (641) 333-2683
Email: donsbodyshop@lenoxia.com

ESTIMATE RECALL NUMBER: 01/05/2022 16:28:27 1022010008

Mitchell Data Version: OEM: DEC_21_V

Software Version: MAPP:DEC_21_V 7.1.242 Copyright (C) 1994 - 2021 Mitchell International
All Rights Reserved

Page 3 of 4