



Date: August 29, 2022

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Mariah Flowers, Fleet Manager

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	# 105973/Deer
Event Date	August 8, 2022
Summary	Vehicle #105973 struck a deer. (242646)
Amount Requested	\$5,194.40 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager

DAS Fleet Services

Mariah.Flowers@iowa.gov

515-414-6582



29C20

1 message

Risk, DAS <das.risk@iowa.gov>

Thu, Aug 11, 2022 at 10:20 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, AOS Peer Review <aos.peer.review@aos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 105973 struck a deer on 8/8/22. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk

Iowa Department of Administrative Services Division of Business and Property Services


Office: 515-725-2243 Das.Risk@iowa.gov https://das.iowa.gov

claim # 3, 250

Vehicle Accident Report

Time and location of accident					
Accident Date (Mo/Day/Year)		Time	No. of Vehicles		
08/08	3/2022	08:52 am	1		
County		State			
Davis	County	Iowa			
Vehicle 1 (State vehicle)					
Driver's Name		Work Street Address			
Tracy	Herrick	321 E 12	2th Street		
Driver's License No./State		City, State, Zip			
515LL7	321/Iowa	Des Moines	lowa 50309		
Date of Birth	Department	Work Phone	Home Phone		
09/23/1965	DIA	515-249-8239 515-707-264			
License Plate No.	VIN	Year, Make, Model			
105973		Chrysler 200 limited			
Estimate (\$) of Damage		Description of Damage			
		Drivers side quarter panel/ headlight and bumper due to deer running into car on HWY 16 E west of Davis county sign.			
Vehicle 2 (other vehicle) if	more than two vehicles-use a	dditional forms			
Driver's Name		Street Address			
Driver's License No./State		City, State, Zip			
Date of Birth	Work Phone	Home Phone License Plate No.			
Description of Damage					

Property Damage other than vehicle (fence, utility pole, etc)					
Owner's Name, Address and Phone	Description of Property Damaged				
Injured Persons (attach additional sheets if necessary)					
Vehicle No. 1/ Name and Address	Describe Injuries				
Vehicle No. 2/ Name and Address	Describe Injuries				
Witness	· · · · · · · · · · · · · · · · · · ·				
Name	Address/Phone				
none					
Name	Address/Phone				



Accident Information Exchange Sheet						
Other Vehicle information						
Driver's Name						
Street Address						
Driver Phone						
Driver's License No./State						
Vehicle Plate No.						
Vehicle year, make, model						
VIN						
Insurance Company Name						
Policy No.						
Agent name						
Agent phone						
Owner's Name/Address (if different)						
Submit this information	along with the accident report to DAS Fleet Service within 72 hours of the accident.					
Complete the r	next section, tear at the dotted line and give to the other party involved.					
State Vehicle Insurance Info	ormation					
Driver's Name						
Driver's License No./State						
Vehicle Plate No.						
Vehicle year, makel, model						

The State of Iowa is self-insured.

If you have any questions regarding an accident, please contact DAS Fleet Services at 515-281-3162 of DAS.Risk@iowa.gov

VIN

Van Buren County Sheriff's Office Initial Contact/Complaint Report

Case Number: 892206985

Subject(s)

REPORTING PARTY

TRACY HERRICK

2223 HOLLIWELL VALLEY CT, WINTERSET, IA, 50273

(515) 707-2643

Date / Time Reported:

Monday, August 8, 2022 at 09:05 hrs.

Officer Notified:

N/A

Officer Enroute:

N/A

Officer Arrived:

N/A

Officer Completed:

N/A

Received By Kathy Yarnell

Method Received 911

Category Citizen Contact

Nature of Contact Animal Complaint

\$0.00

Location

HIGHWAY 16 Douds

Summary

Hit a deer

Details/Narrative

Tracy called to report that she hit a deer on highway 16 near the Douds turnoff. She stated that it hit the drivers side. KY

Emailed a copy to Tracy KY

Status

Officer Assigned

Closed

N/A or Unknown

Vehicle Details

Unit

Ollic

Driver:

TRACY HERRICK

Address:

2223 HOLLIWELL VALLEY CT, WINTERSET, IA, 50273

(515) 707-2643

Vehicle Description

WHI CHRY

VIN:

License/State/Year

/IA

Owner:

(If Different than Driver)

Impound Location:

N/A

Towed:

NO

Inventoried: NO

Reason: N/A

Damage

Name of Insurance:

Insurance Phone:

Notes:

Printed 08/08/22

Page 1 of 2

Cons Novel	0000000			
Case Number:	892206985			_
Printed 08/08/22				
			Page 2 of 2	

QUALITY CLAIMS SOLUTIONS

Workfile ID:

2b75c6bf

105 N Krohn Place SIOUX FALLS, SD 57103 Phone: (877) 237-3727, FAX:(866) 371-2844 qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: STATE OF IOWA Job Number:

Written By: Wayne Malsam

Insured: Type of Loss: STATE OF IOWA

Collision

Point of Impact: 11 Left Front

Policy #: Date of Loss: UNK

8/13/2022 12:00 PM

Claim #:

APDSOI0242646-001

Days to Repair:

Repair Facility:

Owner:

STATE OF IOWA

2223 HOLLINUE VALLY CT

WINTERSET, IA 50273

Inspection Location:

BOB BROWN CHEVROLET 3600 111TH STREET

URBANDALE, IA 50322

Other

(515) 278-7866 Evening

VEHICLE

2016 CHRY 200 Limited FWD 4D SED 4-2.4L Gasoline Sequential MPI

VIN:

1C3CCCAB4GN111321

Production Date:

Interior Color:

License:

Odometer:

101,337

Exterior Color:

State:

Condition:

TRANSMISSION

Automatic Transmission

POWER

Power Steering **Power Brakes**

Power Windows Power Locks

Power Mirrors

DECOR Dual Mirrors

Tinted Glass Console/Storage Overhead Console CONVENIENCE

Air Conditioning Intermittent Wipers

Tilt Wheel

Cruise Control Rear Defogger

Keyless Entry Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel Backup Camera

RADIO

AM Radio FM Radio

Stereo Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes Front Side Impact Air Bags

Head/Curtain Air Bags Hands Free Device

SEATS

Cloth Seats **Bucket Seats**

Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint Metallic Paint OTHER

Traction Control Stability Control

Estimate of Record

Owner: STATE OF IOWA Job Number:

2016 CHRY 200 Limited FWD 4D SED 4-2.4L Gasoline Sequential MPI

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMP	PER & G	RILLE					(81)
2			O/H front bumper				3.4	
3	** <>	Repl	A/M Bumper cover w/o frt pk aid	1WZ18TZZAE	1	439.00	Incl.	2.8
4			Add for Clear Coat					1.1
5		Repl	Lower shield	68210186AC	1	217.00	Incl.	
6		Repl	LT Lamp cover w/o fog lamps	68202999AC	1	33.20	Incl.	
7		Repl	Upper grille 2.4 liter	68227617AC	1	132.00	Incl.	
8		Repl	Molding chrome	68202984AB	1	251.00	Incl.	
9	**	Repl	A/M Lower grille w/o fog lamps	68202988AC	1	97.00	Incl.	
10	**	Repl	A/M Upper molding chrome	68203029AB	1	181.00	Incl.	
11	**	Repl	A/M LT Outer molding chrome	68203035AB	1	155.00	Incl.	
12		Repl	LT Bezel w/o adaptive cruise gloss black	68228875AC	1	51.45		
13	**	Repl	A/M Shutter w/o fog lamps	68302662AA	1	<u>451.00</u>	Incl.	
14	RADIATOR S	UPPORT	Г					
15		Repl	Sight shield	68110455AD	1	97.10		
16		Repl	LT Side support	68158213AA	1	18.55		
17		Repl	LT H'lamp bracket	68385111AA	1	160.00		
18	HOOD							
19	*	Repl	LKQ hood +25%	68143614AC	1	912.50	0.7	2.8
20			Overlap Major Non-Adj. Panel					-0.2
21			Add for Clear Coat					0.5
22			Refn hinge					0.3
23		Repl	Insulator retainer	4878883AA	8	38.80		
24	FENDER							
25	**	Repl	A/M LT Fender (HSS)	68143657AA	1	255.00	2.5	1.8
26			Overlap Major Adj. Panel					-0.4
27			Add for Clear Coat					0.3
28			Add for Edging					0.5
29		Repl	LT Fender liner w/o ride & handling	68174587AE	1	130.00	Incl.	
30		Repl	LT Fender mtg bkt	68143685AB	1	14.90	0.2	0.3
31			Add for Clear Coat					0.1
32		Repl	LT Fender liner retainer	6510827AA	8	14.40		
33	FRONT DOOR	ŧ.						
34	*	Rpr	LT Door shell (HSS)				1.0	2.0
35			Overlap Major Adj. Panel					-0.4
36			Add for Clear Coat					0.3
37		R&I	LT Belt molding chrome				0.3	
38		R&I	LT R&I mirror				0.4	
39		R&I	LT Handle, outside w/o chrome strip white				0.4	
40		R&I	LT Carrier				0.9	

Estimate of Record

Own	er: STATE OF IO	WA				Job N	lumber:
016 C	HRY 200 Limited FWD	4D SED 4-2.4L Gasoline Sequential MI	PI				
41	R8	kI LT R&I trim panel				0.5	
42	R8	kI LT Corner molding 200S				Incl.	
43	PILLARS, ROCKER	& FLOOR					
44	R8	kI LT Rocker molding white				1.1	
45	VEHICLE DIAGNO	STICS					
46	* Re	pl <u>Pre-repair scan (paid per invloice</u>)		1	m		
47	* Re	pl <u>Post-repair scan (paid per</u> <u>invoice)</u>		1	m		
48	#	Hazardous Waste		1	3.00 X		
49	#	Cover Car		1	5.00	0.2	
50	#	Corrosion Protection		1	5.00	0.1	
51	#	Flex Agent		1	5.00		
			SUBTOTALS		3,666.90	11.7	11.8

ESTIMATE TOTALS

Category	Basis	Basis		Cost \$	
Parts				3,663.90	
Body Labor	11.7 hrs	@	\$ 65.00 /hr	760.50	
Paint Labor	11.8 hrs	@	\$ 65.00 /hr	767.00	
Miscellaneous				3.00	
Subtotal			200	5,194.40	
Total Cost of Repairs				5,194.40	
Deductible				0.00	
Total Adjustments				0.00	
Net Cost of Repairs	(a) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c			5,194.40	
X					

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.