



Date: November 5, 2021

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Mariah Flowers, Fleet Manager

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#2536/Hail
Event Date	July 9, 2021
Summary	Vehicle #2536 sustained hail damage. (227462)
Amount Requested	\$5,991.80 - Estimate \$ 182.75 - Review Invoice \$6,174.55 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager

DAS Fleet Services

Mariah.Flowers@iowa.gov

515-725-2243



29C20 - 2536, 2599

1 message

227442

Risk, DAS <das.risk@iowa.gov>

Mon, Jul 19, 2021 at 12:43 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicles 2536 & 2599 sustained hail damage on 7/9/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk

Iowa Department of Administrative Services Division of Business and Property Services

Office: 515-725-2243 Das.Risk@iowa.gov https://das.iowa.gov ESTIMATES

2536-221462

Vehicle Accident Report

Time and location of accide	ent				
Accident Date (Mo/Day/Year)		Time	No. of Vehicles		
7/9/:	2021	1:45pm	1		
County		State			
Po	olk	lo	wa		
Vehicle 1 (State vehicle)					
Driver's Name		Work Street Address			
No	one	400 SW 8t	h St, Ste C		
Driver's License No./State		City, State, Zip			
N	IA	Des M	loines		
Date of Birth	Department	Work Phone	Home Phone		
NA	Iowa Board of Medicine				
License Plate No.	VIN	Year, Make, Model			
347CDP	1FAHP2D87KG108495	2019 Ford Taurus			
Estimate (\$) of Damage		Description of Damage			
世253	00	Hail storm moved through Des Moines and damaged the state cars sitting in the parking lot.			
Vehicle 2 (other vehicle) if n	nore than two vehicles-use ac	dditional forms			
Driver's Name		Street Address			
N.	A				
Driver's License No./State		City, State, Zip			
Date of Birth	Work Phone	Home Phone	License Plate No.		
Description of Damage					

Date: 10/14/2021 12:03 PM

Estimate ID: 7761100040

Estimate Version:

Committed Profile ID: Ouote ID:

* Mitchell 94396606

Property Damage Appraisers (PDA Des Moines)

P.O. Box 144, Collins, IA 50055 (515) 222-1906 Fax: (515) 222-1929 Email: pdadesmoines@pdaorg.net

* Not An Authorization For Repair * Read disclaimers following appraisal calculations.

Damage Assessed By: CALEB CUTLER

Appraised For: JESSICA HACKBARTH

Type of Loss: Other

Classification: Field

Condition Code: Good Deductible:

0.00

File Number:

7761100040

Claim Number: APDSOI0227462-001

Insured: Owner: STATE OF IOWA/IOWA BOARD OF MEDICIN STATE OF IOWA/IOWA BOARD OF MEDICIN 400 SW 8TH ST STE C, DES MOINES, IA 50309

Address: Telephone:

Cell Phone:

(515) 281-3654

Mitchell Service: 911334

Description: 2019 Ford Taurus SE

Body Style:

4D Sed

VIN: 1FAHP2D87KG108495

Mileage: 11,747

OEM/ALT: Color: Options:

0 WHITE

License: 347CDP IA Search Code: 776

Drive Train: 3.5L Inj 6 Cyl 6A FWD

PASSENGER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, POWER STEERING

REAR WINDOW DEFOGGER, AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN

AM/FM STEREO, DRIVER AIRBAG, POWER PASSENGER SEAT

FRONT SIDE AIRBAG WITH HEAD PROTECTION, ANTI-LOCK BRAKE SYS., TRACTION CONTROL

ALUM/ALLOY WHEELS, REARVIEW CAMERA, TIRE INFLATION/PRESSURE MONITOR

AUXILIARY INPUT, BLUETOOTH WIRELESS CONNECTIVITY, CD PLAYER

POWER ADJUSTABLE EXTERIOR MIRROR, TRIP COMPUTER, FIRST ROW BUCKET SEAT

TELEMATIC SYSTEMS, CLOTH SEAT, SIDE AIRBAGS, AUTOMATIC HEADLIGHTS SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION, MP3 PLAYER

DRIVER SEAT WITH POWER LUMBAR SUPPORT, ELECTRONIC STABILITY CONTROL FRONT SEATS WITH POWER LUMBAR SUPPORT, KEYLESS ENTRY SYSTEM, REAR BENCH SEAT

STEERING WHEEL AUDIO CONTROLS

Item Number Type Operation Description Part Number Amount Unit I 100049 BDY REMOVE/INSTALL R Front Combination Lamp 0,3 2 BDY REMOVE/INSTALL Frt Bumper Cover 1,2 3 100050 BDY REMOVE/INSTALL L Front Combination Lamp 0,3 Hood	or
1 100049 BDY REMOVE/INSTALL R Front Combination Lamp 0.3 2 BDY REMOVE/INSTALL Frt Bumper Cover 1.2 3 100050 BDY REMOVE/INSTALL L Front Combination Lamp 0.3	5
2 BDY REMOVE/INSTALL Frt Bumper Cover 1.2 3 100050 BDY REMOVE/INSTALL L Front Combination Lamp 0.3	
3 100050 BDY REMOVE/INSTALL L Front Combination Lamp 0.3	#
0.5	
Hood	#
4 100079 BDY REMOVE/INSTALL Hood Assy 0.5	
5 BDY PAINTLESS REPAIR Hood Panel Sublet 700.00	
6 76 QUARTER SIZE DENTS	
7 100081 BDY REMOVE/INSTALL Hood Insulator Existing 0.3	r
Front Fender	
8 BDY PAINTLESS REPAIR R Fender Panel Sublet 100.00	#
9 1 NICKEL SIZE DENT	
10 BDY PAINTLESS REPAIR L Fender Panel Sublet 100.00	#
11 2 NICKEL SIZE DENTS	

ESTIMATE RECALL NUMBER: 10/14/2021 12:02:58 7761100040

7.1.241

Mitchell Data Version: OEM: SEP_21_V1012

Copyright (C) 1994 - 2021 Mitchell International

All Rights Reserved

Page 1 of 4

Date: 10/14/2021 12:03 PM Estimate ID: 7761100040

Estimate Version: 0

Committed
Profile ID: * Mitchell

						Quote ID:	* Mitchell 94396606		
12	100037	BDY	REMOVE/INSTALL	R Fender Liner		Existing	34330000	0.4	r
13	100038	BDY	REMOVE/INSTALL	L Fender Liner		Existing		0.4	
				Rocker/Pillars/Flo	or				
14		BDY	PAINTLESS REPAIR	R Door Opening Frame	-s	Sublet	125.00		
15				3 NICKEL SIZE DENTS					
16				INCLUDES: Double Panel					
17		BDY	PAINTLESS REPAIR	L Door Opening Frame	-S	Sublet	156.25		
18				2 QUARTER SIZE DENTS					
19				INCLUDES: Double Panel					
				Front Door					
20		BDY	PAINTLESS REPAIR	L Frt Door Shell		Sublet	156.25		#
21				2 QUARTER SIZE DENTS					
22				INCLUDES: Double Panel					
23	101067		REMOVE/REPLACE	R Frt Otr Door Belt Moulding		AG1Z 5421452 A	174.37	0.2	#
24	404060	BDY	REMOVE/INSTALL	R Frt Rear View Mirror			04745300 +4755700 (47474)	0.3	
25	101068		REMOVE/REPLACE	L Frt Otr Door Belt Moulding		AG1Z 5421453 A	174.37	0.2	#
26	101063	BDY	REMOVE/INSTALL	L Frt Rear View Mirror				0.3	
27	101063		REMOVE/REPLACE	R Frt Upr Door Moulding		AG1Z 5420550 B	185.77	0.2	
28	101064	BDY	REMOVE/REPLACE	L Frt Upr Door Moulding		AG1Z 5420551 B	165.52	0.2	
29		BDY	PAINTLESS REPAIR	Rear Door		Cubles	456.25		
30		וטט	PAINTLESS REPAIR	R Rear Door Shell 1 QUARTER SIZE DENT		Sublet	156.25		
31				INCLUDES: Double Panel					
32		BDY	PAINTLESS REPAIR	L Rear Door Shell		Sublet	156.25		
33		001	MINIESS REPAIR	2 QUARTER SIZE DENTS		Subjec	130.23		
34				INCLUDES: Double Panel					
35	100225	BDY	REMOVE/INSTALL	R Rear Otr Door Belt Moulding				INC	#
36	100226		REMOVE/INSTALL	L Rear Otr Door Belt Moulding				0.3	
37	100233	BDY	REMOVE/REPLACE	R Rear Otr Door Belt Moulding		AG1Z 5425596 A	169.23	0.3	
			a to a section contains accessored to the participant and Amazonia and Amazonia	Roof				0.0	
38		BDY	PAINTLESS REPAIR	Roof Panel		Sublet	1,600.00	k	
39				145 QUARTER SIZE DENTS			•		
40				LARGE DENT @ \$400.00					
41	100873	BDY	REMOVE/INSTALL	Roof Antenna				0.3	#
42	102146		REMOVE/REPLACE	R Roof Moulding		EG1Z 5451729 D	135.52	0.3	
43	102148		REMOVE/REPLACE	L Roof Moulding		EG1Z 5451729 D	135.52	0.3	
44	100347	BDY	REMOVE/INSTALL	Roof Headliner				3.7	
				Quarter Panel					
45		BDY	PAINTLESS REPAIR	R Quarter Outer Panel		Sublet	156.25		#
46				1 QUARTER SIZE DENT					
47 48		BDV	DAINTI ECC DEDAID	INCLUDES: Double Panel		Collet	456.05		
49		BDY	PAINTLESS REPAIR	L Quarter Outer Panel		Sublet	156.25	i	#
50				2 QUARTER SIZE DENTS INCLUDES: Double Panel					
30				Luggage Lid					
51	100505	BDY	REMOVE/INSTALL	Luggage Lid Assy				0.5	
52	100510		REMOVE/INSTALL	Luggage Lid Insulator				0.3	
53	200020	BDY	PAINTLESS REPAIR	Luggage Lid Panel		Sublet	525.00 *		
54		1000 (CT) (A17)		31 QUARTER SIZE DENTS		Subject	323.00		
55				LARGE DENT @ \$100.00					
				_Rear Lamps					
56	100012	BDY	REMOVE/INSTALL	R Rear Combination Lamp				0.4	
57	100013	BDY	REMOVE/INSTALL	L Rear Combination Lamp				0.4	
				Additional Operation	ns				
58	933005	BDY	ADD'L OPR	Restore Corrosion Protection			10.00 *		

^{* -} Judgment Item

ESTIMATE RECALL NUMBER: 10/14/2021 12:02:58 7761100040 Mitchell Data Version: OEM: SEP_21_V1012

Copyright (C) 1994 - 2021 Mitchell International

7.1.241 All Rights Reserved

^{# -} Labor Note Applies

r - CEG R&R Time Used For This Labor Operation Paintless Repair calculations provided by Dent Wizard.

Date: 10/14/2021 12:03 PM

Estimate ID: 7761100040

Estimate Version:

Committed

Profile ID: * Mitchell Quote ID: 94396606

Estimate Totals

I.	Labor Subtotals Body	Units 11.6 Taxable	Rate 65.00 Labor	Add'l Labor Amount 10.00	Sublet Amount 4,087.50	Totals 4,851.50 T 4,851.50	II.	Part Replacement Summary Taxable Parts Total Replacement Parts Amount	Amount 1,140.30 1,140.30
	Labor Summary	11.6				4,851.50			
III.	Additional Costs Total Addition	nal Costs				Amount 0.00	IV.	Adjustments Insurance Deductible Customer Responsibility	0.00 0.00
							I. II. III.	Total Labor: Total Replacement Parts: Total Additional Costs: Gross Total:	4,851.50 1,140.30 0.00 5,991.80
							IV.	Total Adjustments: Net Total:	0.00 5,991.80

Point(s) of Impact

16 Non-Collision (P)

Insurance Co: DAS FLEET SERVICES

DES MOINES, IA 50139

Work Phone: (877) 544-7843

Inspection Site: OTHER

Address: 400 SW 8TH ST

DES MOINES, IA 50309

Inspection Date: 10/14/2021

Body Shop: BOB BROWN COLLISION CENTER Address: 4224 MERLE HAY ROAD

DES MOINES, IA 50310

Telephone: (515) 278-7866 Fax Phone: (515) 278-7808 State Lic. No: 42-0846759

ESTIMATE RECALL NUMBER: 10/14/2021 12:02:58 7761100040

Mitchell Data Version: OEM: SEP_21_V1012

Software Version:

Copyright (C) 1994 - 2021 Mitchell International All Rights Reserved

7.1.241



Due upon receipt

INVOICE

INDICIO	SE MUNDED		
INVOIC	CE NUMBER	INVOICE DATE	
776-0	0280522	10/14/2021	

BILL TO	CLIENT CODE		
Attn: JESSICA HACKBARTH DAS FLEET SERVICES	DAS105001		
ttn: JESSICA HACKBARTH AS FLEET SERVICES 09 SE 13TH ST	BUSINESS LINE / LOSS TYPE		
DES MOINESIA 50139	A - Commercial Auto		

FOR INQUIRIES:

PDA Des Moines, IA #776

pdadesmoines@pdaorg.net (515) 222-1906

SUBMIT PAYMENT TO:

Property Damage Appraisers, Inc. 75-1160563

Dept #161, P.O. Box 1000 Memphis, TN 38148-0161

Please reference the invoice number and enclose a copy of the invoice on all payments.

INSURED	CLAIMANT	ASSIGNMENT DATE	PDA ASSIGNMENT #
E OF IOWA/IOWA BOARD OF MEDI		10/13/2021	776-110-0040
CLAIM#	POLICY#	LOSS DATE	REFERENCE #
APDSOI0227462-001			

SERVICE FEE: (1 Unit(s) @ \$179.00)

\$ 179.00

Mileage: (3.00 miles) @ \$1.25

\$ 3.75

ACH Payment Info:
Bank: First Horizon Bank
ABA (US): 084000026 Bank
Account: 220002525824
Email Remit Information to:
achbackup@pdaorg.net

Click here to pay your invoice at PDAClientPortal.com

Same-Day Service. Guaranteed. PDA now offers expedited service for standard auto claims in select markets.

WE HAVE CHANGED OUR BANK REMITTANCE INFORMATION AS NOTED ABOVE PLEASE UTILIZE OUR PORTAL FOR ALL OTHER ELECTRONIC PAYMENTS.

Terms: Professional fees due upon receipt. Interest accrues at 1% per month.

Please include the invoice number on all payments.

INVOICE TOTAL: \$ 182.75

BOB BROWN CHEVROLET

3600 111th Street Urbandele, IA 50322 · Use Exit 126 Off I-80/235 Phone: (515) 278-7844 · Toll Free: (800) 947-3350 www.bobbrownchevy.com

FINAL BILL

	,,,,,			* FEET	4	
CUSTOMER NO. 100015	SERVICE ADVI	COTT E M.	ATLAGE	TAG NO. T8495	INVOICE DATE	INVOICE NO.
STATE OF IOWA DAS 109 SE 13 TH ST	HOURLY RATE O.OO YEAR/MAKE/MI	2536	0.	PO NO. 2536	: 300CT21 color WHITE	1344364 NO. STOCK / STOCK NO
DES MOINES, IA 50319-0106	19 FOR	TELESTION NO.			MILEAGE IN 11747 PROD. DATE	MILEAGE OUT
das,finance.payables@iowa.gov home	1FAHP2 cell phone 515-210	D87KG10	PROM		R.O. DATE	O7JAN20
515-669-1836 TEL BUSINESS EXT. 515-281-3162	COMMENTS	5-7254	118	00 290CT21	250CT21	
A DAS FLEET SERVICES PDA EST. CLAIM#ADPSOI02 96 BODY REPAIR	27462-001					
497 WISNOUSKY, TED LIC#: *		~ ` `		- M. M.		
96 BODY REPAIR 2171 CB			828.06	828.06	o .	
96 BODY REPAIR			260.00	260.00		
2736 CB 96 BODY REPAIR			560.00	560.00		
2872 CB 96 BODY REPAIR 2872 CB			260.00	260.00		
1 15162675 LAMP 1 AG1Z5420550B MOULDING		149.97	260.00 149.97	149.97		
PARTS: 335.74 LABOR: 2168.06 OTHER:	0.00	185.77 TOTAL LI	185.77 NE A:	185.77 2503.80		
B** CARMEDIC HAIL 70 SUBLET		*****	*			
999 CB EUBL CARMEDIC HAIL PO#86519 CB			0.00	0.00		
PARTS: 0.00 LABOR: 0.00 OTHER:	3488.00	TOTAL LIN	3488.00 E B:	3488.00 3488.00		
Uelice # 2536	*****	****	*			
e were						

	Inani	0	
W_e	appreciate	your	business.

HERMANN . WA

THE SELLING DEALER MAKES NO WARRANTY OF ANY KIND WHAT SOEVER AS TO THE MERCHANTABILITY OF THE PRODUCTS LISTED HEREON OR AS TO THEIR FITNESS FOR ANY PARTICULAR PURPOSE. ANY WARRANTY WHICH MAY EXIST IS AN AGREEMENT SOLELY BETWEEN THE MANUFACTURER AND THE PURCHASER.

CUSTOMER SIGNATURE

MI

DESCRIPTION	TOTALS	Mile.
' LABOR AMOUNT	2168.0	6
PARTS	335.7	
GAS, OIL, LUBE	0.0	00
SUBLET REPAIRS	3488.0	0
MISC/ENVIRONMENTAL CHARGES	0.0	0
TOTAL CHARGES	5991.8	0
LESS DISCOUNT/INSURANCE	0.0	0
SALES TAX	0.0	0
PLEASE PAY THIS AMOUNT	5991.8	0

FII F COPY