



Date: November 5, 2021

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

**Executive Council** 

From: Mariah Flowers, Fleet Manager

**DAS Fleet Services** 

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#2944/Deer
Event Date	October 6, 2021
Summary	Vehicle #2944 struck a deer. (227205)
Amount Requested	\$5,480.45 - Estimate \$ 509.34 - Review Invoice \$5,989.79 - Total
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you

Mariah Flowers, Fleet Manager

**DAS Fleet Services** 

Mariah.Flowers@iowa.gov

515-725-2243



Risk, DAS <das.risk@iowa.gov>

### Fwd: Deer Hit

1 message



Risk, DAS <das.risk@iowa.gov>

Thu, Oct 7, 2021 at 10:18 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 2944 struck a deer on 10/6/2021. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



#### **DAS Fleet Services, Risk**

Iowa Department of Administrative Services Division of Business and Property Services

Office: 515-725-2243 Das.Risk@iowa.gov https://das.iowa.gov

----- Forwarded message -----

From: Rusk, Josh <josh.rusk@dnr.iowa.gov>

Date: Thu, Oct 7, 2021 at 9:47 AM

Subject: Re: Deer Hit

To: Risk, DAS <das.risk@iowa.gov>

Cc: Brian Hickman <bri> srian.hickman@dnr.iowa.gov>

Attached is the accident report. The estimate is also attached. He accidently included tax so I used the number before taxes in the report.

Thanks Josh

On Thu, Oct 7, 2021 at 8:26 AM Risk, DAS <das.risk@iowa.gov> wrote:

I received your message this morning. Go ahead and complete the accident report and estimate done, once I receive those I will let you know when repairs are approved.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,

**DAS Fleet Services, Risk** 

Iowa Department of Administrative Services Division of Business and Property Services



Office: 515-725-2243 Das.Risk@iowa.gov https://das.iowa.gov



JOSH RUSK | Natural Resource Technician 2 Grand River Wildlife Unit

Wildlife Bureau

**Iowa Department of Natural Resources** O: 641-783-2166 C: 515-238-7194

2991 State Highway 2, Kellerton, IA 50133











#### 2 attachments


AccidentReportForm\_10-6-21.pdf

DNRJOSHRUSK\_Chevrolet1500Silverado.pdf

## **Vehicle Accident Report**

Time and location of accid	ent		THE RESERVE TO	
Accident Date (Mo/Day/Year)		Time	No. of Vehicles	
10/6	5/2021	7:15AM	1	
County	•	State		
Uı	nion		A	
Vehicle 1 (State vehicle)				
Driver's Name		Work Street Address		
Josh	Rusk	2991 State	Highway 2	
Driver's License No./State		City, State, Zip		
686XX	4586/IA	Kellerton	, IA 50133	
Date of Birth	Department	Work Phone	Home Phone	
06/21/1981	Natural Resources	515-238-7194	641-344-9856	
License Plate No.	VIN	Year, Make, Model		
2944	3GCUKNEH0JG312484	2018, Chevrolet, Silverado 1500		
Estimate (\$) of Damage		Description of Damage		
\$4099.25		Hit deer smashed up bumper and grill.		
Vehicle 2 (other vehicle) if	more than two vehicles-use ac	dditional forms		
Driver's Name		Street Address		
Driver's License No./State		City, State, Zip		
Date of Birth	Work Phone	Home Phone	License Plate No.	
Description of Damage				

Property Damage other than vehicle (fence, utility pole, etc)						
Owner's Name, Address and Phone	Description of Property Damaged					
Injured Persons (attach additional sheets if necessary)						
Vehicle No. 1/ Name and Address	Describe Injuries					
Vehicle No. 2/ Name and Address	Describe Injuries					
Witness						
Name	Address/Phone					
Name	Address/Phone					



Date: 10/8/2021 09:51 AM

Estimate ID: 7761100030

Estimate Version:

Committed Profile ID: Mitchell 94067008 Quote ID:

# **Property Damage Appraisers (PDA Des Moines)**

P.O. Box 144, Collins, IA 50055 (515) 222-1906 Fax: (515) 222-1929 Email: pdadesmoines@pdaorg.net

\* Not An Authorization For Repair \* Read disclaimers following appraisal calculations.

Damage Assessed By: CALEB CUTLER

Appraised For: JESSICA HACKBARTH

Classification: Field

Condition Code: Good

Deductible: 0.00

File Number: 7761100030

Claim Number: APDSOI0227205-001

Insured: STATE OF IOWA

Address:

Owner: STATE OF IOWA

2991 STATE HIGHWAY 2, KELLERTON, IA 50133 Telephone: Work Phone:

(515) 238-7194

Type of Loss: Other

Cell Phone: (641) 344-9856

Mitchell Service: 911611

Description: 2018 Chevrolet Silverado 1500 W/T

Body Style: 4D PkupCrw 6' Bed 144" WB VIN: 3GCUKNEH0JG312484

Vehicle Production Date: 2/18

Search Code: 776

Drive Train: 4.3L Inj 6 Cyl 4WD License: 2944 IA

Mileage: 50,613

OEM/ALT:

BLACK Color:

Options:

PASSENGER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING, AIR CONDITION CRUISE CONTROL, TILT STEERING COLUMN, AM/FM STEREO, DRIVER AIRBAG

FRONT SIDE AIRBAG WITH HEAD PROTECTION, ANTI-LOCK BRAKE SYS., TRACTION CONTROL

REARVIEW CAMERA, TIRE INFLATION/PRESSURE MONITOR, AUXILIARY INPUT

BLUETOOTH WIRELESS CONNECTIVITY, HIGH INTENSITY DISCHARGE HEADLIGHTS, 4WD OR AWD

FIRST ROW SPLIT BENCH SEAT, 4 WHEEL DRIVE, SIDE AIRBAGS

SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION, MP3 PLAYER, DAYTIME RUNNING LIGHTS

ELECTRONIC STABILITY CONTROL, REAR BENCH SEAT

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
	Front Bumper						
1		BDY	OVERHAUL	Frt Bumper Assy			3.1 #
2	103297	BDY	REMOVE/REPLACE	Frt Bumper Impact Bar	** QRP Certified	692.00	INC #
3		REF	REFINISH	Frt Face Bar			C 2.1
4	103299	BDY	REMOVE/REPLACE	R Frt Otr Bumper Filler	** QUAL REPL PART	50.00	0.1 #
5		BDY	REMOVE/INSTALL	R Front Combination Lamp			INC #
6	104142	BDY	REMOVE/REPLACE	Frt Lwr Bumper Fascia	** QUAL REPL PART	419.00	INC #
7	103305	BDY	REMOVE/REPLACE	Frt Bumper License Plate Bracket	** QUAL REPL PART	42.00	INC
8	103342	BDY	REMOVE/REPLACE	R Frt Otr Bumper Bracket	** QUAL REPL PART	56.00	INC #
9		BDY	REMOVE/INSTALL	Frt Bumper Assy			INC #
10	103344	BDY	REMOVE/REPLACE	R Frt Bumper Bracket	** QUAL REPL PART	76.00	INC #
11	103346	BDY	REMOVE/REPLACE	Frt Ctr Bumper Bracket	** QUAL REPL PART	34.00	INC #
				<u>Grille</u>			
12	102741	BDY	REMOVE/REPLACE	Grille Assembly	** QRP Certified	663.00	INC #
13	103422	BDY	REMOVE/REPLACE	Inr Grille	** QRP Certified	65.00	0.2 #
				Front Lamps			
14	103508	BDY	REMOVE/INSTALL	L Front Combination Lamp			0.3 #
15	103551	BDY	REMOVE/REPLACE	R Frt Combination Lamp Assembly	** QUAL REPL PART	1,232.00	0.3 #

ESTIMATE RECALL NUMBER: 10/08/2021 09:51:27 7761100030

Mitchell Data Version: OEM: SEP\_21\_V1004
MAPP:SEP\_21\_V Copyright (C) 1994 - 2021 Mitchell International

Software Version: 7.1.241 All Rights Reserved

Date: 10/8/2021 09:51 AM

Estimate ID: 7761100030

Estimate Version: Committed

Profile ID: Mitchell

				Quote ID.	9400/000	
16	BDY	CHECK/ADJUST	Headlamps			0.4
			Additional Costs & Materials			
17	936012	ADD'L COST	Hazardous Waste Disposal		5.00	*
			Additional Operations			
18	REF	ADD'L OPR	Clear Coat			0.8
19	933005 BDY	ADD'L OPR	Restore Corrosion Protection		6.00	* 0.1*
			Additional Costs & Materials			
20		ADD'L COST	Paint/Materials		104.40	*

<sup>\* -</sup> Judgment Item

KEYSTONE KEYSIQ 2400 KERPER BLVD. STE. E100A DUBUQUE IA 52004 (319) 566-5030 (800) 747-2500 \*\* GM1002869C 692.00 \*\* GM1089183 50.00 \*\* GM1015135C 419.00 6 \*\* GM1068172 42.00 8 \*\* GM1063115 56.00 \*\* GM1063113C 76.00 10 \*\* GM1041136 11 34.00 \*\* GM1200696C 663.00 12 \*\* GM1223112C 65.00 13 \*\* GM2503445N 1,232.00 15

### **Estimate Totals**

I.	Labor Subtotals Body Refinish	4.5 5	Rate Am 58.00 6 58.00 0	dd'I bor ount .00	Sublet Amount 0.00 0.00	Totals 267.00 T 168.20 T 435.20 26.11	II.	Part Replacement Summary Taxable Parts Sales Tax @ Total Replacement Parts Amount	6.000%	Amount 3,329.00 199.74 3,528.74
	Labor Summary	7.4				461.31				
III.	Additional Costs Taxable Costs  Total Addition Paint Material Init Rate = 36	Sales Tax nal Costs I Method: Ra			00% ddl Rate =	Amount 109.40 6.56 115.96	IV.	Adjustments Insurance Deductible Customer Responsibility		Amount 0.00 0.00
							I. II. III.	Total Labor: Total Replacement Parts: Total Additional Costs: Gross Total:		461.31 3,528.74 115.96 4,106.01

<sup># -</sup> Labor Note Applies

<sup>\*\*</sup> QRP Certified - Quality Replacement Parts - Certified \*\* QUAL REPL PART - Quality Replacement Parts

C - Included in Clear Coat Calc

Date: 10/8/2021 09:51 AM

Estimate ID: 7761100030

Estimate Version:

Committed Profile ID:

Mitchell Quote ID: 94067008

T\/ Total Adjustments:

Net Total:

0.00 4,106.01

Point(s) of Impact 12 Front Center (P)

Insurance Co: DAS FLEET SERVICES

DES MOINES, IA 50139

Work Phone: (877) 544-7843

Inspection Site: DNR OFFICE

2991 STATE HIGHWAY 2 Address:

KELLERTON, IA 50133

Inspection Date: 10/8/2021

Body Shop: BICE AUTO LLC Address: 2661 State Hwy 2

Mount Ayr, IA 50854

Telephone: (641) 464-2154

State Lic. No: 20-0105206

Email: biceauto2661@yahoo.com

THIS IS NOT AN AUTHORIZATION FOR REPAIR. ALL COSTS OF REPAIRS ARE THE SOLE RESPONSIBILITY OF THE VEHICLE OWNER, WHO MUST AUTHORIZE ALL REPAIRS. FAILURE TO DELIVER A COPY OF THIS APPRAISAL TO THE REPAIR SHOP BY THE VEHICLE OWNER MAY RESULT IN OUT OF POCKET EXPENSE TO THE VEHICLE OWNER. PROVIDING A COPY OF THIS APPRAISAL IS NOT AN ACCEPTANCE OF COVERAGE OR LIABILITY AND ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE DETERMINED BY THE INSURANCE CARRIER. DEDUCTIBLES MAY OR MAY NOT BE ADDRESSED OR INCLUDED IN THIS APPRAISAL.

IF APPLICABLE, THE REPAIRER SHOULD COLLECT THE DEDUCTIBLE FROM THE VEHICLE OWNER PRIOR TO THE RELEASE OF THE REPAIRED VEHICLE. IT IS THE REPAIRER'S RESPONSIBILITY TO SEND NOTIFICATION OF THE SUPPLEMENT VIA FAX OR EMAIL TO PDA AT 515-222-1929 OR pdadesmoines@pdaorg.net INCLUDING A STATEMENT WHETHER THE REPAIRS HAVE BEEN HALTED ON THE VEHICLE. PDA WILL RESPOND TO YOUR REQUEST WITHIN24 HOURS. PLEASE ALLOW 48 HOURS TO COMPLETE THE SUPPLEMENT PROCESSING FROM THE DATE OF REQUEST TO ENSURE TIMELY RELEASE OF THE VEHICLE.

THIS APPRAISAL IS SUBJECT TO THE COMPLETE REVIEW AND APPROVAL BY THE ASSIGNING INSURANCE COMPANY TO ASSURE ACCURACY, COST EFFECTIVENESS, AND THAT ACCEPTED INDUSTRY REPAIR STANDARDS ARE MET. THE INSURANCE COMPANY LISTED HAS THE RIGHT TO ACCEPT OR REJECT ANY PART OR ALL OF THIS APPRAISAL OR MAKE ANY CHANGES THEY FEEL NECESSARY.

Any person who knowingly presents a false or fraudulent insurance claim for the payment of a loss may be guilty of a crime and may be subject to fines and confinement in state prison.

ESTIMATE RECALL NUMBER: 10/08/2021 09:51:27 7761100030

Software Version:

7.1.241

Mitchell Data Version: OEM: SEP\_21\_V1004

MAPP:SEP\_21\_V Copyright (C) 1994 - 2021 Mitchell International All Rights Reserved



Due upon receipt

INVOICE

INVOICE NUMBER	INVOICE DATE
776-0280382	10/08/2021

## Attn: JESSICA HACKBARTH

DAS FLEET SERVICES

109 SE 13TH ST

DES MOINESIA 50139

CLIENT CODE

DAS105001

BUSINESS LINE / LOSS TYPE

A - Commercial Auto

FOR INQUIRIES:

PDA Des Moines, IA #776

pdadesmoines@pdaorg.net (515) 222-1906

SUBMIT PAYMENT TO:

Property Damage Appraisers, Inc. 75-1160563

Dept #161, P.O. Box 1000 Memphis, TN 38148-0161

Please reference the invoice number and enclose a copy of the invoice on all payments.

INSURED	CLAIMANT	ASSIGNMENT DATE	PDA ASSIGNMENT#
STATE OF IOWA		10/07/2021	776-110-0030
CLAIM#	POLICY#	LOSS DATE	REFERENCE #
APDSOI0227205-001			

SERVICE FEE: ( 1 Unit(s) @ \$179.00 )

\$ 179.00

Mileage: (166.00 miles) @ \$1.25

\$ 207.50

Long Distance Drive Time/Mile: 166.00 miles @\$.74/mile

\$ 122.84

ACH Payment Info: Bank: First Horizon Bank ABA (US): 084000026 Bank Account: 220002525824 Email Remit Information to: achbackup@pdaorg.net

Click here to pay your invoice at PDAClientPortal.com

Same-Day Service. Guaranteed. PDA now offers expedited service for standard auto claims in select markets.

\*\*WE HAVE CHANGED OUR BANK REMITTANCE INFORMATION AS NOTED ABOVE PLEASE UTILIZE OUR PORTAL FOR ALL OTHER ELECTRONIC PAYMENTS.\*\*

\*\*Terms: Professional fees due upon receipt. Interest accrues at 1% per month.
Please include the invoice number on all payments.

INVOICE TOTAL: \$ 509.34

#### **Bice Auto LLC**



Owner

## **Estimate**

Est # 401 ID # 11184401

Collision & Towing 2661 State Hwy 2 Mount Ayr, IA 50854 Business Phone: (641) 464-2152 biceauto2661@yahoo.com

Vehicle Info 2018 Chevrolet -1500 Silverado W/T DNR JOSH RUSK 3GCUKNEH0JG312484 Body Type: 4 Door Crew Cab 144 Engine: 4.3L 6 Cyl Gas Injected Drive Type: 4WD

**Insurance Company** Inspection Date: 10/07/2021

		Oper	Description		Part Number	Price	Labor
	FR	ONT BUMPER					
1		Replace	FRT BUMPER IMPACT BAR	(	GM1002869	\$692.00	Included
							2.1 hrs. Paint panel
			0.8 hrs. Clearcoat				0.8 hrs. Refinish
2		Overhaul	O/H BUMPER ASSY (INCLUDES R&I) (FRT BUMPER ASSY)				3.1 hrs. Body
3		Replace	R FRT BUMPER BRACKET		GM1063113C	\$76.00	Included
4		Replace	R FRT OTR BUMPER BRACKET		GM1063115C	\$59.00	Included
5		Replace	R FRT OTR BUMPER FILLER	(	GM1089183	\$50.00	0.1 hrs. Body
6		Replace	FRT LWR BUMPER FASCIA	0	GM1015135C	\$419.00	Included
7		Replace	FRT BUMPER LICENSE PLATE BRACKET	0	GM1068172	\$42.00	Included
8	+	S2 Replace	L FRT BUMPER BRACKET		84029775	\$89.95	Included
9	+	S2 Replace	L FRT OTR BUMPER BRACKET		84029797	\$69.37	Included
10	+	S2 Replace	L FRT INR BUMPER BRACKET		22757263	\$43.25	0.2 hrs. Body
11	+	S2 Replace	R FRT INR BUMPER BRACKET		22757264	\$43.25	0.2 hrs. Body
	GR	RILLE					
12	+	S1	R&I GRILLE ASSY				0.4 hrs. Body
13		Replace	INR GRILLE		GM1223112C	\$65.00	0.6 hrs. Body
14		Replace	GRILLE ASSEMBLY		ORDER FROM DEALER	\$753.45	0.6 hrs. Body
15	+	S2 Replace	GRILLE ADHESIVE EMBLEM		22786809	\$84.67	0.2 hrs. Body
	FR	ONT LAMPS					
16		R&I	RIGHT R&I COMBINATION LAMP ASSY (R FRONT COMBINATION LAMP)				0.7 hrs. Body
17		Check/Adjust	AIM LAMPS (HEADLAMPS)				0.4 hrs. Body
18	+	S1 R&I	LEFT R&I COMBINATION LAMP ASSY (L FRONT COMBINATION LAMP)				0.7 hrs. Body
19		Replace	R FRT COMBINATION LAMP ASSEMBLY	0	GM2503452R	\$1,275.00	0.7 hrs. Body
	CO	OLING					
20		S2 Replace	COOLING RADIATOR MOUNTING PANEL		23461838	\$422.53	2.8 hrs. Body
21		S2 Replace	COOLING RADIATOR SHUTTER		84363184	\$334.18	0.8 hrs. Body
	OTI	HER					
22	+	S2 Replace	######################################				

Customer: DNR JOSH RUSK Estimate #: 401

## **Totals**

Туре	Labor Time	Cost	Total Taxable
Body Labor	11.1	\$60.00	\$666.00
Paint Labor	2.9	\$60.00	\$174.00
Paint Supplies	2.9	\$42.00	\$121.80
Aftermarket Parts			\$2,678.00
OEM Parts			\$1,840.65
Nontaxable Amount	- W		\$5,480.45
Grand Total			\$5,480.45

Customer: DNR JOSH RUSK Estimate #: 401

### **Supplement Version 2**

		Oper	Description	Part Number	Price	Labor
FR	TNO	BUMPER				
8	+	Replace	L FRT BUMPER BRACKET	84029775	\$89.95	Included
9	+	Replace	L FRT OTR BUMPER BRACKET	84029797	\$69.37	Included
10	+	Replace	L FRT INR BUMPER BRACKET	22757263	\$43.25	0.2 hrs. Body
11	+	Replace	R FRT INR BUMPER BRACKET	22757264	\$43.25	0.2 hrs. Body
GR	ILLE					
15	+	Replace	GRILLE ADHESIVE EMBLEM	22786809	\$84.67	0.2 hrs. Body
CO	OLIN	IG				
20	-	Replace	COOLING RADIATOR MOUNTING PANEL		\$359.00	2.8 hrs. Body
20		Replace	COOLING RADIATOR MOUNTING PANEL	23461838	\$422.53	2.8 hrs. Body
21	-	Replace	COOLING RADIATOR SHUTTER	84363184	\$334.18	0.8 hrs. Body
21		Replace	COOLING RADIATOR SHUTTER	84363184	\$334.18	0.8 hrs. Body
OTH	IER					
22	+	Replace	######################################			

# **Supplement Totals**

Туре	Labor Time	Cost	Total Taxable
Body Labor	0.6	\$60.00	\$36.00
Aftermarket Parts	0.0		(\$359.00)
OEM Parts	0.0		\$753.02
Nontaxable Amount			\$430.02
Grand Total			\$430.02

## Cumulative Effects of Supplement(s)

Estimate	\$4,099.25
Supplement 1	\$951.18
Supplement 2	\$430.02
Total	\$5,480,45