OFFICE OF AUDITOR OF STATE





Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

June 27, 2025

Kristi Onstot Executive Council L O C A L

Subject: Damage to Vehicle #106244 Due to a Fallen Tree on February 28, 2025

Department of Administrative Services

Claim dated March 4, 2025

AOS Claim ID: 4006

The Department's request included a supplemental allocation request of \$101.85 because additional damages were identified. We recommend Executive Council approval of the supplemental allocation of \$101.85, which increases the allocation to \$7,881.43. In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to this loss. We have found the items to be in order as shown below:

Documented request		\$ 7,881.43
Executive Council allocation (Revised)		\$ 7,881.43
Less: Previous payments This payment Total	0.00 7,881.43	\$ 7,881.43
Remaining Executive Council allocation	on	\$ 0.00

We recommend that reimbursement be made in the amount of \$7,881.43. This represents <u>full</u> and <u>final</u> payment on this allocation.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Por RAS

CC: Adam Steen, Director, Department of Administrative Services

Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services



KIM REYNOLDS, GOVERNOR CHRIS COURNOYER, LT. GOVERNOR

ADAM STEEN, DIRECTOR

Date: April 29, 2025

Tammy Hollingsworth, Auditor of State To:

Victoria Newton, Treasurer of State

Executive Council

From: Ryan Betts, DAS Fleet Risk Manager

DAS Fleet Services

Department of Administrative Services

Re: REIMBURSEMENT REQUEST - 29C20 Claim

AOS Claim #	4006
Vehicle / Event	#106244 / Damaged by fallen tree
Event Date	February 28, 2025
Summary	Vehicle 106244 damaged by a fallen tree (Claim 301534)
Amount Requested	\$7,881.43 Total

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: 0665-005-5790-0657. If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts

DAS Fleet Risk Manager

ryan.betts1@iowa.gov

515-281-8008















世出

Cancel

* Required fields

88

♦ ★ ♠♦

Warrants

Warrant Information

Fiscal Year 2025

Vendor Customer 00002112221

\$7,881.43 Amount

Line Number

Last Updated 73539970

Warrant Number

04/02/2025 08:08 PM

Issue Information

04/02/2025 12:00 AM Issued

Void 9 N

> Duplicate 8 N

Line Amount \$2,947.50

Comments

Stop

Transaction Line Number

RISK00525092003

Transaction ID

9 N

Redeemed Information

















Redeemed Bank	Redeemed Department		Dept Object	Dept Revenue -	Sub Unit	Sub Revenue Source	BSA .
Batch Number -	Redeemed Fund		Object 2715	Sub Object	Unit 5790	Revenue Source	Revenue Source Class
Redeemed -	Sequence Number	< COA	Fund 0665	Sub Fund	Department 005	Object Class	Appropriation 0000 Sub BSA - Show More

fin-2024.FS3-PRD.1

© CGI Inc.

CGI Advantage

About | Privacy | Important Links | Accessibility



WITHAM COLLISION CENTER

Workfile ID: Federal ID:

b257c2c5 42-1060951

FORD-CHEVROLET-VW-KIA 2033 LAPORTE RD, WATERLOO, IA 50702 Phone: (319) 234-4200

Final Bill

RO Number: 16006936

Customer:

Insurance:

Adjuster:

Estimator:

Branden Frederick

State of Iowa

Creative Risk

Phone:

Create Date:

3/4/2025

Claim:

APDSOI0301534-00

Loss Date:

(319) 292-2353

Deductible:

2024 CHEV Malibu LS 4D SED 4-1.5L Turbocharged Gasoline Direct Injection

VIN:

IΑ

1G1ZB5ST7RF251204

Interior Color:

Mileage In:

Vehicle Out:

License: State:

Exterior Color: Production Date: Mileage Out: Condition:

Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		FRONT BUMPER & GRILLE						
2	E01	Repair	Bumper cover w/o auto park				1.0	Body	3.3
3	E01		Add for Clear Coat						1.3
4	E01	Overhaul	O/H bumper assy			OEM	3.5	Body	
5	E01	Remove/Install	Lower cover				0.0	Body	
6	E01	Remove/Install	Lower deflector				0.0	Body	
7	E01	Remove/Install	License bracket				0.2	Body	
8	E01	Remove/Install	Lower grille w/o chrome				0.0	Body	
9	E01		FRONT LAMPS						
10	E01	Remove/Install	RT Headlamp assy				0.3	Body	
11	E01	Remove/Install	LT Headlamp assy				0.3	Body	
12	E01		HOOD						
13	E01	Repair	Hood				6.0	Body	2.8
14	E01		Add for Clear Coat						
15	E01	Remove/Install	Insulator				0.3	Body	
16	E01	Remove/Install	R&I hood assy				0.8	Body	
17	E01		ROOF						
18	E01	Repair	Roof panel				4.0	Body	3.4
19	E01		Overlap Major Non-Adj. Panel						(0.2)
20	E01		Add for Clear Coat						
21	E01	Remove/Install	R&I headliner				2.9	Body	
22	E01		PILLARS, ROCKER & FLOOR						
23	E01	Blend	RT roof rail and rocker						3.6
24	E01	Remove/Replace	RT Protector	1	12.72	OEM	0.2	Body	
25	E01	Repair	LT Uniside assy				2.0	Body	3.6
26	E01		Overlap Major Adj. Panel						(0.4)

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 16006936

2024 CHEV Malibu LS 4D SED 4-1.5L Turbocharged Gasoline Direct Injection

27	E01		Add for Clear Coat						
27	E01								0.2
28	E01	D /D	feather block and prime		0.20	OFM	0.3	D - d -	0.3
29	E01	Remove/Replace	LT Protector	1	9.29	OEM	0.2	Body	
30	E01	Damas a /Damlasa	FRONT DOOR		205.00	OEM	0.5	Dadu	
31	S01	Remove/Replace	LT Mirror assy w/o heated w/o object warng	1	395.00	OEM	0.5	Body	
32	S01	Remove/Replace	LT Mirror cover paint to match	1	88.32	OEM	0.2	Body	0.5
33	E01		Overlap Minor Panel						(0.2)
34	E01		Add for Clear Coat						
35	E01	Repair	LT Door shell				2.0	Body	2.0
36	E01		Overlap Major Adj. Panel						(0.4)
37	E01		Add for Clear Coat						
38	E01		feather block prime						0.4
39	E01	Remove/Install	LT Belt molding				0.3	Body	
40	E01	Remove/Replace	LT Nameplate "MALIBU" chrome	1	66.75	OEM	0.2	Body	
41	E01	Remove/Install	LT Handle, outside w/o chrome				0.4	Body	
42	E01	Remove/Install	LT R&I trim panel				0.6	Body	
43	E01		REAR DOOR						
44	E01	Blend	RT Door shell						1.0
45	E01	Remove/Install	RT Belt molding				0.3	Body	
46	E01	Remove/Install	RT Handle, outside w/o chrome				0.4	Body	
47	E01	Remove/Install	RT R&I trim panel				0.5	Body	
48	E01		QUARTER PANEL						
49	E01	Remove/Install	RT Wheelhouse liner				0.4	Body	
50	E01	Repair	RT Quarter panel				2.0	Body	2.7
51	E01		Overlap Major Adj. Panel						(0.4)
52	E01		Add for Clear Coat						
53	E01		feather block prime						0.5
54	E01	Remove/Install	RT Quarter glass GM				1.6	Body	
55	S01	Blend	LT Quarter panel						1.4
56	S01	Remove/Install	LT Wheelhouse liner				0.4	Body	
57	S01	Remove/Install	LT Quarter glass GM				1.6	Body	
58	E01		TRUNK LID						
59	E01	Repair	Trunk lid w/o spoiler				1.5	Body	2.4
60	E01		Overlap Major Adj. Panel						(0.4)
61	E01		Add for Clear Coat						2.5
62	E01		feather block prime						0.3
63	E01	Remove/Replace	Nameplate "MALIBU" Silver	1	39.13	OEM	0.2	Body	
64	E01	Remove/Replace	Emblem gold	1	67.60	OEM	0.2	Body	
65	E01		REAR LAMPS						
66	E01	Remove/Install	RT Tail lamp assy				0.4	Body	
67	E01	Remove/Install	RT Backup lamp assy				0.3	Body	
68	E01	Remove/Install	LT Backup lamp assy				0.3	Body	
69	S01	Remove/Install	LT Tail lamp assy				0.4	Body	
70	E01		REAR BUMPER						

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 16006936

2024 CHEV Malibu LS 4D SED 4-1.5L Turbocharged Gasoline Direct Injection

71	E01	Remove/Install	R&I bumper cover				1.8 Body
72	E01		MISCELLANEOUS OPERATIONS				
73	E01		Hazardous waste removal	1	3.00	Other	
74	E01	Remove/Replace	Flex Additive	1	5.00	Other	
75	E01		Corrosion protection	1	5.00	Other	0.1 Body
76	E01		Pre Scan				1.0 Mech
77	E01		Post Scan				1.0 Mech
78	E01		Lift Reveal B/G				0.5 Body
79	E01		Lift Reveal w/s				0.5 Body

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts	(67.88)				620.93
Labor, Body			75.00	39.3	2,947.50
Labor, Refinish			135.00	30.0	4,050.00
Labor, Mechanical			130.00	2.0	260.00
Miscellaneous					3.00
Subtotal				*	7,881.43
Sales Tax					0.00
Grand Total					7,881.43
Net Total					7,881.43

Estimate Version	Total \$
Original	7,442.08
Supplement S01	439.35
Insurance Total \$:	7,881.43
Received from Insurance \$:	0.00
Balance due from Insurance \$:	7,881.43
Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

3/31/2025 8:32:37 AM

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

OF OF STATE OF OF OF STATE OF OF STATE OF STATE

OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

April 28, 2025

Kristi Onstot Executive Council L O C A L

Subject: Damage to Vehicle #106244 Due to a Fallen Tree on February 28, 2025

Department of Administrative Services

Claim dated March 4, 2025

AOS Claim ID: 4006

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$7,779.58, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Phi RAS

CC: Adam Steen, Director, Department of Administrative Services

Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services

Heather Hackbarth, Department of Management