

MEMBERS OF COUNCIL

HON. KIM REYNOLDS  
GOVERNOR

HON. PAUL D. PATE  
SECRETARY OF STATE

HON. ROB SAND  
AUDITOR OF STATE

HON. ROBY SMITH  
TREASURER OF STATE

HON. MIKE NAIG  
SECRETARY OF AGRICULTURE



## Executive Council of Iowa

CAPITOL BUILDING  
DES MOINES, IOWA 50319  
PHONE: 515 281-5368  
FAX: 515 281-7562

July 20, 2026

Accounting Department  
Office of the Treasurer  
Lucas Building  
321 E 12<sup>th</sup> Street  
Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for a supplemental emergency allocation in the amount of \$2,803.50, which brings the total allocation to \$19,900.57. On April 2, 2026, Vehicle #482 was damaged by hail. Request was to cover repair costs.

This represents full and final payment, and this allocation closed.

EXECUTIVE COUNCIL OF IOWA

A handwritten signature in cursive script that reads "Kristi Onstot".

Kristi Onstot  
Executive Secretary

cc: Kyle Wear, DAS Fleet Chief Financial Officer  
Ryan Betts, Fleet Services Risk Program Manager  
Matt Bender, Department of Management  
Heather Hackbarth, Department of Management



**OFFICE OF AUDITOR OF STATE**  
**STATE OF IOWA**

State Capitol Building  
Des Moines, Iowa 50319-0006  
Telephone (515) 281-5834

Rob Sand  
Auditor of State

July 8, 2026

Kristi Onstot  
Executive Council

Subject: Hail Damage to Vehicle #482 on April 2, 2026  
Department of Administrative Services  
Claim dated April 13, 2026  
AOS Claim ID: 4291

The Department's request included a supplemental allocation request of \$2,803.50 because additional damages were identified. We recommend Executive Council approval of the supplemental allocation of \$2,803.50, which increases the allocation to \$19,900.57. In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to the above-mentioned damage and have found the items to be in order as shown below:

|                                        |                  |                     |
|----------------------------------------|------------------|---------------------|
| Documented Payment Request             |                  | <u>\$ 19,900.57</u> |
| Executive Council Allocation (Revised) |                  | \$ 19,900.57        |
| Less:                                  |                  |                     |
| Previous payments                      | \$ 0.00          |                     |
| Current payment                        | <u>19,900.57</u> |                     |
| Total                                  |                  | <u>\$ 19,900.57</u> |
| Remaining Executive Council Allocation |                  | <u>\$ 0.00</u>      |

We recommend reimbursement be made in the amount of \$19,900.57. This represents full and final payment of the loss.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA  
Deputy Auditor of State

cc: Kyle Wear, Fleet Services CFO, Department of Administrative Services  
Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services



Department of  
Administrative Services

KIM REYNOLDS, GOVERNOR  
CHRIS COURNOYER, LT. GOVERNOR

MARK CAMPBELL, DIRECTOR

Date: June 18, 2026

To: Tammy Hollingsworth, Auditor of State  
Victoria Newton, Treasurer of State  
Executive Council


From: Ryan Betts, DAS Fleet Risk Manager  
DAS Fleet Services  
Department of Administrative Services

**Re: REIMBURSEMENT REQUEST - 29C20 Claim**

|                  |                                                  |
|------------------|--------------------------------------------------|
| AOS Claim #      | 4291                                             |
| Vehicle / Event  | #482 / Hail                                      |
| Event Date       | April 2, 2026                                    |
| Summary          | Vehicle 482 sustained hail damage (Claim 336484) |
| Amount Requested | <b>\$19,900.57 TOTAL</b>                         |

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: **0665-005-5790-0657**. If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,



Ryan Betts  
DAS Fleet Risk Manager  
[ryan.betts1@iowa.gov](mailto:ryan.betts1@iowa.gov)  
515-281-8008

Filters

Bank Account

External Disbursement ID

Disbursement Type

Transaction Code

Check / EFT

External Issue Date

Record Date

Transaction Dept

Issue Date

Status

Transaction ID

Apply

Reset

Grid Actions

1 - 1 of 1 Records

View per Page - 20 50 100

| Bank Account | Check / EFT     | Issue Date | Status | Record Date | Amount      | Transaction Code | Transaction Dept | Transaction ID       | Disbursement Type |
|--------------|-----------------|------------|--------|-------------|-------------|------------------|------------------|----------------------|-------------------|
| 0100         | 000002000997608 | 06/08/2026 | Paid   | 06/08/2026  | \$19,900.57 | EFT              | 005              | ADC06082600000853855 | EFT               |



# COPELAND AUTO BODY, INC.

Workfile ID:

7750e381

estimates@copelandautobody.com  
506 E 2nd St, P.O. Box 109, Hedrick, IA 52563  
Phone: (641) 653-2140  
FAX: (641) 653-4301

## Final Bill

### RO Number: 22295

|                      |               |             |              |                 |
|----------------------|---------------|-------------|--------------|-----------------|
| Customer:            | Insurance:    | Adjuster:   | Estimator:   | Brandon Petrehn |
| State Of Iowa        | Creative Risk | Phone:      | Create Date: | 4/13/2026       |
| 301 E 7th St         |               | Claim:      | 336484       |                 |
| Des Moines, IA 50319 |               | Loss Date:  | 4/2/2026     |                 |
| (319) 385-8715       |               | Deductible: |              |                 |

2023 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection Sterling Gray Metall

|                        |                                      |                    |                       |
|------------------------|--------------------------------------|--------------------|-----------------------|
| VIN: 1GNSKLED7PR409402 | Interior Color: Jet Black            | Mileage In: 60,371 | Vehicle Out: 6/1/2026 |
| License: 482           | Exterior Color: Sterling Gray Metall | Mileage Out:       |                       |
| State: IA              | Production Date: 6/2023              | Condition:         | Job #: Level 4        |

| Line | Ver | Operation      | Description                          | Qty | Extended Price \$ | Part Type | Labor | Type | Paint |
|------|-----|----------------|--------------------------------------|-----|-------------------|-----------|-------|------|-------|
| 1    | E01 |                | <b>FRONT BUMPER &amp; GRILLE</b>     |     |                   |           |       |      |       |
| 2    | S01 | Remove/Install | Push Bumper                          |     |                   |           | 2.5   | Body |       |
| 3    | E01 | Remove/Install | R&I bumper cover                     |     |                   |           | 1.7   | Body |       |
| 4    | E01 |                | <b>FRONT LAMPS</b>                   |     |                   |           |       |      |       |
| 5    | E01 | Remove/Install | RT Headlamp assy                     |     |                   |           | 0.5   | Body |       |
| 6    | E01 | Remove/Install | LT Headlamp assy                     |     |                   |           | 0.5   | Body |       |
| 7    | E01 |                | <b>HOOD</b>                          |     |                   |           |       |      |       |
| 8    | E01 | Remove/Replace | Hood (ALU)                           | 1   | 1,009.00          | A/M       | 1.5   | Body | 3.2   |
| 9    | E01 |                | Add for Clear Coat                   |     |                   |           |       |      | 1.3   |
| 10   | E01 |                | Add for Underside(Complete)          |     |                   |           |       |      | 1.6   |
| 11   | E01 |                | Add for Clear Coat                   |     |                   |           |       |      | 0.3   |
| 12   | S01 | Remove/Replace | Seam Seal underside of hood          |     |                   |           | 1.0   | Body |       |
| 13   | E01 |                | <b>FENDER</b>                        |     |                   |           |       |      |       |
| 14   | E01 | PDR            | RT Fender                            | 1   | 150.00            | Other     |       |      |       |
| 15   | E01 | PDR            | LT Fender                            | 1   | 575.00            | Other     |       |      |       |
| 16   | E01 | PDR            | Oversize Dent(s) 1.5-2.5 9 @ \$50 EA | 1   | 450.00            | Other     |       |      |       |
| 17   | E01 | Remove/Install | RT Fender liner w/o Z71, Police, SSV |     |                   |           | 0.3   | Body |       |
| 18   | E01 | Remove/Install | LT Fender liner w/o Z71, Police, SSV |     |                   |           | 0.3   | Body |       |
| 19   | E01 | Blend          | RT Fender                            |     |                   |           |       |      | 1.1   |
| 20   | E01 | Blend          | LT Fender                            |     |                   |           |       |      | 1.1   |
| 21   | S01 | Remove/Replace | RT "STATE TROOPER" decal             |     |                   |           | 0.3   | Body |       |
| 22   | S01 | Remove/Replace | LT "STATE TROOPER" decal             |     |                   |           | 0.3   | Body |       |
| 23   | E01 |                | <b>ELECTRICAL</b>                    |     |                   |           |       |      |       |
| 24   | E01 | Remove/Install | Antenna assy w/sat radio             |     |                   |           | 0.3   | Body |       |
| 25   | E01 |                | <b>COWL</b>                          |     |                   |           |       |      |       |
| 26   | E01 | Remove/Replace | Cowl grille Tahoe                    | 1   | 176.44            | OEM       | 0.5   | Body |       |

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

6/3/2026 9:41:21 AM

Page 1

# Final Bill

## RO Number: 22295

2023 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection Sterling Gray Metall

|    |     |                |                                                         |   |          |       |      |      |       |
|----|-----|----------------|---------------------------------------------------------|---|----------|-------|------|------|-------|
| 27 | E01 |                | <b>ROOF</b>                                             |   |          |       |      |      |       |
| 28 | E01 | Remove/Replace | Roof panel w/o luggage rails                            | 1 | 1,306.41 | OEM   | 22.0 | Body | 5.4   |
| 29 | E01 |                | Overlap Major Non-Adj. Panel                            |   |          |       |      |      | (0.2) |
| 30 | E01 |                | Add for Clear Coat                                      |   |          |       |      |      | 1.0   |
| 31 | S01 | Repair         | Map, Drill & Debur 7 Antenna Holes                      |   |          |       | 5.0  | Body |       |
| 32 | S01 | Repair         | Time to Seal 7 Antenna Holes                            |   |          |       | 1.5  | Body |       |
| 33 | S01 | Remove/Install | Wiring for Rear 3 Wi-Fi, Label & Protect Plugs          |   |          |       | 3.5  | Body |       |
| 34 | S01 | Remove/Install | Wiring for Center 3 Wi-Fi, Label & Protect Plugs        |   |          |       | 3.0  | Body |       |
| 35 | S01 | Remove/Install | Light Bar Wiring, Label & Protect Plugs                 |   |          |       | 2.0  | Body |       |
| 36 | S01 | Repair         | Clean & Re-Tape Rear 2 Antennas                         |   |          |       | 2.0  | Body |       |
| 37 | S01 | Remove/Install | Hatch Wiring for All Accessories, Label & Protect Plugs |   |          |       | 2.0  | Body |       |
| 38 | S01 | Remove/Install | Front Facing Radar, Camera and Mounts                   |   |          |       | 1.5  | Body |       |
| 39 | S01 | Remove/Install | Rear Facing Radar, Camera and Mounts                    |   |          |       | 1.5  | Body |       |
| 40 | E01 |                | Car Cover                                               | 1 | 10.00    | Other | 0.5  | Body |       |
| 41 | E01 |                | Urethane glass kit                                      | 1 | 25.00    | A/M   |      |      |       |
| 42 | E01 | Remove/Replace | RT Roof molding w/o luggage rack                        | 1 | 88.49    | OEM   | 0.0  | Body |       |
| 43 | E01 | Remove/Replace | LT Roof molding w/o luggage rack                        | 1 | 88.49    | OEM   | 0.0  | Body |       |
| 44 | E01 | Remove/Install | Light bar                                               |   |          |       | 1.0  | Body |       |
| 45 | S01 | Remove/Replace | LT CB antenna                                           |   |          |       | 0.3  | Body |       |
| 46 | E01 | Remove/Install | Center antenna                                          |   |          |       | 0.3  | Body |       |
| 47 | E01 | Remove/Install | RT CB antenna                                           |   |          |       | 0.3  | Body |       |
| 48 | E01 | PDR            | RT Roof Rail Half Dollar 16-30                          | 1 | 525.00   | Other |      |      |       |
| 49 | E01 | PDR            | Oversize Dent(s) 1.5-2.5 6 @ \$50 EA                    | 1 | 300.00   | Other |      |      |       |
| 50 | S01 |                | <b>INSTRUMENT PANEL</b>                                 |   |          |       |      |      |       |
| 51 | S01 | Repair         | Wrap/Protect Inst cluster & Dash                        |   |          |       | 0.5  | Body |       |
| 52 | S01 |                | <b>CONSOLE</b>                                          |   |          |       |      |      |       |
| 53 | S01 | Repair         | Wrap/Protect Center Console Stack                       |   |          |       | 0.5  | Body |       |
| 54 | E01 |                | <b>SEATS &amp; TRACKS</b>                               |   |          |       |      |      |       |
| 55 | E01 | Remove/Install | RT R&I front seat                                       |   |          |       | 0.5  | Body |       |
| 56 | E01 | Remove/Install | LT R&I front seat                                       |   |          |       | 0.5  | Body |       |
| 57 | E01 | Remove/Install | R&I second row seat bench                               |   |          |       | 0.4  | Body |       |
| 58 | E01 | Remove/Install | RT R&I second row seat bucket                           |   |          |       | 0.4  | Body |       |
| 59 | S01 | Repair         | Wrap & Protect Modules & Wiring under Driver's seat     |   |          |       | 0.5  | Body |       |
| 60 | E01 |                | <b>PILLARS, ROCKER &amp; FLOOR</b>                      |   |          |       |      |      |       |
| 61 | E01 | Remove/Install | LT Frt rocker mldg w/o pwr assist step                  |   |          |       | 0.8  | Body |       |
| 62 | E01 | Remove/Install | LT Rear rocker mldg w/o pwr assist step                 |   |          |       | 0.0  | Body |       |
| 63 | S01 | Section        | LT Uniside assy quarter panel cut roof rl & rocker      | 1 | 936.00   | OEM   | 12.0 | Body | 3.5   |
| 64 | S01 |                | Overlap Major Adj. Panel                                |   |          |       |      |      | (0.4) |
| 65 | S01 |                | Add for Clear Coat                                      |   |          |       |      |      | 0.6   |
| 66 | S01 | Repair         | RT Uniside assy                                         |   |          |       | 0.5  | Body |       |
| 67 | E01 |                | <b>FRONT DOOR</b>                                       |   |          |       |      |      |       |

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

# Final Bill

## RO Number: 22295

2023 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection Sterling Gray Metall

|     |     |                |                                                           |   |        |       |          |
|-----|-----|----------------|-----------------------------------------------------------|---|--------|-------|----------|
| 68  | E01 | PDR            | LT Outer panel                                            | 1 | 575.00 | Other |          |
| 69  | E01 | PDR            | Oversize Dent(s) 1.5-2.5 9 @ \$50 EA                      | 1 | 450.00 | Other |          |
| 70  | E01 | Remove/Replace | LT Belt molding chrome                                    | 1 | 76.05  | OEM   | 0.3 Body |
| 71  | S01 | Remove/Replace | LT Upper molding black                                    | 1 | 139.65 | OEM   | 0.2 Body |
| 72  | E01 | Remove/Install | LT R&I door assy                                          |   |        |       | 1.2 Body |
| 73  | E01 | Remove/Replace | LT "IOWA STATE PATROL" decal                              |   |        |       |          |
| 74  | S01 | Remove/Install | LT Handle, outside w/o chrome                             |   |        |       | 0.4 Body |
| 75  | E01 | Remove/Install | LT R&I trim panel                                         |   |        |       | 0.4 Body |
| 76  | E01 | Remove/Install | LT Door glass GM Tahoe                                    |   |        |       | 0.5 Body |
| 77  | E01 | Remove/Install | LT R&I mirror                                             |   |        |       | 0.4 Body |
| 78  | S01 | Remove/Replace | State of Iowa Shield Decal                                |   |        |       | 0.6 Body |
| 79  | E01 |                | <b>REAR DOOR</b>                                          |   |        |       |          |
| 80  | E01 | PDR            | LT Outer panel                                            | 1 | 450.00 | Other |          |
| 81  | E01 | PDR            | Oversize Dent(s) 1.5-2.5 10 @ \$50 EA                     | 1 | 500.00 | Other |          |
| 82  | E01 | Remove/Replace | LT Belt molding chrome                                    | 1 | 50.70  | OEM   | 0.3 Body |
| 83  | E01 | Remove/Install | LT R&I door assy                                          |   |        |       | 1.2 Body |
| 84  | S01 | Remove/Replace | LT Upper molding black                                    | 1 | 84.96  | OEM   | 0.2 Body |
| 85  | E01 | Remove/Install | LT R&I trim panel                                         |   |        |       | 0.4 Body |
| 86  | E01 | Remove/Install | LT Door glass GM w/privacy tint                           |   |        |       | 0.5 Body |
| 87  | E01 | Remove/Replace | RT Belt molding chrome                                    | 1 | 50.70  | OEM   | 0.3 Body |
| 88  | S01 | Remove/Install | LT Handle, outside w/o chrome                             |   |        |       | 0.4 Body |
| 89  | E01 |                | <b>QUARTER PANEL</b>                                      |   |        |       |          |
| 90  | E01 | PDR            | RT Quarter panel                                          | 1 | 200.00 | Other |          |
| 91  | E01 | PDR            | Oversize Dent(s) 1.5-2.5 2 @ \$50 EA                      | 1 | 100.00 | Other |          |
| 92  | E01 | Remove/Replace | LT Qtr glass GM, w/o glass breakage sensor w/privacy tint | 1 | 349.28 | Glass | 0.0 Body |
| 93  | E01 |                | Urethane glass kit                                        | 1 | 25.00  | A/M   |          |
| 94  | E01 | Remove/Install | Fuel door                                                 |   |        |       | 0.3 Body |
| 95  | E01 | Remove/Install | LT Wheelhouse liner                                       |   |        |       | 0.3 Body |
| 96  | S01 | Remove/Replace | LT Front molding chrome                                   | 1 | 162.97 | OEM   | 0.2 Body |
| 97  | E01 | Remove/Install | LT Rear molding                                           |   |        |       | 0.4 Body |
| 98  | E01 | Remove/Install | LT Upper molding chrome                                   |   |        |       | 0.2 Body |
| 99  | E01 | Remove/Install | LT Lower trim panel                                       |   |        |       | 0.7 Body |
| 100 | S01 | Remove/Install | RH Quarter Trim Strobe Light                              |   |        |       | 1.0 Body |
| 101 | S01 | Remove/Replace | LT Upper molding black                                    | 1 | 254.81 | OEM   | 0.2 Body |
| 102 | E01 |                | <b>LIFT GATE</b>                                          |   |        |       |          |
| 103 | E01 | PDR            | Lift Gate Quarter 6-15                                    | 1 | 325.00 | Other |          |
| 104 | E01 | PDR            | Oversize Dent(s) 1.5-2.5 1 @ \$50 EA                      | 1 | 50.00  | Other |          |
| 105 | E01 | Remove/Install | R&I liftgate assy                                         |   |        |       | 1.4 Body |
| 106 | E01 | Remove/Install | Lower trim panel manual lift gate black                   |   |        |       | 0.6 Body |
| 107 | S01 | Remove/Install | Disassemble Hatch Light Bar to Disconnect Internal Wiring |   |        |       | 1.0 Body |
| 108 | E01 |                | <b>REAR LAMPS</b>                                         |   |        |       |          |
| 109 | E01 | Remove/Install | RT Tail lamp                                              |   |        |       | 0.4 Body |
| 110 | E01 | Remove/Install | LT Tail lamp                                              |   |        |       | 0.4 Body |

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

# Final Bill

## RO Number: 22295

2023 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection Sterling Gray Metall

|     |     |                |                                 |   |         |       |      |     |
|-----|-----|----------------|---------------------------------|---|---------|-------|------|-----|
| 111 | E01 |                | <b>REAR BUMPER</b>              |   |         |       |      |     |
| 112 | E01 | Remove/Install | R&I bumper cover                |   |         | 1.1   | Body |     |
| 113 | S01 | Remove/Install | LT Guide bracket                |   |         | 0.1   | Body |     |
| 114 | S01 | Remove/Replace | LT Guide bracket rivet          | 6 | 9.00    | OEM   |      |     |
| 115 | S01 |                | <b>RESTRAINT SYSTEMS</b>        |   |         |       |      |     |
| 116 | S01 | Remove/Install | RT Head air bag                 |   |         | 0.6   | Mech |     |
| 117 | S01 | Remove/Install | LT Head air bag                 |   |         | 0.6   | Mech |     |
| 118 | E01 |                | <b>VEHICLE DIAGNOSTICS</b>      |   |         |       |      |     |
| 119 | E01 | Repair         | Pre-repair scan                 |   |         | 0.5   | Mech |     |
| 120 | E01 | Repair         | Post-repair scan                |   |         | 0.5   | Mech |     |
| 121 | E01 |                | <b>MISCELLANEOUS OPERATIONS</b> |   |         |       |      |     |
| 122 | E01 |                | Hazardous Waste                 | 1 | 4.00    | Other |      |     |
| 123 | E01 |                | Corrosion Protection            | 1 | 30.00   | Other |      |     |
| 124 | E01 |                | Adjustment for State            | 1 | (49.28) | Other |      |     |
| 125 | S01 | Repair         | Feather edge prime and block    |   |         |       |      | 1.5 |
| 126 | S01 | Repair         | Disc/Recon Batteries 3X         |   |         | 0.5   | Body |     |
| 127 | S01 |                | Disarm airbags                  |   |         | 0.5   | Body |     |

| Estimate Totals    | Discount \$ | Markup \$ | Rate \$ | Total Hours | Total \$         |
|--------------------|-------------|-----------|---------|-------------|------------------|
| Parts              |             |           |         |             | 4,733.67         |
| Labor, Body        |             |           | 78.00   | 89.3        | 6,965.40         |
| Labor, Refinish    |             |           | 145.00  | 20.0        | 2,900.00         |
| Labor, Mechanical  |             |           | 100.00  | 2.2         | 220.00           |
| Miscellaneous      |             | 337.50    |         |             | 5,081.50         |
| <b>Subtotal</b>    |             |           |         |             | <b>19,900.57</b> |
| Sales Tax          |             |           |         |             | 0.00             |
| <b>Grand Total</b> |             |           |         |             | <b>19,900.57</b> |
| <b>Net Total</b>   |             |           |         |             | <b>19,900.57</b> |

| Estimate Version | Total \$  |
|------------------|-----------|
| Original         | 17,047.79 |
| Supplement S01   | 2,852.78  |

|                                |           |
|--------------------------------|-----------|
| Insurance Total \$:            | 19,900.57 |
| Received from Insurance \$:    | 0.00      |
| Balance due from Insurance \$: | 19,900.57 |
| Customer Total \$:             | 0.00      |
| Received from Customer \$:     | 0.00      |
| Balance due from Customer \$:  | 0.00      |

ATTENTION: WHEELS NEED TO BE RE-TORQUED WITHIN 100 MILES. FAILURE TO DO SO MAY RESULT IN FURTHER DAMAGE!

Warranty Disclosure: All Warranty will include our Workmanship, including neccessary refinishing for as long as the you, the customer, own the vehicle. Guarenting corrective repairs will be provided at no additional cost. Warranty and workmanship gusrantee may NOT include items such as normal wear

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

## Final Bill

---

### RO Number: 22295


2023 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection Sterling Gray Metall

and tear, prior damage, new damage or negligence.

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

6/3/2026 9:41:21 AM

Page 5



**OFFICE OF AUDITOR OF STATE**  
STATE OF IOWA

State Capitol Building  
Des Moines, Iowa 50319-0006  
Telephone (515) 281-5834

Rob Sand  
Auditor of State

May 8, 2026

Kristi Onstot  
Executive Council

Subject: Hail Damage to Vehicle #482 on April 2, 2026  
Department of Administrative Services  
Claim dated April 13, 2026  
AOS Claim ID: 4291

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damaged incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$17,097.07, subject to an audit of actual invoices.

Sincerely,

A handwritten signature in black ink, appearing to read "Brian R. Brustkern".

Brian R. Brustkern, CPA  
Deputy Auditor of State

cc: Kyle Wear, Fleet Services CFO, Department of Administrative Services  
Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services  
Heather Hackbarth, Department of Management