

Newton, Victoria [TOS]

From: Pierce Richard <pierce@dps.state.ia.us>
Sent: Tuesday, June 9, 2020 1:42 PM
To: ExecutiveCouncil [TOS]; DAS.Risk@iowa.gov; Tammy.Hollingsworth@auditor.state.ia.us
Subject: 6-5-20 Trp. Kyle Kluender #367 SVD - Hail Damage 29C20
Attachments: Damage to patrol car; P1000011.JPG; P1000010.JPG; P1000009.JPG; State Vehicle Damage Report.Form.doc; Carlson Auto Body Estimate for 367's 19 CHARGER.pdf; 6-4-20 Trp. Kyle Kluender #367 SUV - Hail damage 29C20 notification; 6-5-20 Trp. Kyle Kluender #367 SVD - Hail Damage.doc

Executive Council & Tammy

Attached is Trp. Kyle Kluender's (#367) state vehicle damage report, photos, initial 29C20 notification, and estimate regarding the hail damage that occurred to his patrol car on 6-5-20 (*Please note the date change from the initial report of 6-4-20*). The estimate is \$4,413.64 which exceeds the \$2K threshold to qualify for 29C20 funds. The ISP wishes to pursue 29C20 Funding for this AON event.

Thank you for your consideration.

Lt. Pierce

From: Niles Wesley <niles@dps.state.ia.us>
Sent: Tuesday, June 9, 2020 8:34 AM
To: DAS.Risk@iowa.gov
Cc: post7sup <post7sup@dps.state.ia.us>; Pierce Richard <pierce@dps.state.ia.us>; Adams Jeannie <jadams@dps.state.ia.us>; Hansen Robert <rhansen@dps.state.ia.us>
Subject: Act of Nature Vehicle Damage Report- Trooper Kluender's hail damage to patrol car

All, this is the State Vehicle Damage Report for Trooper Kluender's hail damage that occurred On June 5th while his car was parked at his residence.

Sgt. Niles

Newton, Victoria [TOS]

From: Kluender Kyle <krkluend@dps.state.ia.us>
Sent: Monday, June 8, 2020 8:08 AM
To: Miller Mark; Niles Wesley; Smidt Aaron; Morenz Neil
Subject: Damage to patrol car

Lt. Miller:

On June 5th, 2020 between 03:30 and 04:00 Humboldt County had a storm go thru town with quarter to ping pong ball size hail. My patrol car was parked at my residence and received damage due to the hail.

Senior Trooper Kyle R. Kluender ★ 367 ★

District #7

2437 235th Street

Fort Dodge, IA 50501

515-972-4213 - Office

515-972-4218 - Fax

krkluend@dps.state.ia.us

Iowa Department of Public Safety



-NOTICE* This e-mail message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this e-mail by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this e-mail or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient



State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: **DPS – Vehicle Damage; DAS – Risk**

- One Repair Estimate from Approved State Bid Shop
- DOT MARS Report (if reportable)
- Memo from the Driver of the State Vehicle
- 3-4 photos of the vehicle damage

*****Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!**

STATE VEHICLE: (Mark if Act of Nature ☒) CASE #: 2020013686

Date: <small>(Month/Day/Year)</small>	06/05/2020	Time: <small>(Time plus a.m./p.m.)</small>	3:00 a.m.
Vehicle Plate #:	367	Vehicle Mileage:	5,927
Vehicle Description: <small>(Yr/Make/Model/ & Vin#)</small>	2019/Dodge/Charger Police/2C3CDXKT8KH755353		
Assigned To:	Trp. Kluender	Badge #	367
Driven By:	not driven	Badge #	
Driver's Lic #:	008AA2516	Damage:	\$4,413.64
Vehicle Towed: <small>(Yes / No)</small>	No	Towed By:	N/A
Towed To:	N/A	Towing Cost:	\$0.00
Seat Belt: <small>(Yes / No)</small>	No	Type of Vehicle: <small>(Marked/Semi /Unmarked)</small>	Marked
Injured/Injuries:	none		
Occupants: <small>(Other than driver)</small>	none		

VEHICLE #2:

DL #:	State:
Vehicle Lic. #	State:
Driver's Name:	
Driver's Address:	
Owner's Name:	
Owner's Address:	
Owner's Phone:	

Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	No
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

OTHER INFORMATION:

Witnesses:	none
Accident Location: (Street/Hwy)	Trooper's residence 1007 8 th Ave North, Humboldt, IA
County:	Humboldt
Weather/Road Conditions:	half dollar size hail and strong winds
Narrative: Trooper Kluender's patrol car was parked on the street at his residence. At approximately 3:00 am, on June 5 th , it received hail damage with high winds.	
Property Damage other than Vehicles:	none
Cost:	\$0.00
Citations Issued To: (List Charge(s) and Statute Code(s))	N/A

Investigating Officer:	Sgt. Niles
------------------------	------------

VEHICLE #3: (If needed) (For more vehicles, please make extra copies of this portion)

DL #:		State:	
Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			

Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing Seat Belt: (Yes/No)	Yes		

Date: 6/ 8/2020 02:57 PM
 Estimate ID: 3289
 Estimate Version: 0
 Preliminary
 Profile ID: State of Iowa

Carlson Auto Body & Repair

540 High St, Rockwell City, IA 50579
 (712) 297-5517
 Fax: (712) 297-8106
 Email: carlsonauto@hotmail.com
 Tax ID: 27-0942183

Damage Assessed By: Weston Carlson
 Classification: None

Deductible: UNKNOWN

Owner: IOWA STATE PATROL

Mitchell Service: 911667

Description: 2019 Dodge Charger Police
 Body Style: 4D Sed
 VIN: 2C3CDXKT8KH755353
 Mileage: 6,112
 OEM/ALT: O

Drive Train: 5.7L Inj 8 Cyl 5A AWD

Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	100374	BDY	REMOVE/INSTALL	Frnt Bumper Cover			2.0 #
2	900500	BDY *	REMOVE/INSTALL	Bumper Guard	Existing		1.0* r
3	100559	BDY	REMOVE/REPLACE	Hood Panel (Alum)	68265445AB	1,065.00	1.6
4	AUTO	REF	REFINISH	Hood Outside			C 2.8
5	AUTO	REF	REFINISH	Add For Hood Underside			C 1.4
6	100002	REF	BLEND	R Fender Outside			C 0.8
7	100379	REF	BLEND	L Fender Outside			C 0.8*
8	101043	BDY	PAINTLESS REPAIR	L Fender Panel	Sublet	110.00	* 0.0* #
9	102049	BDY	REMOVE/INSTALL	R Rocker Moulding			0.4
10	102050	BDY	REMOVE/INSTALL	L Rocker Moulding			0.4
11	900500	BDY *	ADD'L LABOR OP	Remove Fender Stickers & Adhesive	Existing		0.8*
12	101425	BDY	PAINTLESS REPAIR	L Frt Door Shell (Steel/HSS)	Sublet	137.50	* 0.0* #
13	100731	BDY	PAINTLESS REPAIR	L Rear Door Shell (Steel/HSS)	Sublet	137.50	* 0.0* #
14	101694	BDY	PAINTLESS REPAIR	Roof Panel	Sublet	600.00	* 0.0*
15	900500	BDY *	PAINTLESS REPAIR	R Rail	Sublet	180.00	* 0.0*
16	101699	BDY	REMOVE/INSTALL	Roof Headliner			4.4 #
17	100290	BDY	PAINTLESS REPAIR	R Quarter Outer Panel	Sublet	125.00	* 0.0* #
18	100291	BDY	PAINTLESS REPAIR	L Quarter Outer Panel	Sublet	110.00	* 0.0* #
19	101795	BDY	REMOVE/INSTALL	Luggage Lid Assy			0.5
20	101797	BDY	REMOVE/INSTALL	Luggage Trim Panel			0.3
21	103148	BDY	PAINTLESS REPAIR	Luggage Lid Panel	Sublet	325.00	* 0.0*
22	100462	BDY	REMOVE/INSTALL	R Rear Combination Lamp			0.6 #
23	100463	BDY	REMOVE/INSTALL	L Rear Combination Lamp			0.6 #
24	AUTO	REF	ADD'L OPR	Clear Coat			2.1
25	933018	REF	ADD'L OPR	Mask For Overspray		10.00	*
26	AUTO		ADD'L COST	Paint/Materials		319.40	*
27	AUTO		ADD'L COST	Hazardous Waste Disposal		5.00	*

ESTIMATE RECALL NUMBER: 06/08/2020 14:57:13 3289
 Mitchell Data Version: OEM: APR_20_V

Copyright (C) 1994 - 2020 Mitchell International
 All Rights Reserved

Software Version: 7.1.238

Page 1 of 2

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc
r - CEG R&R Time Used For This Labor Operation

Estimate Totals

		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals			Amount
I.	Labor Subtotals						II.	Part Replacement Summary	
	Body	12.6	62.89	0.00	1,725.00	2,517.41 T		Taxable Parts	1,065.00
	Refinish	7.9	62.89	10.00	0.00	506.83 T		Total Replacement Parts Amount	1,065.00
	Taxable Labor					3,024.24			
	Labor Summary	20.5				3,024.24			
III.	Additional Costs					Amount	IV.	Adjustments	Amount
	Taxable Costs					324.40		Customer Responsibility	0.00
	Total Additional Costs					324.40			
	Paint Material Method: Rates								
	Init Rate = 40.43 , Init Max Hours = 99.9, Addl Rate = 0.00								
							I.	Total Labor:	3,024.24
							II.	Total Replacement Parts:	1,065.00
							III.	Total Additional Costs:	324.40
								Gross Total:	4,413.64
							IV.	Total Adjustments:	0.00
								Net Total:	4,413.64

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.