OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

September 22, 2025

Kristi Onstot Executive Council L O C A L

Subject: Hail Damages to Vehicle #37 and #904 on April 17, 2025

Department of Administrative Services

Claims dated April 22, 2025 and April 30, 2025

AOS Claim ID: 4039

The Department's request included a supplemental allocation request of \$120.45 because additional damages were identified. We recommend Executive Council approval of the supplemental allocation of \$120.45, which increases the allocation to \$9,980.76. In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to this loss. We have found the items to be in order as shown below:

Documented request			\$ 9,980.76
Executive Council allocation (Revi	\$ 9,980.76		
Less: Previous payments This payment Total	\$	0.00 9,980.76	\$ 9,980.76
Remaining Executive Council allo	cation		\$ 0.00

We recommend that reimbursement be made in the amount of \$9,980.76. This represents <u>full</u> and <u>final</u> payment on this allocation.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

BiRBS

cc: Kyle Wear, Fleet Services CFO, Department of Administrative Services Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services



KIM REYNOLDS, GOVERNOR CHRIS COURNOYER, LT. GOVERNOR

ADAM STEEN, DIRECTOR

Date: August 6, 2025

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Ryan Betts, DAS Fleet Risk Manager

DAS Fleet Services

Department of Administrative Services

Re: REIMBURSEMENT REQUEST - 29C20 Claim

AOS Claim #	4039
Vehicle / Event	#37 & #904 / Hail
Event Date	April 17, 2025
Summary	Vehicles 37 & 904 sustained hail damage (Claim 305061/305779)
Amount Requested	\$1,804.50 (vehicle 37) + \$8,176.26 (vehicle 904) \$9,980.76 TOTAL

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: 0665-005-5790-0657. If you have any questions or need additional information, please do not hesitate to contact me.


Thank you,

Ryan Betts

DAS Fleet Risk Manager

ryan.betts1@iowa.gov

515-281-8008



All Makes Collision Center

524 23rd Ave Council Bluffs, IA 51501 Phone (712) 256-3195

Name

Signature:

Invoice

Date:

No: 3071


Scheduled In Date: 4/23/2025 Completed Date: 4/25/2025 Service Rep: Kortnie Getzschman Page 1 PO No:

Insurance Information

state of iowa		Lic: VIN Mile	23 Chevrolet Tahoe Commercial 4 DR Wago Lic: Unit# VIN: 1GNSKLED9PR430946 Color: Mileage In: Mileage Out: Paint Code :			Claim No: Policy No: Date of Loss: Deductible: 0.0000		
Insurar	Insurance Company		ured		Adjuster	THE RESERVENCE OF THE PARTY OF		
Ext:			λim#3	305061		ı		
Туре	Description	Qty	Each	Amount Sa	ales Tax%	Sales Tax	Tota	
BL	Body Labor	4.4	55.00	242.00	7.00%	0.00	242.00	
NS	NonTaxable Sublet			1,562.50	0.00%	0.00	1,562.50	
ESTIM	ATE TOTALS			\$1,804.50		\$0.00	\$1,804.50	
Туре	Description	Qty	Each	Amount S	ales Tax%	Sales Tax	Tota	
BL	Body Labor	4.4	55.00	242.00	7.00%	0.00	242.0	
NS	NonTaxable Sublet			1,562.50	0.00%	0.00	1,562.5	
INVOIC	E TOTALS			\$1,804.50		\$0.00	\$1,804.50	

Service Item

©Copyright Solera inc. 2025. All rights reserved



Grid Actions	> su									
1 - 1 of 1 Records	sp				View per Page - 20 50 100	100				« < Page 1 of 1 >
П	Bank Account 🌲	Check / EFT ♦	Issue Date 🌲	Status 💠	Record Date 💠	Amount	Transaction Code	Amount Transaction Code Transaction Dept Transaction ID	Transaction ID	Disbursement Type
0080	0800	000001000178636 07/10/2025	07/10/2025	Paid	07/10/2025	\$8,176.26 AD	AD	005	ADC0710250000020955 Check	Check



Your Complete Auto Repair Center

111 INDIAN STREET, CHEROKEE, IA 51012 Phone: (712) 225-3877 FAX: (712) 225-3878

Final Bill

RO Number: 7629

Customer:

Insurance:

Adjuster:

Estimator:

Federal ID:

Rick Weaver

42-1468487

Iowa State Patrol

5116 IA-3

Phone: Claim:

Create Date:

4/21/2025

Cherokee, IA 51012

(712) 225-5119

IΑ

Loss Date: Deductible:

2024 RAM 2500 Tradesman Crew Cab 4WD w/6'4" Box 4D SHORT 6-6.7L Turbocharged Diesel Diesel Direct Injection

VIN:

3C6UR5CL7RG314738

Interior Color:

Mileage In: Mileage Out:

Vehicle Out:

5/13/2025

License: State:

Exterior Color: Production Date:

Condition:

Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		Wash PDR	1	30.00	Other	0.5	Body	
2	E01		Disconnect Battery & Disarm SRS				0.3	Mech	
3	E01		GRILLE						
4	E01	Remove/Install	Grille Tradesman matte black				0.5	Body	
5	E01		FRONT LAMPS						
6	E01	Remove/Install	LT R&I headlamp assy				0.4	Body	
7	E01	Remove/Install	RT R&I headlamp assy				0.4	Body	
8	E01		RADIATOR SUPPORT						
9	E01	Remove/Install	Sight shield				0.3	Body	
10	E01		HOOD						
11	E01	Remove/Replace	hood	1	919.03	LKQ	0.7	Body	3.3
12	E01		Add for Clear Coat						1.3
13	E01	Repair	Clean up used hood				1.5	Body	
14	E01	Remove/Install	RT Nameplate "2500" black				0.2	Body	
15	E01	Remove/Install	LT Nameplate "2500" black				0.2	Body	
16	S01	Remove/Replace	Front seal	1	90.45	OEM	0.4	Body	
17	E01		FENDER						
18	E01	PDR	LT Fender w/o flare (HSS) NOTE: PDR 5 half	1	125.00	Other			
19	E01	Blend	LT Fender w/o flare (HSS)						1.3
20	E01	Remove/Install	LT Fender liner				0.5	Body	
21	E01	PDR	RT Fender w/o flare (HSS) NOTE: PDR 2 half	1	125.00	Other			
22	E01	Blend	RT Fender w/o flare (HSS)						1.3
23	E01	Remove/Install	RT Fender liner				0.5	Body	
24	E01	Remove/Install	Nameplate w/o code M17				0.2	Body	
25	E01	Remove/Install	Nameplate w/code M17				0.2	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 7629

2024 RAM 2500 Tradesman Crew Cab 4WD w/6'4" Box 4D SHORT 6-6.7L Turbocharged Diesel Diesel Direct Injection

Clean and retape nameplates	0.5 Body	
Roof panel w/o roof lamps 1	0.5 Body	
Main		
Remove/Install R&I headliner RI Headliner RI Headliner retainer black Remove/Install LT Headliner retainer black Remove/Install LT Headliner retainer black Remove/Install Coverhead console w/LED, w/o sunroof Remove/Install RT W/S pillar trim black RT Remove/Install RT Rear pillar trim black RT Remove/Install RT Rear pillar trim black RT Remove/Install RT Rear pillar trim black REMOVE/Install REMOVE/Install LT Rear pillar trim black RT W/S pillar trim black REMOVE/Install LT W/S pillar trim black RT W/S pil		
Bot		
Second Remove/Install LT Headliner retainer black Second Remove/Install Overhead console w/LED, w/o sunroof Second Remove/Install RT W/S pillar trim black Second Remove/Install LT W/S pillar trim black Second Remove/Install RT Rear pillar trim black Second Remove/Install RT Rear pillar trim black Second Remove/Install LT W/S PDR 4 quarter, 6 half Second Second Remove/Install LT W/S PDR 4 half Second Remove/Install LT Door shell crew mega cab Second Remove/Install LT Rear mirror Second Remove/Install LT Rear mirror Second Remove/Install LT Rear mirror Second Remove/Install RT Rear mirror Remove/Install RT Rear mirror REAR DOOR Second Second REAR DOOR Second Second REAR DOOR Second Sec	3.6 Body	
Second Fig. Second Fig. Second Fig. Second Fig.	0.2 Body	
Second Remove/Install RT W/S pillar trim black Second Remove/Install LT W/S pillar trim black Second Remove/Install RT Upr ctr plr trim black Second Remove/Install RT Upr ctr plr trim black Second Remove/Install RT Rear pillar trim black Second Remove/Install LT Rear pillar trim black Second Remove/Install RT Second REAR DOOR Remove/Install RT Second REAR DOOR	0.2 Body	
Second Remove/Install RT Uy/S pillar trim black RT Upr. ctr. plr. trim black RT Rear pillar trim black RT Uniside panel RT NOTE: PDR 4 halif RT Rear pillar trim black RT NOTE: PDR 1 halif RT Rear pillar trim black RT Side panel w/o flares RT S	0.5 Body	
36 E01 Remove/Install RT Upr ctr plr trim black 37 E01 Remove/Install LT Upr ctr plr trim black 38 E01 Remove/Install RT Rear pillar trim black 39 E01 Remove/Install LT Rear pillar trim black 40 E01 PDR LT Uniside panel NOTE: PDR 4 quarter, 6 half 1 275.00 Other 41 E01 PDR RT Uniside panel NOTE: PDR 4 half 1 125.00 Other 42 E01 FRONT DOOR FRONT DOOR 1 125.00 Other 43 E01 PDR LT Door shell crew mega cab NOTE: PDR 1 half 1 125.00 Other 44 E01 Remove/Install LT Belt w'strip crew cab, mega cab W/black 1 125.00 Other 45 E01 Remove/Install RT R&I mirror RT R&I mirror 4 RT R&I mirror REAR DOOR Toor shell crew mega cab W/black 1 125.00 Other 49 E01 Remove/Install RT Belt w'strip black Toor she	0.0 Body	
37 E01 Remove/Install LT Upr ctr plr trim black 38 E01 Remove/Install RT Rear pillar trim black 39 E01 Remove/Install LT Rear pillar trim black 40 E01 PDR LT Uniside panel NOTE: PDR 4 blaff 1 275.00 Other Other Other Other Other POR 4 blaff 41 E01 PDR NOTE: PDR 4 blaff 1 125.00 Other Other Other Other POR 4 blaff 42 E01 FRONT DOOR FRONT DOOR 1 125.00 Other Other Other POR 4 blaff 44 E01 Remove/Install LT Rear mirror 1 125.00 Other Other Other Other Other POR 1 blaff 45 E01 PDR RT Door shell crew mega cab W/black 1 125.00 Other	0.0 Body	
38 E01 Remove/Install RT Rear pillar trim black 39 E01 Remove/Install LT Rear pillar trim black 40 E01 PDR LT Uniside panel NOTE: PDR 4 quarter, 6 half 1 275.00 Other Other Other Other 41 E01 PDR RT Uniside panel NOTE: PDR 4 half 1 125.00 Other Other Other Other Other 42 E01 FRONT DOOR 1 125.00 Other Othe	0.3 Body	
Bell Remove/Install LT Rear pillar trim black	0.3 Body	
More PDR LT Uniside panel NoTE: PDR 4 quarter, 6 half	0.0 Body	
NOTE: PDR 4 quarter, 6 half	0.0 Body	
NOTE: PDR 4 half		
Hermony Por Remove/Install LT Door shell crew mega cab NOTE: PDR 1 half Hermony Por Remove/Install LT R&I mirror Hermony Por Remove/Install LT Belt w'strip crew cab, mega cab w/black Hermony Por Remove/Install RT Door shell crew mega cab w/black Hermony Por Remove/Install RT R&I mirror Hermony Por Remove/Install RT R&I mirror Hermony Remove/Install RT R&I mirror Hermony Remove/Install RT Belt w'strip crew cab, mega cab w/black Hermony Por Remove/Install RT Belt w'strip crew cab, mega cab w/black Hermony Remove/Install RT Door shell NOTE: PDR 2 half Hermony Por Remove/Install LT Belt w'strip black Hermony Por Remove/Install LT Belt w'strip black Hermony Por Remove/Install LT Side panel w/o flares NOTE: PDR 4 quarter, 6 half Hermony Remove/Install RT Side panel w/o flares NOTE: PDR 2 half Hermony Remove/Install RT Side panel w/o flares NOTE: PDR 2 half Hermony Remove/Install RT Side panel w/o flares NOTE: PDR 2 half Hermony Remove/Install RT Side panel w/o flares NOTE: PDR 2 half Hermony Remove/Install RT Side panel w/o flares NOTE: PDR 2 half Hermony Remove/Install RT Side panel w/o flares NOTE: PDR 2 half		
NOTE: PDR 1 half 44 E01 Remove/Install LT R&I mirror 45 E01 Remove/Install LT Belt w'strip crew cab, mega cab w/black 46 E01 PDR RT Door shell crew mega cab NOTE: PDR 1 half 47 E01 Remove/Install RT R&I mirror 48 E01 Remove/Install RT Belt w'strip crew cab, mega cab w/black 49 E01 REAR DOOR 50 E01 PDR LT Door shell NOTE: PDR 2 half 51 E01 Remove/Install LT Belt w'strip black 52 E01 PICK UP BOX 53 E01 PDR RT Side panel w/o flares NOTE: PDR 4 quarter, 6 half 54 E01 Remove/Install RT Side panel w/o flares NOTE: PDR 2 half 55 E01 Remove/Install RT Side rail RT Side rail RT Side rail		
45 E01 Remove/Install LT Belt w'strip crew cab, mega cab w/black 46 E01 PDR RT Door shell crew mega cab NOTE: PDR 1 half 47 E01 Remove/Install RT R&I mirror 48 E01 Remove/Install RT Belt w'strip crew cab, mega cab w/black 49 E01 REAR DOOR 50 E01 PDR LT Door shell NOTE: PDR 2 half 51 E01 Remove/Install LT Belt w'strip black 52 E01 PDR LT Side panel w/o flares NOTE: PDR 4 quarter, 6 half 54 E01 Remove/Install RT Side panel w/o flares NOTE: PDR 2 half 85 E01 Remove/Install RT Side panel w/o flares NOTE: PDR 2 half 86 REMOVE/Install RT Side rail		
w/black46E01PDRRT Door shell crew mega cab NOTE: PDR 1 half1125.00Other47E01Remove/InstallRT R&I mirror48E01Remove/InstallRT Belt w'strip crew cab, mega cab w/black49E01REAR DOOR50E01PDRLT Door shell NOTE: PDR 2 half1125.00Other51E01Remove/InstallLT Belt w'strip black52E01PICK UP BOX53E01PDRLT Side panel w/o flares NOTE: PDR 4 quarter, 6 half1275.00Other54E01PDRRT Side panel w/o flares NOTE: PDR 2 half1125.00Other55E01Remove/InstallRT Side railRT Side rail	0.2 Body	
NOTE: PDR 1 half 47 E01 Remove/Install RT R&I mirror 48 E01 Remove/Install RT Belt w'strip crew cab, mega cab w/black 49 E01 REAR DOOR 50 E01 PDR LT Door shell NOTE: PDR 2 half 51 E01 Remove/Install LT Belt w'strip black 52 E01 PICK UP BOX 53 E01 PDR LT Side panel w/o flares NOTE: PDR 4 quarter, 6 half 54 E01 PDR REmove/Install RT Side panel w/o flares NOTE: PDR 2 half 87 Side panel w/o flares NOTE: PDR 2 half 88 RT Side panel w/o flares NOTE: PDR 2 half 89 RT Side panel w/o flares NOTE: PDR 2 half 80 RT Side panel w/o flares NOTE: PDR 2 half 80 REMOVE/Install RT Side rail	0.3 Body	
RT Belt w'strip crew cab, mega cab w/black REAR DOOR E01 PDR LT Door shell NOTE: PDR 2 half E01 Remove/Install LT Belt w'strip black PICK UP BOX E01 PDR LT Side panel w/o flares NOTE: PDR 4 quarter, 6 half RT Belt w'strip black REAR DOOR 1 125.00 Other 275.00 Other 1 275.00 Other RT Side panel w/o flares 1 125.00 Other NOTE: PDR 4 quarter, 6 half RT Side panel w/o flares 1 125.00 Other		
w/black 49 E01 REAR DOOR 50 E01 PDR LT Door shell NOTE: PDR 2 half 1 125.00 Other 51 E01 Remove/Install LT Belt w'strip black 52 E01 PICK UP BOX 53 E01 PDR LT Side panel w/o flares NOTE: PDR 4 quarter, 6 half 1 275.00 Other NOTE: PDR 4 quarter, 6 half 54 E01 PDR RT Side panel w/o flares NOTE: PDR 2 half 1 125.00 Other NOTE: PDR 2 half 55 E01 Remove/Install RT Side rail	0.2 Body	
50E01PDRLT Door shell NOTE: PDR 2 half1125.00Other Other NOTE: PDR 2 half51E01Remove/InstallLT Belt w'strip black52E01PICK UP BOX53E01PDRLT Side panel w/o flares NOTE: PDR 4 quarter, 6 half1275.00Other Other NOTE: PDR 2 half54E01PDRRT Side panel w/o flares NOTE: PDR 2 half1125.00Other NOTE: PDR 2 half55E01Remove/InstallRT Side rail	0.3 Body	
NOTE: PDR 2 half E01 Remove/Install LT Belt w'strip black FICK UP BOX E01 PDR LT Side panel w/o flares NOTE: PDR 4 quarter, 6 half RT Side panel w/o flares 1 125.00 Other NOTE: PDR 2 half RT Side panel w/o flares 1 125.00 Other NOTE: PDR 2 half RT Side rail		
52 E01 PICK UP BOX 53 E01 PDR LT Side panel w/o flares NOTE: PDR 4 quarter, 6 half 1 275.00 Other O		
E01 PDR LT Side panel w/o flares 1 275.00 Other NOTE: PDR 4 quarter, 6 half F1 PDR RT Side panel w/o flares 1 125.00 Other NOTE: PDR 2 half F2 E01 Remove/Install RT Side rail	0.3 Body	
NOTE: PDR 4 quarter, 6 half S4 E01 PDR RT Side panel w/o flares 1 125.00 Other NOTE: PDR 2 half S5 E01 Remove/Install RT Side rail		
NOTE: PDR 2 half 55 E01 Remove/Install RT Side rail		
	0.3 Body	
56 E01 Remove/Install LT Side rail	0.3 Body	
57 E01 Remove/Install Tonneau cover w/o Rambox	1.0 Body	
58 E01 REAR LAMPS		
59 E01 Remove/Install LT Tail lamp assy w/o blind spot w/o black	0.3 Body	
60 E01 Remove/Install RT Tail lamp assy w/o blind spot w/o black	0.3 Body	

7/8/2025 10:42:49 AM Page 2

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 7629

2024 RAM 2500 Tradesman Crew Cab 4WD w/6'4" Box 4D SHORT 6-6.7L Turbocharged Diesel Diesel Direct Injection

61	E01		VEHICLE DIAGNOSTICS				
62	E01		Connect Battery & Arm SRS				0.2 Mech
63	E01	Repair	Battery support during PRE/POST scans				0.2 Mech
64	E01		Memory function reset				0.2 Body
65	E01	Sublet	Pre-repair scan	1	120.00	Sublet	
66	E01	Sublet	Post-repair scan	1	120.00	Sublet	
67	E01	Remove/Replace	Corrosion Protection	11	110.00	Other	0.3 Body
68	E01	Remove/Replace	Cover Car Charge	1	10.00	Other	0.2 Body
69	E01	Remove/Replace	Hazardous Waste Charge	1	5.00	Other	
70	E01	Repair	De Nib and Polish (.5 per panel)				1.5
71	E01		pre delivery inspection/ detail	1	30.00	Other	0.5 Body
72	E01	Remove/Replace	Job cost materials	1	404.28	Other	

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					1,788.76
Sublet/Miscellaneous					240.00
Labor, Body			75.00	16.8	1,260.00
Labor, Refinish			135.00	8.7	1,174.50
Labor, Mechanical			90.00	0.7	63.00
Miscellaneous		500.00			3,650.00
Subtotal					8,176.26
Sales Tax					0.00
Grand Total					8,176.26
Net Total					8,176.26

Estimate Version	Total \$
Original	8,055.81
Supplement S01	120.45
Insurance Total \$:	0.00
Received from Insurance \$:	0.00
Balance due from Insurance \$:	0.00
Customer Total \$:	8,176.26
Received from Customer \$:	0.00
Balance due from Customer \$:	8,176.26

7/8/2025 10:42:49 AM

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

July 14, 2025

Kristi Onstot Executive Council L O C A L

Subject: Hail Damages to Vehicle #37 and #904 on April 17, 2025

Department of Administrative Services

Claims dated April 22, 2025 and April 30, 2025

AOS Claim ID: 4039

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damages incurred by the Department of Administrative Services are covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$9,860.31, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Phi RAS

cc: Adam Steen, Director, Department of Administrative Services

Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services

Heather Hackbarth, Department of Management