MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE

SEAL SEAL STATE OF 10 P.

Executive Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

January 9, 2024

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for a supplemental emergency allocation in the amount of \$1,168.61. This brings to total allocation to \$9,940.94. On June 7, 2023, Vehicle #105240 was damaged by a deer. Request was to cover repair costs.

This represents full and final payment and this allocation will be closed.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton

Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services

DAS Fleet Services, Risk

Matt Bender, Department of Management

OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004

Telephone (515) 281-5834 Facsimile (515) 281-6518

December 28, 2023

Victoria Newton Executive Council L O C A L

Subject: Deer Damage to Vehicle #105240 on June 7, 2023

Department of Administrative Services

Claim dated June 20, 2023

AOS Claim ID: 3570

The Department's request included a supplemental allocation request of \$1,168.61 because additional damages were identified. We recommend Executive Council approval of the supplemental allocation of \$1,168.61, which increases the allocation to \$9,940.94. In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to this loss. We have found the items to be in order as shown below:


Documented request	\$ 9,940.94
Executive Council allocation (Revised)	\$ 9,940.94
Less: Previous payments \$ 0.00 This payment 9,940.94 Total	\$ 9,940.94
Remaining Executive Council allocation	\$ 0.00

We recommend that reimbursement be made in the amount of \$9,940.94. This represents full and final payment on this allocation.

Sincerely,

Ernest H. Ruben, Jr., CPA Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services





Date: October 5, 2023

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Mariah Fucaloro, Fleet Manager

DAS Fleet Services

Department of Administrative Services

Re: REIMBURSEMENT REQUEST - 29C20 Claim

Claim #	3570
Vehicle / Event	105240/Deer
Event Date	June 7, 2023
Summary	Vehicle 105240 struck a deer. (258271)
Amount Requested	\$9,940.94 - Total

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: **0665-005-5790-0657**.

If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Mariah Fucaloro, Fleet Manager

DAS Fleet Services

Mariah.Fucaloro@iowa.gov

515-414-6582

Warrants

					Mer
Fiscal Year Warrant Number Lin	e Number Line Amount	Issued	Redeemed	Vendor Customer	
√ 2024 86021196	1 \$2,336.00	09/27/2023	10/02/2023	00003068762	
2024 86021196	2 \$225.00	09/27/2023	10/02/2023	00003068762	
2024 86021196	3 \$3,067.20	09/27/2023	10/02/2023	00003068762	
2024 86021196	4 \$4,312.74	09/27/2023	10/02/2023	00003068762	
First Prev Next Last	44,012,14	03/21/2020	10/02/2020	0000000702	
Search 🛷 🕽					
▼Warrant Information					
Fiscal Year : 2024	Amount: \$	9,940.94			
Warrant Number: 86021196	Vendor Customer : 0				
Line Number: 1	Last Updated: 1				
▼Issue Information	The second secon				
Issued: 09/27/2023		id :			
Document ID: RISK005242	51002 Duplica	te:			
Document Line Number: 1	Sto	p :			
Line Amount: \$2,336.00					
Comments :					
▼Redeemed Information	72.00				
Redeemed: 10/02/2023	Batch Nun	nber: 0992			
Redeemed Bank: 0022	Sequence Nun	ber: 00007			
Redeemed Fund: 0665					
Redeemed Department : 005					
Fund Accounting		***************************************		100.00	
Fund: 0665	Object :	2715	Dept Object	at:	
Sub Fund :	Sub Object :		Dept Revenue	e :	
Department: 005	Object Class:				
Unit: 5790	Revenue Source :				
Sub Unit :	Sub Revenue Source :				
Appropriation: 0000	Revenue Source Class :				
	BSA:				
	Sub BSA :				
Detail Accounting	1 2000	-			
Location :	Reporting:		Major Prog	jram :	
Sub Location :	Sub Reporting :			ıram :	
Activity :	Task:			nase :	
Sub Activity :	Sub Task :		Program Pe	riod :	
Function :	Task Order :				
Sub Function :					
on.					



AUTO TECH INC

Workfile ID: PartsShare: 11c3ada7 7pjtyB

Federal ID:

35-2432379

autotechinc@windstream.net 2015 20th Ave SE, Dyersville, IA 52040

Phone: (563) 875-2748 FAX: (563) 875-2889

Final Bill

RO Number: 3663

Customer:

Insurance:

Adjuster:

Estimator:

Levi Benn

State of Iowa

SELF PAY

Phone:

(877) 237-3727

Business

Create Date:

6/8/2023

PO Box 9207

Claim:

APDSOI0258271-00

Des Moines, IA 50306

(877) 544-7843 x5925

Loss Date:

Deductible:

2022 FORD Escape S AWD 4D UTV 3-1.5L Turbocharged Gasoline Port/Direct Injection

VIN:

1FMCU9F60NUB53412

Interior Color:

Mileage In:

5,125 Vehicle Out: 8/30/2023

License:

Exterior Color:

Mileage Out:

State:

IΑ

Production Date:

Condition:

Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		FRONT BUMPER & GRILLE						
2	E01	Remove/Install	R&I bumper cover				1.6	Body	
3	E01		FRONT LAMPS						
4	E01	Remove/Install	RT R&I headlamp assy				0.2	Body	
5	E01		HOOD						
6	E01	Repair	Hood				1.0	Body	2.8
7	S01		Add for Clear Coat						1.1
8	E01	Remove/Install	R&I hood assy				0.6	Body	
9	E01		FENDER						
10	S01	Remove/Replace	RT Fender	1	201.55	OEM	2.2	Body	2.2
11	S01		Overlap Major Adj. Panel						(0.4)
12	S01		Add for Clear Coat						0.4
13	S01		Add for Edging						0.5
14	S01		Add for Clear Coat						0.1
15	E01	Remove/Install	RT Wheel opng mldg black				0.0	Body	
16	E01	Remove/Install	RT Fender liner				0.0	Body	
17	S01	Remove/Replace	Molding Extension,Right	1	18.23	Other	0.1	Body	
18	E01		FRONT SUSPENSION						
19	E01	Remove/Replace	Wheel alignment align four wheels			OEM	2.0	Mech	
20	E01		WINDSHIELD						
21	E01	Remove/Install	Windshield FORD, w/o auto wiper w/o htd park area						
22	S01	Sublet	Remove & Save Windshield	1	105.00	Other			

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 3663

2022 FORD Escape S AWD 4D UTV 3-1.5L Turbocharged Gasoline Port/Direct Injection

23	S01		Reinstall Windshield	1	95.00	Other			
24	S01	Remove/Replace	Urethane Kit	1	42.85	Other			
25	E01	,	ROOF	-	,				
26	E01	Remove/Install	RT Roof molding				0.4	Body	
27	E01		PILLARS, ROCKER & FLOOR						
28	E01	Repair	RT Aperture panel				6.0	Body	4.2
29	E01		Overlap Major Adj. Panel					•	(0.4)
30	S01		Add for Clear Coat						0.8
31	E01	Refinish	Feather Edge Prime and Block						1.8
32	E01	Remove/Install	RT Rocker molding				0.5	Body	
33	E01	Remove/Install	RT Front sill plate				0.4	Body	
34	E01	Remove/Install	RT Lwr ctr plr trim				0.5	Body	
35	E01	Remove/Install	RT Rear sill plate				0.3	Body	
36	E01		FRONT DOOR						
37	E01	Remove/Replace	RT Door shell (HSS)	1	719.10	OEM	5.8	Body	3.2
38	E01		Overlap Major Adj. Panel						(0.4)
39	S01		Add for Clear Coat						0.6
40	E01	Remove/Replace	Seam Seal New Door	1	25.00	Other	1.0	Body	
41	E01	Remove/Replace	RT Mirror assy	1	757.95	OEM	0.0	Body	
42	E01	Remove/Replace	RT Belt molding black	1	88.33	OEM	0.0	Body	
43	E01	Remove/Replace	RT Mirror cover	1	134.10	OEM	0.0	Body	0.4
44	E01		Overlap Minor Panel						(0.2)
45	S01		Add for Clear Coat						0.1
46	E01	Remove/Replace	RT Door glass FORD w/o laminated	1	318.22	Glass	0.0	Body	
47	E01	Remove/Install	RT W'strip on body				0.3	Body	
48	E01	Remove/Install	RT Striker				0.2	Body	
49	S01	Remove/Replace	RT Side molding	1	126.62	OEM	0.3	Body	
50	S01	Remove/Replace	RT Applique retainer	4	15.00	OEM			
51	E01		REAR DOOR						
52	E01	Remove/Replace	RT Door shell (HSS)	1	599.10	OEM	5.0	Body	3.1
53	E01		Overlap Major Adj. Panel						(0.4)
54	S01		Add for Clear Coat						0.5
55	E01		Seam Seal New Door	1	25.00	Other	1.0	Body	
56	E01	Remove/Replace	RT Belt molding black	1	84.23	OEM		Body	
57	E01	Remove/Install	RT W'strip on body					Body	
58	E01	Remove/Install	RT Striker					Body	
59	S01	Remove/Replace	RT Side molding	1	98.43	OEM	0.3	9.757	
60	S01	Remove/Replace	RT Handle, outside black	1	42.03	OEM		Body	
61	S01	Remove/Replace	RT Cap	1	14.25	OEM	0.3	Body	
62	S01	Remove/Replace	RT Applique retainer	4	15.00	OEM			
63	E01		QUARTER PANEL						
64	E01	Repair	RT Quarter pnl assy				5.0	Body	2.7

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 3663

2022 FORD Escape S AWD 4D UTV 3-1.5L Turbocharged Gasoline Port/Direct Injection

65	E01		Overlap Major Adj. Panel						(0.4)
66	S01		Add for Clear Coat						0.5
67	E01		Clear Coat						2.5
68	E01	Refinish	Feather Edge Prime and Block						1.5
69	E01	Remove/Install	RT Wheelhouse liner				0.3	Body	
70	E01	Remove/Replace	RT Qtr glass FORD green tint	1	419.55	Glass			
71	S01	Sublet	Remove RT Qtr Glass	1	95.00	Other			
72	S01		Install RT Qtr Glass	1	95.00	Other			
73	S01	Remove/Replace	Urethane Kit	1	42.85	Other			
74	E01	Remove/Install	RT Lower qtr trim w/o woofer				0.5	Body	
75	E01	Remove/Install	RT Upper trim w/package tray				0.3	Body	
76	S01	Remove/Replace	RT Wheel opng mldg	1	117.35	OEM	0.3	Body	
77	E01		REAR LAMPS						
78	E01	Remove/Install	RT Tail lamp assy				0.3	Body	
79	E01		REAR BUMPER						
80	E01	Remove/Install	RT Side extn w/o auto park				0.4	Body	
81	E01		VEHICLE DIAGNOSTICS						
82	E01		Scan - Pre-Repair Diagnostic				0.5	Diag	
83	E01		Scan - Post-Repair Code Reset				0.5	Diag	
84	E01		MISCELLANEOUS OPERATIONS	7					
85	E01		Cover Car for Paint	1	5.00	Other	0.2	Body	
86	E01		Cover Car for Primer	1	5.00	Other	0.2	Body	
87	E01		Color Sand & Buff				0.3	Body	
88	E01		Corrosion Protection Primer	1	5.00	Other	0.1	Body	
89	E01	Sublet	Hazardous Waste Removal	1	3.00	Other			
90	E01		Additional Clear Coat					9-30	1.6

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts		1900			4,109.74
Sublet/Miscellaneous					203.00
Labor, Body			64.00	36.5	2,336.00
Labor, Diagnostic			75.00	1.0	75.00
Labor, Refinish			108.00	28.4	3,067.20
Labor, Mechanical			75.00	2.0	150.00
Subtotal	300 300				9,940.94
Sales Tax					0.00
Grand Total					9,940.94
Net Total					9,940.94

Estimate Version	Total \$
Original	8,772.33

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 3663

2022 FORD Escape S AWD 4D UTV 3-1.5L Turbocharged Gasoline Port/Direct Injection

Supplement S01		1,168.61
Insurance Total \$:		0.00
Received from Insurance \$:	•	0.00
Balance due from Insurance \$:		0.00
Customer Total \$:		9,940.94
Received from Customer \$:		0.00
Balance due from Customer \$:		9,940.94

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building Des Moines, Iowa 50319-0004

Telephone (515) 281-5834 Facsimile (515) 281-6518

September 25, 2023

Victoria Newton Executive Council L O C A L

Subject:

Deer Damage to Vehicle #105240 on June 7, 2023

Department of Administrative Services

Claim dated June 20, 2023

AOS Claim ID: 3570

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$8,772.33, subject to an audit of actual invoices.

Sincerely,

Ernest H. Ruben, Jr., CPA Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services Mariah Flowers, Fleet Services Manager, Department of Administrative Services Joel Lunde, Department of Management