



Speed and Innovation is Our WaterMark

August 15, 2024

Mr. Mark Mackey
Village of Kronenwetter
1582 Kronenwetter Dr
Kronenwetter, WI 54455

RE: 10" Pipe Spool Repair

Dear Mr. Mackey,

Thanks again for the opportunity to serve you and your community – very much appreciated. Earlier this week we inspected a leaking spool and have two options for repair: replace in-kind with ductile iron or custom build with type 304 stainless steel. We are pleased to estimate the following:

Ductile Iron

- Remove (1) full spool and (1) half ductile iron spool
- Provide (1) 10" x 18" full spool w/ 1" NPT tap, (1) 10" x 19" half spool and 10" wafer style gear operated butterfly valve
- Provide New gaskets and all labor complete

Estimated DI Spool Cost.....\$6491

Stainless Steel

- Apply for DNR approval
- Remove (1) full spool and (1) half ductile iron spool
- Provide (1) type 304 10" x 18" full spool w/ 1" NPT tap, (1) 10" x 19" half spool and 10" wafer style gear operated butterfly valve
- Provide NEW 10" Hymax transition fitting from DI to stainless steel
- Provide New gaskets and all labor complete

Estimated Stainless Steel Cost.....\$6912

Please let us know if you need any additional information and thank you for your continued patronage.

Respectfully,

Troy Simonar
CTW Corporation