WHITE'S INTL TRUCKS

Repair Management

7045 ALBERT PICK ROAD - GREENSBORO, NC 27409

Phone: (1) 800-6321050 - Fax: (1) 336-6689536 Estimate Number: 4907318 - RO Number: N/A





Currency: USD

Unit No: QUOTE

VIN: 3HAJTSKM1DL326126 Model: 4300M7 SBA 4X2

Engine: MAXXFORCE 7, 260 HP/2600 RPM GOV SPD

Make: International Delivered: 1/9/2015

In Service: 10 Years 7 Months

Mileage: 0 Eng Hrs: 0

Recall/AFC: No

Contact Name: QUOTE QUOTE

Position: service-primary

Phone:

E-Mail: NOEMAIL@NOEMAIL.COM

PO Number:

Operation Section A	Labor Cost	Parts Cost	Core Charge	Total Cost
Hydraulic Compact Unit (HCU) Pump - (FULL POWER BRAKES), Replace	\$1,170.00	\$4,500.26	\$0.00	\$5,670.26
(1) ELECTRONIC CONTROL UNIT, ABS, (WET) W/ ECU, SERVICE EXCHANGE, 8 COILS, 12V, W/O ATC, W/O BRACKETS, W/ RESERVOIR (DETACHED)				
Computer Hook Up - Fixed Cost	\$0.00	\$0.00	\$0.00	\$150.00
Bleed System (QUADRAULIC BRAKES), Perform	\$351.00	\$38.68	\$0.00	\$389.68
(4) FLUID, POWER STEERING, FLEETRITE 32OZ; TYPE: POWER STEERING FLUID				
Complaint: Not Available				
Cause: Not Available				
Correction: Not Available				

Operation Se	ection B	Labor Cost	Parts Cost	Core Charge	lotal Cost
Clutch Pedal Switch (CAB), Replace		\$117.00	\$204.09	\$0.00	\$321.09
(1) SWITCH, CLUTCH TRAVEL, HPB/SLS					
Aft Diag, Roadtest Snapshot And Data Analysis		\$195.00	\$0.00	\$0.00	\$195.00
Complaint:	Not Available				
Cause:	Not Available				
Correction:	Not Available				

Notes: [8/11/2025 1:57 PM] - Dealer: REPLACE HBP UNIT

Summary					
Parts:	\$4,743.03				
Core:	\$0.00				
Labor:	\$1,833.00				
Other Items:	\$150.00				
Shop:	\$100.00				
Тах:	\$460.76				
Haz. Waste:	\$16.01				
TOTAL:	\$7,302.80				

Generated by On Command Repair Management Copyright 2009-2025 Navistar Inc. All rights reserved. Printed On: 8/11/2025 2:14 PM (C)

Currency: USD Page: 1 of 1