



**BMW
MOTORCYCLES**

SOUTHEAST MICHIGAN

Estimate

Due: \$1,591.85

Doc Number: Estimate
Service Writer: M. Glinski - M250423
Date Printed: 09/26/2023
Date Promised: 09/26/2023

**CITY OF LATHRUP VILLAGE
27400 SOUTHFIELD ROAD
LATHRUP VILLAGE, MI 48076**

Customer Information

Home Phone: 248-557-3600
Email: policechief@lathrupvillage.

Pay Here

Summary

Approve	Decline	Unit	Job	Job Total
<input type="checkbox"/>	<input type="checkbox"/>	2008 BMW R1200RTP	Repair Leak at Counter Balance Seal	\$1,581.85

Job Subtotal: \$1,581.85

Misc: \$10.00

Job Parts Subtotal: \$81.85

Job Labor Subtotal: \$1,500.00

Tax: \$0.00

Total: \$1,591.85

Less Deposits: \$0.00

Total Due: \$1,591.85

Thank You For Your Business! This estimate is only an estimate. All prices are subject to change.

MICHIGAN REPAIR FACILITY# F170050

NO RETURNS ON ELECTRICAL PARTS!

Signature: _____

Detail

Unit **2008 BMW R1200RTP**

Color:

Keyboard:

VIN/Serial No:WB103880X8ZT12762

Plate:

Odom/Hrs In:25,267

Out:25,267

Repair Leak at Counter Balance Seal

Description:

Resolution: Estimate to split motorcycle / remove trans / replaced counter balance shaft seal

Parts

Part #	Qty	Description	Price	Discount	Total
11277686883	1.00	ISA SCREW:T99V00SM08	\$7.73	\$0.00	\$7.73
11117721848	1.00	SHAFT SEAL:T99D00TW	\$27.70	\$0.00	\$27.70
23127705086	1.00	SHAFT SEAL:T99D00TW	\$27.70	\$0.00	\$27.70
33177687623	1.00	CABLE TIE:T99V00K	\$2.64	\$0.00	\$2.64
21212332469	6.00	INNER HEX BOLT:T99V00SM06	\$2.68	\$0.00	\$16.08
Parts Subtotal					\$81.85

Labor

Description	Technician	Hours	Total
Remove / Replace Counter Balance Seal		10	\$1,500.00
Labor Subtotal			\$1,500.00
Job Subtotal			\$1,581.85
Approve: <input type="checkbox"/>			Decline: <input type="checkbox"/>

All Jobs Subtotal:	\$1,581.85
Shop Supplies:	\$10.00
Tax:	\$0.00
Total:	\$1,591.85
Less Deposits:	\$0.00
Total Due:	\$1,591.85