## CC&A **CONSTRUCTION CONSULTANTS & ASSOCIATES, INC.**

PROJECT : Snack Shack Café DATE: 3/12/2025 LOCATION: Madeira Beach, Florida PROJ #: 2025.113 PAGE : 1 OF 1

FILE NAME: SSC Budget

**DESCRIPTION** QTY. UNIT **UNIT COST** TOTAL **REMARKS** LIMITED STORM DAMAGE ASSESSMENT BUDGET Structural Repair Recommendations Scope of Work \$67.818 New Stainless Steel tiedowns at ext wd walls 90 ea 150.00 13,500 Replace WD Rim Beam 18 If 500.00 8,800 Reinforce WD Window Sub-Frames 500.00 15 ea 7,500 Reinforce WD Door Sub-Frames 2 ea 500.00 1,000 Replace Roof Sheathing at porch 750 sf 25.00 18,750 Replace 10% ext wall wd studs 250.00 3,493 14 ea Remove Timber siding 100% 2,280 sf 5.00 11,400 450 sf 7.50 3,375 Replace ext wall sheathing 25% \$28.560 **Electrical Repairs Recommendations Scope of Work** 19,040 Replace all branch circuit wiring 1,904 sf 10.00 Replace all receptacles 1,904 sf 5.00 9,520 Incoming Service - Remain as is Electrical Panels - Remain as is **Architectural Repairs Recommendations Scope of Work** \$264,163 **New Impact Windows** 435 sf 125.00 54,338 New Impact Door 6070 5,500.00 5,500 1 ea New Impact Door 3070 3,500.00 3.500 ea Replace gyp bd 4ft high 1.940 sf 15.00 29.100 Misc. gyp bd repairs due to water intrusion 1 ls 25,000.00 25.000 Replace tile floors & base 100% 2,094 sf 23.00 48,171 Replace metal roofing 100% 2,461 sf 20.00 49,220 Replace ext wall wd siding 100% 2,622 sf 15.00 39,330 2.50 Interior painting 1,904 sf 4,760 Exterior painting 2,622 sf 2.00 5,244 Sub-Total 360,540 **Contractor General Conditions** 15% 54,081 Contractor Insurance & Bonds 3% 12.439 **Estimate Contingency** 20% 85,412 **Escalation 12months** 5% 25,624 Permits - Allowance 1% 5,381 Contractor OH&P 6% 32,609

576,085

The above budget is very limited in scope and only includes the specific work as listed above.

All storm cleanup, exterior wood deck repairs, steps and railings are excluded.

Replacement of ext. canvas canopies is excluded.

**Probable Construction Repairs Budget** 

Repair/replacement of all termite damages are excluded

All interior repairs at the 2nd floor attic are excluded.