



AQUATIC COMMERCIAL SOLUTIONS, INC.

P.O. BOX 1233 • DRIPPING SPRINGS TX 78620
Phone; 210.381.3544

Rick Contreras
Aquatics Director
City of Mission

October 27, 2025

Below you will find the Buy Board Contract number and pricing information for Swimming Pool Chemicals, Supplies & Equipment. Due to market supply issues and other, below products may become unavailable in the specified sizes or product itself, if so, there may be an upcharge, for different sizes or if other manufactures/suppliers must be resourced. City will be notified of any upcharge changes, prior to ordering products. If actual products below have a price increase, the actual manufacture/supplier marginal increase will be added to the below pricing. A letter from manufacture/supplier can be supplied at that time. If you have any further questions, please do not hesitate to contact me.

Sincerely,

Joe York
Sales
Aquatic Commercial Solutions, Inc.
jeyorkiv@gmail.com
210.381.3544 Cell

Product & Description		Unit Cost	Ext. Cost
PULSAR BRIQUETTES, CAL HYPO,	50 LB. PAIL	\$ 4.36 Lb.	\$ 218.00 Ea.
PULSAR CAL HYPO GRAN,	50 LB. DRUM	\$ 4.18 Lb.	\$ 209.00 Ea.
PULSAR CAL HYPO GRAN,	100 LB. DRUM	\$ 3.25 Lb.	\$ 325.00 Ea.
PULSAR ISOCYANURIC ACID, (Stabilizer)	100 LB. DRUM	\$ 2.50 Lb.	\$ 250.00 Ea.
SODIUM BICARBONATE	50 LB. BAG	\$.99 Lb.	\$ 49.50 Ea.
HYDROCHLORIC ACID	4x1 Gal. Case	\$ 8.75 Gal.	\$ 35.00 Cs.
HYPOCHLORITE SOLUTION	4x1 Gal. Case	\$ 9.25 Gal.	\$ 37.00 Cs.
TRICHLOR 3" TABLETS	50 lb. pail	\$ 4.50 Lb.	\$ 225.00 Ea.

Water Management Upcharge per pound/gallon, may apply Per Gal/Pound \$0.50
EFS CHARGE: 6% of invoice total or a minimum charge of \$100.00,
If not available locally a delivery charge may apply.

Buy Board Contract: Swimming Pool Chemicals, Supplies&Equipment #701-23

Aquatic Commercial Solutions, Inc. Effective date: **6/01/2024**

P. O. Box 1233 Dripping Springs, TX. 78620 Expiration date: **5/31/2026**

Water Management Consist of Providing New Chemical Feeding Equipment Repair & Service of Supplied Equipment (any parts needed to repair may have an associated cost).