

Estimate

Date	Estimate #
12/19/2023	17802

Name / Address	Ship To
City of Needles 817 Third Street Needles, CA 92363	City of Needles 817 Third Street Needles, CA 92363

P.O. N	lo.	Terms	Terms Ship Via FOB		Rep			
		Net 30 Will Call			RPM Shop		ВВ	
Item		Description		(Qty	Price	Total	
	Repair of 1065274460V 3P Code: 06 Upon ins shorted to will fall to the manu The imperto be replexed to the code.	RE: Sewage Lift Station - W439197 Repair of Hydromatic model S12LXP4000FA, S/N 10652740, submersible solids handling pump, 40HP 460V 3PH 870RPM, 61FLA, 14.13" impeller, Date Code: 0620 Upon inspection our technician found that the stator was shorted to ground and needs to be replaced. This repair will fall under the extended warranty and be covered by the manufacturer. The impeller and wear ring were also damaged and need to be replaced. This damage is not covered under the extended warranty and will not be covered by the manufacturer.						
Shop 27973D003 27996A000 03718-300-1	repairs. STATOR SEAL-SI	oor to inspect, diagnose, 30-40HP, 870RPM 8P HAFT Silcar/Carbon Nit HAFT 3.0 TYPE2100 B	e, 230-460V/3PH trile		6.6667 1 1	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	
08565A026 07167-019-1	Hydroma	tic BEARING BALL N	.DEPT.#3309 3.93		1	0.00	0.00	

Notice: Due to a global spike in demand, combined with material and labor shortages, we are experiencing shipping delays with some of our manufactures. Any quoted lead times cannot be guaranteed.

Upon approval, sign at bottom and fax to 702-240-9319.
Estimate expires within 30 days from date shown above. Any alteration or deviation from above specifications, involving extra costs will be executed and become an extra charge over and above the Estimate.


Subtotal

Sales Tax (0.0%)

Total

J	ıuı	าล	ιu	ı	;.

Date:			



Estimate

Date	Estimate #
12/19/2023	17802

Name / Address	
City of Needles 817 Third Street Needles, CA 92363	

Ship To	
City of Needles 817 Third Street	
Needles, CA 92363	

P.O. No.		Terms	Ship Via		FOB		Rep
	Net 30		Will Call		R	LPM Shop	BB
Item		Description		(Qty	Price	Total
Shop		Labor to inspect, diagnose, and perform varranty repairs.			4	135.00	540.00
Cord cap rebuild		s needed to rebuild cord	cap (35FT, 6-4, 18-5)		1	436.74	436.74
25456E568		ER 14.25" S12LXP			1	5,438.80	5,438.80
25458D000	WEAR R	RING, S12L(X)P			1	916.80	916.80
Parts Income		as required			1	15.00	15.00
Supplies Income		Aisc. Supplies: Oil (13 Gallons), oil disposal, paint, ardware, connectors, etc.			1	635.00	635.00
Insulation Test	Motor insulation test, performed with Crown Model 2109 insulation tester, S/N 90014, 115V 60Hz 6A. Cal. 5-17-2021			1	0.00	0.00	
	Pentair H	January 1st, 2024. Repa	ncrease that is going into				

Notice: Due to a global spike in demand, combined with material and labor shortages, we are experiencing shipping delays with some of our manufactures. Any quoted lead times cannot be guaranteed.

Upon approval, sign at bottom and fax to 702-240-9319.
Estimate expires within 30 days from date shown above. Any alteration or deviation from above specifications, involving extra costs will be executed and become an extra charge over and above the Estimate.

Subtotal	\$7,982.34
Sales Tax (0.0%)	\$0.00
Total	\$7,982.34

Signature:	 	
Date:		