



Brown Bear Plumbing

401 Virginia Street
New Meadows, ID 83654

(208) 347-3271

kyla.cityclerk@newmeadowsidaho.us

ESTIMATE	#171
SERVICE DATE	Jun 22, 2023
TOTAL	\$904.00

CONTACT US

1420 W Washington St.
Boise, ID 83702

(208) 400-3359

support@bbpidaho.com

ESTIMATE

Services	amount
Service Kohler Sloan FlishMate Removed Tank and tightened all 3 bolts to seal gaskets to tank. Inspected tank to bowl gasket and applied Teflon paste to help seal. Tightened tank to bowl bolts down to keep tank from wobbling. Tightened bowl to flange bolts to resolve bowl rocking. Cleaned Sloan intake screen. Resealed water inlet to tank to resolve gasket leak. Removed and cleaned air intake "duck bill" and reset. Tested for function Installed new braided stainless steel supply line.	\$285.00
Kohler Sloan tank Install new Sloan Kohler replacement tank and tank to bowl gasket. 1 year parts and labor warranty	\$769.00
Services subtotal: \$1,054.00	
Subtotal	\$1,054.00
Non Repairable	-\$150.00
Total	\$904.00

Thank You For Choosing Brown Bear Plumbing For Your Service Needs.

After the repair was completed, we found that the Sloan canister is leaking at the tank to bowl connection. This is a non-repairable leak no matter what attempts were made. At this point each flush will release one droplet of water out the backside of the tank.

The other two causes of the leak have been repaired, but this is going to require replacement. We have a company found that it is much better to just order in a new tank when available rather than go through Sloan to get a replacement canister that way everything is new on the installation for approximately the same cost And is less labor intensive.





















