



**Express Auto Paint Customs**  
 1522 S. Robinson Ave.  
 Oklahoma City, OK 73109  
 Business Phone: (405) 905-0077  
 nannis59@yahoo.com

# Estimate

Est # 170  
 ID # 13807696

**Vehicle Info**

2014 Audi -A8 L Quattro  
 N005017  
 Body Type: 4 Door Sedan  
 Engine: 4.0L 8 Cyl Gas Injected  
 Turbocharged  
 Transmission: 8 Speed Auto Trans  
 Drive Type: AWD

**Owner**

José Valenciano  
 (405) 401-5802  
 L

**Insurance Company**

Inspection Date: 10/17/2023

**Shop Info**

Estimators Phone: (925) 917-0154

Oper	Description	Part Number	Price	Labor
<b>INFORMATION LABELS</b>				
1	Other	AIM DISTANCE SENSOR Final Charge per invoice		3 hrs. Mechanical
<b>FRONT BUMPER</b>				
2	Replace	FRT BUMPER COVER 4H0 807 065 E GRU 1.4 hrs. Clearcoat Includes R&I/R&R Grille & Front Fender Liners	\$1,573.33	Included 3.6 hrs. Paint panel 1.4 hrs. Refinish
3	R&R	ADD TO R&R OR O/H FRONT BUMPER COVER ASSY W/PARKING AID SENSORS (FRT ADD W/PARKI		0.7 hrs. Body
4	Overhaul	O/H FRONT BUMPER COVER ASSY (INCLUDES R&I) (FRT BUMPER COVER ASSY)		4.6 hrs. Body
5	Replace	FRT LWR BUMPER SPOILER 4H0 807 110	\$213.33	Included
6	Replace	FRT BUMPER AIR DEFLECTOR 4H0 807 611	\$371.67	Included
7	Replace	R FRT BUMPER GRILLE ORDER FROM DEALER	\$380.00	Included
8	Replace	R FRT BUMPER GUIDE 4H0 807 284 w/Front Bumper Cover Assy Removed	\$50.00	Included
9	Replace	FRT BUMPER IMPACT ABSORBER 4H0 807 694 C w/Front Bumper Cover Assy Removed		
10	Replace	FRT LWR BUMPER COVER 4H0 807 217 A 01C	\$65.00	Included
11	Replace	R FRT BUMPER BRACKET 4H0 807 140	\$18.00	
12	Replace	FRT PARKING SENSOR HARNESS 4H0 971 095 AF w/Front Bumper Cover Assy Removed, Not Included in O/H	\$386.15	
13	Replace	R FRT CRUISE CONTROL ADAPTIVE SENSOR -M 4H0 907 561 B w/Front Bumper Cover Assy Removed, Not Included in O/H, Does Not Include Aim and Calibrate Adaptive Cruise Control System	\$4,711.43	0.3 hrs. Mechanical
<b>FRONT LAMPS</b>				
14	Replace	R FRT COMBINATION LAMP ASSEMBLY 4H0 941 030 AF	\$2,723.33	0.8 hrs. Body
15	Check/Adjust	AIM LAMPS (HEADLAMPS)		0.4 hrs. Body
16	R&I	RIGHT R&I COMBINATION LAMP ASSY (R FRONT COMBINATION LAMP)		0.4 hrs. Body
17	Replace	R H/LAMP WASHER PRESSURE CYLINDER 4H0 955 102 D	\$195.00	Included

		R&R One Side Complete, w/Front Bumper Cover Removed, Included in R&R or O/H Front Bumper Cover Assy			
18	Replace	H/LAMP WASHER HOSE	4H0 955 970 D	\$118.33	
<b>FRONT FENDER</b>					
19	Replace	R FRT OTR FENDER PANEL EXTENSION	4H0 807 544	\$45.00	0.2 hrs. Body
		R&R One Side Complete			
20	Replace	R FENDER PANEL	4H0 821 106 B	\$1,136.67	2.2 hrs. Body 2 hrs. Paint panel 0.8 hrs. Refinish
		0.8 hrs. Clearcoat			
		w/Front Bumper Cover Assy, Combination Lamp Assy & Rocker Cover Removed, Includes R&R Rear Fender Liner, Right Side Includes R&I/R&R Washer Reservoir			
21	Replace	R FENDER FRONT LINER	4H0 821 172 L	\$230.00	0.3 hrs. Body
<b>FRONT DOOR</b>					
22	Refinish	R FRT DOOR SHELL			2.2 hrs. Paint panel 0.9 hrs. Refinish
		0.9 hrs. Clearcoat			
<b>SIDE BODY</b>					
23	R&I	RIGHT R&I ROCKER COVER (R ROCKER COVER)			0.6 hrs. Body
<b>OTHER</b>					
24	Other	PRE / POST REPAIR SCAN			1.5 hrs. Mechanical
25	Replace	COVER CAR FOR OVERSPRAY		\$5.00	0.3 hrs. Body
26	Refinish	COLOR SAND & BUFF per panel			1.5 hrs. Other

## Totals

Type	Labor Time	Cost	Total	Taxable
Body Labor	10.5	\$72.00	\$756.00	
Mechanical Labor	4.8	\$140.00	\$672.00	
Other Labor	1.5	\$48.00	\$72.00	
Paint Labor	10.9	\$72.00	\$784.80	
Paint Supplies	10.9	\$28.00	\$305.20	✓
OEM Parts			\$12,217.24	✓
Other Parts			\$5.00	✓
Taxable Amount			\$12,527.44	
Tax	8%		\$1,002.20	
Nontaxable Amount			\$2,284.80	
Grand Total			\$15,814.44	