City of Oelwein

Capital Improvement Program Detail Sheet



Department: Library

Project Title: Masonry Maintenance and Repair

Project Number: Karr Tuckpointing Project Start Date: 2025
GL Number: Completion Date: ongoing
Funding Source(s): General Fund Project Location: Oelwein Library

FY25	FY26	FY27	FY28	FY29	FY30	Total	
\$ 10,000.00	\$	-	\$ -		\$ 5,000.00	\$ 15,000.00	

Project Description: Masonry Maintenance and Repair

Efflorescence removal, powerwash surface dirt, tuckpoint damaged mortar joints, replace defective brick units, seal movement cracks, re-caulk. Allow \$15,000 - \$20,000 over a 10 year period.







Budget Approval

Amended

FY25 _____ FY26 ____ FY27 ____ FY28 ____ FY29____

City of Oelwein

Capital Improvement Program Detail Sheet



Department: Library

Project Title: Replace computers

Project Number: Premier Technology Project Start Date: 2025
GL Number: Completion Date: ongoing

Funding Source(s): General Fund Project Location: Oelwein Library

FY25	FY26	FY27	FY28	FY29	FY30	Total
	\$0	\$0	\$7,000	0	\$0	\$7,000

Project Description: Replace computers

Replace 6-9 computers on a rotational basis. Replace monitors as needed. Update switches and routers as needed.



Budget Approval

Amended

FY25 _____ FY26 ____ FY27 ___ FY28 ___ FY29 ___

City of Oelwein

Capital Improvement Program Detail Sheet



Depai	unent.	LIDIAIY	

Project Title: Roof Repair and Maintenance

Project Number: TectaTracker Project Start Date: 2024 GL Number: Completion Date: 2026

Funding Source(s): General Fund **Project Location: Oelwein Library**

FY25	FY26	FY27	FY28	FY29	FY30	Total
\$8,000	\$7,000	\$0	0	0		\$15,000

Project Description: Roof Repair and Maintence

FY24: Urgent repairs will be completed to prevent water intrusion. Repair step flashing along Gable, flash pillars, penetrating flashing, deteriorated roof decking. FY25:

Recommended repairs to additional flashing.

term performance repairs: Deteriorated valley tin.



Improperly installed step flashing along Gable wallImproperly installed step flashing along Gable wall



Section B - Deficiency #5 Poorly installed flashing



Section B - Deficiency #7 Roof decking corroded, deteriorated or Deteriorated valley tin deflected



FY26: Long-

Section B - Deficiency #3

Budget Approval

Amended

FY26 _____ FY27 ____ FY28 ____ FY29_ FY25 _____