# **ESTIMATE**

Diamond Doctors of Iowa, LLC 312 11th Ave Vinton, IA 52349-2336 diamonddoctorsiowa@gmail.com +1 (319) 283-0700 www.diamonddoctorsiowa.com



\$4,850.00

Bill to
Oelwein Youth Baseball
Oelwein Youth Baseball
19142 70th St
Oelwein, IA 50662

#### Estimate details

Estimate no.: 1050

Estimate date: 08/26/2025

#	Date	Product or service	Description	Qty	Rate	Amount
1.	08/25/2025	Skinned Infield Laser Grading - Regulation Field	Laser Grading - Field 3	1	\$1,500.00	\$1,500.00
2.	08/25/2025	Base Peg Alignment	Align bases - per set	2	\$75.00	\$150.00
3.	08/25/2025	Sod Removal	Sod removal to extend infield	1	\$500.00	\$500.00
4.	08/25/2025	Infield Mix Spreading	Spread new infield material on infield - per ton of material - fields will need 51 tons min	51	\$10.00	\$510.00
5.	08/25/2025	Home Plate Installation	Install new Champro Home Plate - per field	1	\$150.00	\$150.00
6.	08/25/2025	Materials	Infield Mix - Wendling Quarries - 51 tons/3 loads	51	\$40.00	\$2,040.00

Total

### Note to customer

### **ESTIMATE**

Diamond Doctors of Iowa, LLC 312 11th Ave Vinton, IA 52349-2336 diamonddoctorsiowa@gmail.com +1 (319) 283-0700 www.diamonddoctorsiowa.com



Bill to

Oelwein Youth Baseball Oelwein Youth Baseball 19142 70th St Oelwein, IA 50662

### Estimate details

Estimate no.: 1051

Estimate date: 09/02/2025

#	Date	Product or service	Description	Qty	Rate	Amount
1.	08/25/2025	Box Blade Leveling	Level playing field - non laser	2	\$750.00	\$1,500.00
2.	08/25/2025	Base Peg Alignment	realign base pegs	4	\$75.00	\$300.00
3.	08/25/2025	Infield Edging	Edge infield/outfield transition	2	\$150.00	\$300.00
4.	08/25/2025	Infield Mix Spreading	Spread new infield material on infield - per ton of material	68	\$10.00	\$680.00
5.	08/25/2025	Materials	Infield Mix	68	\$40.00	\$2,720.00
6.	08/25/2025	Bases	2nd/3rd bases	1	\$115.00	\$115.00
7.	08/25/2025	Double First Base white/orange	Double First Base	1	\$160.00	\$160.00
			Total	\$5,775.00		

Note to customer

Fields 1 & 2

Accepted date

Accepted by

From: Tom Osboe < tom@iowaathleticfields.com >

Date: Sat, Sep 14, 2024, 11:37 AM

Subject: Estimates/Oelwein LL ball fields

## Wings Park SE Field -

• Mix in approx. 3 inches of Montour ag lime with existing skin surface aggregate

• Laser grade new skin surface to aid in efficient drainage

Estimated cost of above - \$13,000

## Wings Park NE Field -

- Core out infield skin to a depth of approx. 3 inches
- Install new Montour ag lime in it's place
- Install new base anchors, plugs included
- Laser grade new skin surface to aid in efficient drainage
- Haul spoils off of field and deposit in a designated dumping area on site

Estimated cost of above - \$15,000

# Wings Park SW Field-

- Mix in approx. 3 inches of Montour ag lime with existing skin surface aggregate
- Laser grade new skin surface to aid in efficient drainage

Estimated cost of above - \$12,000

# **Oelwein Sports Complex- West Field**

- Mix in approx. 3 inches of Montour ag lime with existing skin surface aggregate
- Laser grade new skin surface to aid in efficient drainage

Estimated cost of above - \$12,000

The estimates stated above are estimates only and do not represent a firm and final quote. In our experience, we are usually pretty close to the final cost. Also, the numbers are based on doing all of the above listed work, and are not valid for anything else. If changes are required, we will re-figure the costs for the changes.

Tom

Iowa Athletic Fields Construction Company

tom@iowaathleticfields.com