



352 Roosevelt Rd, Glen Ellyn, IL 60137

dreisilker.com

630.469.7510

Attn

Shane Waters

cc

Phone:

(815) 562-4155 x

Fax:

Quote

1/2

Quote Number

RQ4654

Customer Information

Rochelle Municipal Utilities
333 Lincoln Hwy #1684
ROCHELLE, IL 61068

Ship To Information

Rochelle Municipal Utilities
333 Lincoln Hwy #1684
ROCHELLE, IL 61068

Quote Date: 2/11/2026

Customer ID: 260205001

Quoted By: Matt Dreisilker

RFQ #:

Salesperson: House Employee

Terms: COD/Cash Customer

Nameplate Information

ID R5394

Quote Information

Ship Via: Common Carrier

Reason For Work: Generator Shaft Failure

Required Work:

GENERATOR REPAIR
Disassemble generator
Steam clean and bake windings
Inspect salient pole rotor windings:
-AC voltage drop
-DC voltage drop
-Resistance tests
-Visually inspect amortisseur/rotor bars
-Insulation resistance
Inspect stator windings:
-Visual inspection
-Resistance
-Insulation resistance
-P.I.
-Surge test
Measure and inspect bearing housing
Remove, measure and inspect generator driven coupling
Reverse engineer shaft and relation to generator components
Disassemble salient pole rotor to remove shaft safely
Remove shaft from rotor body
Ultrasonically inspect new shaft material for flaws
Machine new shaft with 4140 HR Q&T alloy
Reinstall new shaft into rotor body
Replace nuts for salient pole rotor mountings
Reassemble and test salient pole rotor windings
Precisions dynamically balance rotor
Overspray stator windings with epoxy as needed
Machine polish slip ring surfaces
Replace slip ring brushes
Replace 22324-E1-XL FAG bearing
Reassemble generator

SIGNATURE: _____

DATE: _____

PRINT NAME: _____

PO# (If not yet issued) _____



352 Roosevelt Rd, Glen Ellyn, IL 60137

dreisilker.com

630.469.7510

Attn

Shane Waters

cc

Phone:

(815) 562-4155 x

Fax:

Quote

2/2

Quote Number

RQ4654

Customer Information

Rochelle Municipal Utilities
333 Lincoln Hwy #1684
ROCHELLE, IL 61068

Ship To Information

Rochelle Municipal Utilities
333 Lincoln Hwy #1684
ROCHELLE, IL 61068

Quote Date: 2/11/2026

Customer ID: 260205001

Quoted By: Matt Dreisilker

RFQ #:

Salesperson: House Employee

Terms: COD/Cash Customer

ONSITE COMMISSIONING

Review endplay, rotor alignment and air gap during installation

Perform start up vibration analysis

Perform one vibration analysis within one month

Perform one vibration analysis within three months

Perform three further vibration analysis within twelve months from shipment

Onsite commissioning is required to obtain warranty on the repair per Dreisilker Electric Motors, Inc. contract terms and conditions listed in the weblink presented in this quotation.

TERMS:

Set up a NET 30 Account w/ Down Payment

C.O.D - Credit Card or Check payment schedule

Comments: Special Shipping Required - Not Included

	Pick Up On	Lead Time	Total Price
Work Based on Straight Time:		14 Weeks	\$93,215.05

Customer's signature or action on this Quote confirms its acceptance of the Terms & Conditions found at <https://dreisilker.com/pdf-files/Terms-and-Conditions.pdf>. The signer warrants signer's authority to bind the Customer.

SIGNATURE: _____ DATE: _____

PRINT NAME: _____ PO# (If not yet issued) _____