

Prima Commercial Services, LLC

3885 US Highway 93 N
Stevensville, MT 59870
Point of Contact:
Suzanne Higginson
(406) 802-4370
Suzanne@primaaz.com

Proposal: Harvest View Park Playground (Robin Park)

April 29, 2021

Overview

Prima Commercial Services, in coordination with the City of Santaquin, UT and HG Utah I, proposes the following playground as a portion of Harvest View Sports Complex to be constructed on approximately 5050 square feet of the park, adjacent to future baseball diamonds.

Objectives

1. **Playground Equipment:**
 - a. The “Gorilla” playground set in natural colors, from Playground Boss. (Exhibit A)
 - b. The “Monkey in the Middle” playground set in natural colors, from Playground Boss. (Exhibit B)
 - c. The Double-Decker Cone Spinner provided by Big “T” Recreation. (Exhibit C)
 - d. 8ft swings with 3.5’ arch, 6 standard swings and 2 bucket swings, provided by Playground Boss. (Exhibit D)

2. **Playground Safety Surface:**

- a. Engineered Wood Fiber or Poured-in-place rubber safety surface with an aggregate sub-base and 50/50 color blend provided by either Big T Recreation or Playground Boss.

Specifications & Exhibits

1. Budget

City of Santaquin - Additional Playground Equipment & Safety Surface upgrade

Big T Recreation - Double Decker Cone Spinner, \$16,495 plus \$1,295 freight

Playground Boss - 5049 sq ft Poured in Place Rubber Safety Surface with aggregate sub base 50/50 color blend- Includes all construction and mobilization costs- \$90,882

-OR-

Big T Recreation - 5049 total sq ft pour in place safety surfacing for play area with 50/50 color - Includes all construction and mobilization costs. - \$93,460

HG Utah, LLC - Playground equipment and installation

-The Gorilla Playground by Playground Boss - \$39,516

-Monkey In the Middle by Playground Boss - \$23,544

-Arch Swings by Playground Boss - \$2,960

-Installation of all playground equipment, including double decker cone spinner and site preparation - \$22,000

-Playground safety surface engineered wood fibers, 5049 square feet - \$7,200
in lieu of rubberized surface or as a credit off the cost of rubber surface.

Total costs from HG Utah, LLC - \$95,220

Timeline - Ground preparation and playground installation to take place as soon as the Harvest View Sports Complex location is prepared.

2. Maps & Layouts




3. Exhibit A - "The Gorilla" playground set in natural colors (Provided by HG Utah)



Exhibit A continued:



Exhibit A Continued




4. Exhibit B - "The Monkey in the Middle" in natural colors (Provided by HG Utah)




Exhibit B continued



Exhibit B continued



5. Exhibit C - The "Double Decker Cone Spinner" (Diameter 7' 11", Height 12' 8")



6. Exhibit D - Six swings, 4 standard and 2 buckets (for infants) (Provided by HG Utah)

