

# Santaquin Canyon

## 2020 Road Damage

A partial photographic log of  
Damage to Uintah-Wasatch-Cache National Forest Route 014  
(a.k.a. Santaquin Canyon Road)



Images taken August 10 & 31, 2021  
By Ryan Lind, Santaquin Fire/EMS Chief &  
Dennis Marker, Santaquin Operations Manager

# Santaquin Canyon

2020 Road Damage




Image courtesy of Google Earth Pro. (earth.google.com)



# Santaquin Canyon

## 2019-2020 Road Damage






# Santaquin Canyon

2020 Road Damage

#1



Looking downstream



# Santaquin Canyon

2020 Road Damage

#1





# Santaquin Canyon

2020 Road Damage

#2





# Santaquin Canyon

2020 Road Damage

#2



Looking upstream



Looking downstream



# Santaquin Canyon

2020 Road Damage  
#3



Looking upstream



# Santaquin Canyon

2020 Road Damage

#3



Looking upstream



Looking downstream



# Santaquin Canyon

2020 Road Damage

#4



Looking downstream




# Santaquin Canyon

2020 Road Damage

#5



Looking upstream



Looking downstream



# Santaquin Canyon

2020 Road Damage

#6








70-80 feet














## Santaquin Canyon

2020 Road Damage

#7





**Santaquin Canyon**  
2020 Road Damage  
#7

80 feet



Exposed  
6 x 4 culvert  
Dated 6-15-2001



Damaged culvert  
terminus



Confluence of Summit Creek and local watershed





## Santaquin Canyon

2020 Road Damage

#7



# Santaquin Canyon

2020 Road Damage

#8





# Santaquin Canyon

2020 Road Damage

#8





# Santaquin Canyon

2020 Road Damage

#9





# Santaquin Canyon

2020 Road Damage

#10




Normally, the flows from this watershed (top left) are manageable along the left shoulder, but burned over conditions resulted in flows that crossed Santaquin Canyon Road and eroded shoulder areas on the right side of the road.

This location and those preceding locations in this packet are those areas with most significant damage. There are many other areas along the road where shoulders will need to be reconstructed and segments of the road replaced.

Please contact Santaquin City at 801-754-3211 to discuss





**Dennis L Marker, AICP, MPA**  
Santaquin Operations Manager  
275 West Main Street, Santaquin, UT 84655  
O 801-754-1907, F 801-754-3526  
dmarker@santaquin.org