



Date: 08/23/2023  
(Effective until 09/22/2023)

Bret Quinnell,  
Eaton Corporation  
W126N7250 Flint Dr  
Menomonee Falls, WI 53051  
6084950197  
Email: bretsquinnell@eaton.com

**Prepared For:**

Billing Contact: Bill Swearingen,  
Billing Company: Sheboygan Water Utility  
72 PARK AVE  
Sheboygan, WI 53081  
920-459-3812  
Email: billswearingen@sheboyganwater.org

**For Covered Equipment at Site:**

Site Contact: Bill Swearingen,  
Site Company: Sheboygan Water Utility  
72 PARK AVE  
Sheboygan, WI 53081  
920-459-3812  
Email: billswearingen@sheboyganwater.org

We are pleased to provide the following services proposal for your power quality equipment. Please refer to the Scopes of Work (SOW) for descriptions of service coverage and exclusions. Eaton Corporation terms and conditions (Eaton Corp. Service Agreement T-0 attachment) govern this proposal, and any purchase order submitted to Eaton pursuant thereto. Additional or different terms proposed by Buyer, whether in its purchase order or otherwise, shall not be binding upon Eaton Corporation and are hereby rejected unless expressly agreed to in writing by Eaton Corporation. Eaton Corporation cannot be held liable, and Buyer shall not be entitled to any damages and/or indemnifications, in case Eaton Corporation is prevented, hindered or delayed from or in performing any of its obligations resulting from the impact of the outbreak of COVID-19 for reasons not attributable to Eaton Corporation.

Serial Number	New/Renewal	Model Description	Battery Type, Quantity
EJ406UXX01	N	93PM-60-100	VRLA Sealed, 36

**Quantity 1, Eaton 93PM-60-100, VRLA Sealed, 36**

- Labor and parts to install the new power module and 2 fuses
  - 1 ea. UPM assembly, P/N 744-A4535 - \$15,943
  - 2 ea. FUSE, 200 A, 500 VAC/500 VDC - \$132
  - P-128000024
- Labor (includes travel) to install - \$4,900
- Weekday work

We anticipate that replacing UPM and fuses will restore the unit to full function. However, the existing corrosion may be indicative of some compromise to other components within the UPS, such that we cannot warrant that the present proposed repair will restore the UPS to like new condition.

We understand the difficulty of the situation and would like to extend discounted parts pricing in order to assist you with this repair.

There will be a 30 day warranty on the new UPM Assembly

**Grand Total Price: \$20,975.00**

- Non Contract Payment Terms: Net 30 days, Billing Cycle: Upon Completion
- Service quotes valued at less than \$5,000 may be subject to Eaton's prepayment requirement. Prepayment may be made via credit card, ACH transaction or a check mailed to Eaton prior to order acceptance. All credit card transactions with Eaton will incur a 3.5% service fee.
- Important Tax Notice: Tax is not included in the above purchase price. All orders will be subject to all applicable sales tax unless a current tax exemption certificate is on file covering the state shown in the ship-to address or service equipment location.
- To purchase (renew) your service contract, please sign and date below.
- Return all attachments with purchase order for **Eaton products** to:

**Did you know?** Eaton has PredictPulse remote monitoring and a suite of professional assessment and testing services (Load Bank, IR Scan, PQ Meter) that take traditional preventive maintenance to the next level by proactively identifying issues for greater peace of mind. Learn more at [Eaton.com/UPSservices](https://www.eaton.com/UPSservices)



- Eaton Corporation, 8609 Six Forks Road, Raleigh, NC 27615, Tel 800/843-9433, Fax 800/228-1899.
- Make Payments for Eaton products to: Eaton Corporation, 29085 Network Place, Chicago, IL 60673-1290

Accepted By:	Name	Title	Date	Purchase Order Number
Print Name:				

**Did you know?** Eaton has PredictPulse remote monitoring and a suite of professional assessment and testing services (Load Bank, IR Scan, PQ Meter) that take traditional preventive maintenance to the next level by proactively identifying issues for greater peace of mind. Learn more at [Eaton.com/UPSservices](http://Eaton.com/UPSservices)