

## July-25 PUBLIC WORKS MONTHLY REPORT

	HOURS	YEARS TOTAL	
STREET			468 0 Hrs. of Street Repairs, 65 0 Hrs. of Alley Repairs, 157 0 Hrs. of Street Sweeping
			146.0 Hrs. of Repair of Street Equipment, 55.0 Hrs. of Shop Clean-up and Shop
	736	3728	Equipment, 2.0 Hrs. of Street Markers & Signs Repairs or Replacement, 0.0 Hrs. of
			snow removal
			Completed paving 4 Ave. SE, from 4th Ave to 2nd - 3rd Street SW, 10th Ave. to 8th Aven
			11th Street SW from 9th Ave to 11th Avene
STREET SWEEPING	157	586	157 0 Hrs, of Street Sweeping was complete for the Month
			23 Business Miles, 335 Residenial Miles, 358 Total Miles, \$1230 00 Total Fuel Cost,
			\$27.11 Cost per Mile, 110.3 Tons of Debris Picked Up
CE & SNOW	0	638 5	None
PARKS	762	3185	436.5 Hrs. of mowing, 25.5 Hrs. of watering, 5.5 Hrs. of office and record keeping
			292 5 Hrs. of Park Equipment Maintenance and 33 5 Hrs. of Park Clean-up,
			and 2.0 Hrs. of Replacement or Repair of Playground Equipment
GARBAGE WATER	735,5	5297	495 94 Tons of Garbage picked up, 3,526 0 miles driven, 1,109 96 gallons of
			fuel used, 80 total loads, 614,0 Manhours of Garbage Hauling, 70,0 Manhours
			of Alley Clean-up, 51,0 manhours of Sanitation Equipment Maintenance
			Year to date total tons hauled = 2,996
			Total Fuel \$3,041.27
	239,5	1951	1.0 Hours of meter reading, 0.0 Hours of meter repairs, 22.0 Hours of
			water equipment maintenance, 155.5 Hours of maintenance of hydrants,
			valves and mains, 0.0 Hours of office and records, and 61.0 Hours of
			trealment plant operation and testing 0,0 Hours of Lead Copper Rule Study
SEWER	567	3682	43.0 Hrs. sewer main cleaning & TV, 155.5 Hrs maintenance of sewermains, manholes
			& equipment, 23.0 Hrs, maintenance of lift stations, 56.5 Hrs, maintenance of storm
			sewers, 6.0 Hrs. of Office & Records, and 368.5 Hrs of Treatment Plant Operation &
			Testing.
			No Sewer Call for this Month
GENERAL CITY	26	288	26 0 hours of general city cleanup and miscellaneous work , 46 0 hrs. of swimming pool
CENEIVIE OIT		200	maintenance, 26 5 Hours of Code Compliance issues
			Overtime hrs = 93.5, Vacation = 237.5, Sick Leave = 225.5
			Totoal Hours Worked = 4233 5
			Totoal Hours Worked = 4233,5
SHOP, MECHANICAL	146	1034.5 STREET	
SHOP, MECHANICAL	146	1034,5 STREET	SV280 - Added Hydraulic Fluid
SHOP, MECHANICAL	146	1034,5 STREET	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam
SHOP, MECHANICAL	146	1034,5 STREET	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter
SHOP, MECHANICAL	146	1034,5 STREET	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp,
SHOP, MECHANICAL	146		SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires
SHOP, MECHANICAL	146	1034.5 STREET SWEEPING	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom
SHOP, MECHANICAL	146		SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filler Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay
SHOP, MECHANICAL	146		SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom
SHOP, MECHANICAL	146		SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay
SHOP, MECHANICAL	146	SWEEPING	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None
SHOP, MECHANICAL	146		SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay
SHOP, MECHANICAL	146	SWEEPING	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None
SHOP, MECHANICAL	146	SWEEPING	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None
SHOP, MECHANICAL	146	SWEEPING	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit 194 - Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None
SHOP, MECHANICAL	146	SWEEPING	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab.
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab, Hussler 400 - Regular service, new blades
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab.
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab, Hussler 400 - Regular service, new blades
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab, Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit 19-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit 194 - Replaced all 4 tires Unit P-1, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit 194 - Replaced to wafer main broom Unit P-1, Replaced dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS SOLID WASTE	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab, Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 1012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS SOLID WASTE	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  Rone  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto 020 - Regular Service
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS SOLID WASTE	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 1012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS SOLID WASTE	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  Rone  Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto 020 - Regular Service
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS SOLID WASTE	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit 194 - Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab, Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto 020 - Regular Service Unit 208 - Replace spare tire rack holder
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS SOLID WASTE	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit P9-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto 020 - Regular Service Unit 208 - Replaced Spare tire rack holder  Unit 350 - Replaced Flex Plate, Shaft and bearings
SHOP, MECHANICAL	146	SWEEPING ICE&SNOW PARKS SOLID WASTE	SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp, Unit 194 - Replaced all 4 tires Unit 194 - Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None  None  Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab, Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto 020 - Regular Service Unit 208 - Replace spare tire rack holder