

July-23 PUBLIC WORKS MONTHLY REPORT

DEPARTMENT	HOURS	YEARS TOTAL	
	HOURS	TEARS TOTAL	726 0 Hrs. of Street Repairs, 71,0 Hrs. of Alley Repairs, 86,0 Hrs. of Street Sweeping
STREET			121 5 Hrs, of Repair of Street Equipment, 37 0 Hrs. of Shop Clean-up and Shop
	958.5	5293.5	Equipment, 3.0 Hrs. of Street Markers & Signs Repairs or Replacement, 0.0 Hrs. of
			snow removal
	4		Completed milling 4 Ave, SE, from 7th Street to 4th - 9th Street SE, 5th Ave, NE and Yellow-
TREET SWEEPING	86	741,5	stone Trailer Court, waiting for asphalt 86.0 Hrs, of Street Sweeping was complete for the Month.
IRCEI SWEEPING	80	741.5	30 of this, of others of others and the months.
			9 Business Miles, 266 Residenial Miles, 275 Total Miles, \$602,00 Total Fuel Cost,
			\$17,33 Cost per Mile, 58,50 Tons of Debris Picked Up.
CE & SNOW	0	674.5	None
ARKS	678	2409 5	483.5 Hrs. of mowing, 22.5 Hrs. of watering, 0.0 Hrs. of office and record keeping
			169.0 Hrs. of Park Equipment Maintenance and 21,5 Hrs. of Park Clean-up,
			and 3.0 Hrs. of Replacement or Repair of Playground Equipment
		F1	
ARBAGE	686	5096	421,57 Tons of Garbage picked up, 3,894,0 miles driven, 1,255,55 gallons of
GARBAGE	000	0030	fuel used, 62 total loads, 632.5 Manhours of Garbage Hauling, 1,5 Manhours
	R E		of Alley Clean-up, 52 0 manhours of Sanitation Equipment Maintenance
			Year to date total tons hauled = 2,777,61
	· ·		Total Fuel \$4,199,01
VATER	472	3007.5	0.0 Hours of meter reading, 0.0 Hours of meter repairs, 22.0 Hours of
			water equipment maintenance, 295.5 Hours of maintenance of hydrants, valves and mains, 0.0 Hours of office and records, and 72.5 Hours of
	5		treatment plant operation and testing, 82.0 Hours of Lead Copper Rule Study
EWER	310	2240 5	23.5 Hrs. sewer main cleaning & TV, 146.0 Hrs maintenance of sewermains, manholes
			& equipment, 42.5 Hrs, maintenance of lift stations, 16.5 Hrs, maintenance of storm
OENEDAL CITY			sewers, 5.0 Hrs. of Office & Records, and 140.5 Hrs of Treatment Plant Operation &
			Testing.
	5.5	174.5	No Sewer Call for this Month 5.5 hours of general city cleanup and miscellaneous work , 57,0 hrs. of swimming pool
GENERAL CITY	5.5	174.5	maintenance, 4.0 Hours of Code Compliance issues
			Overtime hrs = 77.5, Vacation = 128.0, Sick Leave = 208.5.0
			Overtime his = 77.5, Vacation = 120.6, Clore Ecove - 200.6.6
	9	-	Totoal Hours Worked = 4374.0
	20 5	ń.	Totoal Hours Worked = 4374.0
SHOP, MECHANICAL	121.5	1306 STREET	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid
SHOP, MECHANICAL	121.5	1306 STREET	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam
SHOP, MECHANICAL	121.5	1306 STREET	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air darn Unit 117-2 - Replaced Evap Filter
SHOP, MECHANICAL	121.5	1306 STREET	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam
SHOP, MECHANICAL	121.5	1306 STREET	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp.
SHOP, MECHANICAL	121.5	5 5 6 2	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air darn Unit 117-2 - Replaced Evap Filler Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replaced dirt shoes and scrapers, Replaced starter relay
SHOP, MECHANICAL	121.5	5 5 6 2	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 117-2 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom
SHOP, MECHANICAL	121.5	5 5 6 2	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air darn Unit 117-2 - Replaced Evap Filler Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replaced dirt shoes and scrapers, Replaced starter relay
SHOP, MECHANICAL	121.5	SWEEPING	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit 9-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None
SHOP, MECHANICAL	121.5	5 5 6 2	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air darn Unit 117-2 - Replaced Evap Filler Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replaced dirt shoes and scrapers, Replaced starter relay
HOP, MECHANICAL	121.5	SWEEPING	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit 9-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None
HOP, MECHANICAL	121.5	SWEEPING	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit 9-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None
SHOP, MECHANICAL	121.5	SWEEPING ICE&SNOW	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None
HOP, MECHANICAL	121.5	SWEEPING	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #6 - Replaced all cutting blades, adjusted park brake
HOP, MECHANICAL	121.5	SWEEPING ICE&SNOW	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab.
HOP, MECHANICAL	121.5	SWEEPING ICE&SNOW	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced of wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades
HOP, MECHANICAL	121.5	SWEEPING ICE&SNOW	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 117-2 - Replaced erated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced all 4 tires Unit P-1, Replaced dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair
HOP, MECHANICAL	121.5	SWEEPING ICE&SNOW	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced of wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades
HOP, MECHANICAL	121.5	SWEEPING ICE&SNOW PARKS	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 112 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced of wafer main broom Unit P-1, Replaced dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service
HOP, MECHANICAL	121.5	SWEEPING ICE&SNOW PARKS	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab, Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service
HOP, MECHANICAL	121.5	SWEEPING ICE&SNOW PARKS	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replaced dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab, Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced
HOP, MECHANICAL		SWEEPING ICE&SNOW PARKS SOLID WASTE	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filler Unit 017-2 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced all 4 tires Unit P-1, Replaced dir shoes and scrapers, Replaced starter relay Tennet - None Orasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck
HOP, MECHANICAL		SWEEPING ICE&SNOW PARKS	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filler Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced all 4 tires Unit P-1, Replaced dir shoes and scrapers, Replaced starter relay Tennet - None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab, Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto
SHOP, MECHANICAL	121.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced all 4 tires Unit P-1, Replaced dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto 020 - Regular Service
HOP, MECHANICAL	121.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filler Unit 012 - Engine derated - repaired by Tri County Imp Unit 194 - Replaced all 4 tires Unit P-2, Replaced all 4 tires Unit P-1, Replaced dir shoes and scrapers, Replaced starter relay Tennet - None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab, Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto
SHOP, MECHANICAL	121.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced all 4 tires Unit P-1, Replaced dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto 020 - Regular Service
SHOP, MECHANICAL	121.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filter Unit 012 - Engine derated - repaired by Tri County Imp Unit 194 - Replaced all 4 tires Unit P-2, Replaced all 4 tires Unit P-1, Replaced dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto 020 - Regular Service
SHOP, MECHANICAL	121.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Totoal Hours Worked = 4374.0 SV280 - Added Hydraulic Fluid Unit 020- LF Tire Repair, Regular Service, Installed new front air dam Unit 117-2 - Replaced Evap Filler Unit 012 - Engine derated - repaired by Tri County Imp. Unit 194 - Replaced all 4 tires Unit P-2, Replaced to wafer main broom Unit P-1, Replace dirt shoes and scrapers, Replaced starter relay Tennet - None None Grasshopper #6 - Replaced all cutting blades, adjusted park brake Grasshopper #7 - Installed new hold down - adjusted park brake - Repaired clutch tab. Hussler 400 - Regular service, new blades Grasshopper #5 - Tire Repair Unit 506 - Regular Service 417 - Tire Repairs x 5 421 - Hydraulic Pump Issues 422 - Replaced Cabin Filter and Regular Service 835 - Monitor Control Modual Replaced 831 - Retired - Will convert to dump truck 2013 Jeep - A/C condenser repaired - Action Auto 020 - Regular Service Unit 208 - Replace spare tire rack holder